

DGX A100 System Firmware Update Container

Release Notes

Table of Contents

Chapter 1. DGX A100 System FW Update Container Overview	1
Chapter 2. Using the DGX A100 FW Update Utility	2
2.1. Using NVSM	3
2.2. Using docker run	4
2.3. Using the .run File	5
2.4. Command and Argument List	5
2.5. Troubleshooting Update Issues	7
Chapter 3. Using the DGX A100 Firmware Update ISO	9
3.1. About the Firmware Update Menu	9
3.2. Booting to the Firmware Update ISO from a USB Flash Drive	. 10
3.3. Booting to the Firmware Update ISO by PXE Boot	. 11
Chapter 4. DGX A100 System Firmware Update Container Version 22.12.1	. 13
4.1. Special Instructions for Red Hat Enterprise Linux 7	. 17
4.2. Instructions for Updating Firmware	. 18
4.3. Known Issues	. 22
4.3.1. VBIOS cannot update due to running service processes	. 22
4.3.2. [BCM users only] Firmware Update Completes with Error on Base Command	
Manager	23
Chapter 5. DGX A100 System Firmware Update Container Version 22.5.5	. 24
5.1. Special Instructions for Red Hat Enterprise Linux 7	. 27
5.2. Instructions for Updating Firmware	. 28
5.3. Known Issues	. 32
5.3.1. Chassis Power State Remains On	32
5.3.2. Incorrect Thermal and Voltage Sensor and Fan RPM Values are Displayed	33
5.3.3. Processor Power Limit and Power Metrics are Not Supported	. 33
5.3.4. IndicatorLED Status Might Display an Incorrect State	33
5.3.5. Unable to Update BMC Firmware	.34
5.3.6. Firmware Update Container Unable to Recover PSU with Corrupted Firmware	. 34
5.3.7. Setting Up Active Directory Settings Might Fail with "Invalid Domain Name" Error 3	34
5.3.8. NVSM Incorrectly Reports the Delta PSU Part Number Instead of the Model	35
5.3.9 BMC KVM Screen May Show "No Signal" Under Certain Conditions	
5.3.10. SBIOS "Bootup NumLock State" not Enforced.	35
5.3.11. NVSM Fails to Run the FWUC show version Command	36
5.3.12. NVSM Exits With an Error Message When Updating Firmware by Using NVSM	. 36

5.3.13. After an FPGA Update, BMC Sel Log Shows Sensor-Related Errors	36
5.3.14. After a Firmware Update, Only the Delta Manifest Version Displays	37
5.3.15. PSUs Sometimes Display an Error after an Update	37
5.3.16. Force FPGA Update Sometimes Fails	37
5.3.17. Updating to Firmware Container Version 22.5.5 Fails for SSDs	37
Chapter 6. DGX A100 System Firmware Update Container Version 21.11.4	39
6.1. Special Instructions for Red Hat Enterprise Linux 7	42
6.2. Instructions for Updating Firmware	44
6.3. Known Issues	47
6.3.1. BMC Incorrectly Reports CPU Motherboard Overvoltage	47
6.3.2. TEMP_I00_IB0_P0 Reading not Reported in BMC "Disabled Sensors" List	47
6.3.3. nvipmitool Reports PCIe Correctable Errors as "Asserted"	47
6.3.4. KVM "Power On Server" Option is Grayed Out	48
6.3.5. BMC Web UI Performance Drop	48
6.3.6. SOL Cannot be Activated for a Newly Created User Account	48
6.3.7. Unable to Set Static IPv6 Address Using BMC Web UI	48
6.3.8. The BMC KVM May Stop Accepting Keyboard Input on the OS Command Line	49
6.3.9. BMC Kernel Panic Upon Power Cycle then BMC Reset Sequence	49
6.3.10. REDUNDANCY_PSU Sensor May Report 0x0a80 for Sensor Status	50
6.3.11. SBIOS "Bootup NumLock State" not Enforced	50
6.3.12. Updating only Active or Inactive SBIOS Can Cause Internal Compatibility Issues	50
6.3.13. IPMITool "Persistent" Flag Does not Work	51
6.3.14. User is Logged Out of the BMC Web UI After Powering On the System	51
6.3.15. SBIOS Versions Might not be Reported After BMC Cold Reboot	52
6.3.16. NVSM Incorrectly Reports the Delta PSU Part Number Instead of the Mode	۱
Numbers	52
6.3.17. BMC KVM Screen May Show "No Signal" Under Certain Conditions	52
6.3.18. "Power On Server" Option in KVM is Grayed Out	53
6.3.19. BMC SEL Log May Show a Negative Value for Sensor "TEMP_MB_AD_CARD	
During AC/DC/Warm reboot	53
6.3.20. Setting Up Active Directory Settings May Fail with "Invalid Domain Name" Error.	53
6.3.21. Systems Won't PXE Boot After BMC and CEC FW Update	54
6.3.22. BMC UI May not be Accessible from Mac OS	54
6.3.23. Unable to Launch BMC Dashboard under Pre-84.01 Firefox	55
6.3.24. The system starts the POST process several times during boot after updating the	5
	55
6.3.25. Restoring BMC Default Affects Power LED	55
6.3.26. The "Relative Mouse Mode" Option is grayed out in the KVM Menu	56

Chapter 7. DGX A100 System Firmware Update Container Version 21.05.7	. 57
7.1. Special Instructions for Red Hat Enterprise Linux	. 59
7.2. Instructions for Updating Firmware	. 60
7.3. Known Issues	. 63
7.3.1. BMC UI May not be Accessible from Mac OS	63
7.3.2. Boot Order in the SBIOS Reverts to the Default	. 64
7.3.3. Unable to Launch BMC Dashboard under Pre-84.01 Firefox	. 64
7.3.4. The system starts the POST process several times during boot after updating the SBIOS	64
Chapter 8. DGX A100 System Firmware Update Container Version 21.03.6	. 65
8.1. Special Instructions for Red Hat Enterprise Linux	. 67
8.2. Instructions for Updating Firmware	. 68
8.3. Known Issues	. 70
8.3.1. BMC UI May not be Accessible from Mac OS	71
8.3.2. Boot Order in the SBIOS Reverts to the Default	. 71
8.3.3. Unable to Launch BMC Dashboard under Pre-84.01 Firefox	. 71
8.3.4. The system starts the POST process several times during boot after updating the SBIOS	72
Chapter 9, DGX A100 System Firmware Update Container Version 20,12,3,3	73
9.1. Special Instructions for Red Hat Enterprise Linux	. 74
9.2. Instructions for Updating Firmware	. 75
9.3. Known Issues	. 78
9.3.1. BMC UI May not be Accessible from Mac OS	79
9.3.2. Update Timeout Reported for Motherboard CEC	. 79
9.3.3. Boot Order in the SBIOS Reverts to the Default	. 80
Chapter 10. DGX A100 System Firmware Update Container Version 20.12.3	. 81
10.1. Instructions for Updating Firmware	. 82
10.2. Known Issues	. 84
10.2.1. BMC UI May not be Accessible from Mac OS	84
10.2.2. Update Timeout Reported for Motherboard CEC	. 85
10.2.3. Boot Order in the SBIOS Reverts to the Default	. 85
Chapter 11. DGX A100 System Firmware Update Container Version 20.11.3	. 86
11.1. Instructions for Updating Firmware	. 88
11.2. Known Issues	. 89
11.2.1. Firmware Update Log File Size Impacts nvsm dump health	. 90
11.2.2. BMC UI May not be Accessible from Mac OS	90
11.2.3. Update Timeout Reported for Motherboard CEC	. 90
11.2.4. Boot Order in the SBIOS Reverts to the Default	. 91

Chapter 12. DGX A100 System Firmware Update Container Version 20.05.12.3	.92
12.1. Updating Firmware on DGX Systems Installed with DGX OS Release 5.0 or Later	. 93
12.2. Instructions for Updating Firmware	. 93
Chapter 13. DGX A100 System Firmware Update Container Version 20.05.12.2	.96
13.1. Instructions for Updating Firmware	. 97
Chapter 14. DGX A100 System Firmware Update Container Version 20.05.12	100
14.1. Instructions for Updating Firmware	102
Chapter 15. DGX A100 Firmware Changes	104
15.1. DGX A100 BMC Changes	104
15.2. DGX A100 SBIOS Changes	105
15.3. DGX A100 U.2 NVMe Changes	107
15.4. DGX A100 Broadcom 88096 PCIe Switchboard Changes	107
15.5. DGX A100 Broadcom 880xx Retimer Changes	108
15.6. A100 VBIOS Changes	108
15.7. DGX A100 BMC CEC Changes	109
15.8. DGX A100 BMC CEC SPI Changes	109
15.9. DGX A100 BMC Changes	111
15.10. DGX A100 FPGA Release Notes	112
15.11. DGX A100 Delta PSU Release Notes	114
Appendix A. DGX A100 Firmware Update Process	115

Chapter 1. DGX A100 System FW Update Container Overview

The NVIDIA DGXTM A100 System Firmware Update container is the preferred method for updating firmware on DGX A100 system. It provides an easy method for updating the firmware to the latest released versions, and uses the standard method for running Docker containers.

This document describes firmware components that can be updated, any known issues, and how to run this container.

Features

- Automates firmware (FW) update for DGX A100 system firmware, such as the system BIOS and BMC.
- Provides flexibility to update individual or all FW components
- Embeds the following
 - Qualified FW binaries for supported components
 - Flash update utilities and supporting dependencies
 - Manifest file which lists
 - Target platform and firmware version numbers
 - Sequence in which FW update should be applied
 - "On-Error" policy for every FW component
- Supports interactive and non-interactive firmware update

Chapter 2. Using the DGX A100 FW Update Utility

The NVIDIA DGX A100 System Firmware Update utility is provided in a tarball and also as a .run file. Copy the files to the DGX A100 system, then update the firmware using one of the following three methods:

- NVSM provides convenient commands to update the firmware using the firmware update container
- **Using Docker** to run the firmware update container
- Using the .run file which is a self-extracting package embedding the firmware update container tarball

Note: Fan speeds may increase while updating the BMC firmware. This is a normal part of the BMC firmware update process.

Requirements

Refer to the **Highlights and Changes** in the specific release for the DGX OS and EL7/EL8 versions supported by the firmware update container.

The firmware update container requires that the following modules are installed on the system.

- nvidia_vgpu_vfio
- nvidia-uvm
- nvidia-drm
- nvidia-modeset
- nv_peer_mem
- nvidia_peermem
- nvidia
- i2c_nvidia_gpu
- ipmi_devintf
- ipmi_ssif
- acpi_ipmi

- ipmi_si
- ▶ ipmi_msghandler

These modules are installed as part of the standard DGX OS, EL7, or EL8 installation. The container may fail if any of these modules are not installed. Be sure to follow the provided instructions when installing or upgrading DGX OS, EL7, or EL8.

CAUTION: Observe the following before running the firmware update container:

- Do not log into the BMC dashboard UI while a firmware update is in progress.
- Stop all unnecessary system activities before attempting to update firmware.
- Stop all GPU activity, including accessing nvidia-smi, as this can prevent the VBIOS from updating.
- When issuing update_fw all, stop the following services if they are launched from Docker through the docker run command:
 - dcgm-exporter
 - nvidia-dcgm
 - nvidia-fabricmanager
 - nvidia-persistenced
 - xorg-setup
 - lightdm
 - nvsm-core
 - kubelet

The container will attempt to stop these services automatically, but will be unable to stop any that are launched from Docker.

- Do not add additional loads on the system (such as user jobs, diagnostics, or monitoring services) while an update is in progress. A high workload can disrupt the firmware update process and result in an unusable component.
- When initiating an update, the update software assists in determining the activity state of the DGX system and provides a warning if it detects that activity levels are above a predetermined threshold. If the warning is encountered, you are strongly advised to take action to reduce the workload before proceeding with the update.

2.1. Using NVSM

The NVIDIA DGX A100 system software includes Docker software required to run the container.

1. Copy the tarball to a location on the DGX system.

2. From the directory where you copied the tarball, enter the following command to load the container image.

```
$ sudo docker load -i nvfw-dgxa100_22.12.1_221208.tar.gz
```

3. To verify that the container image is loaded, enter the following.

```
REPOSITORY TAG
nvfw-dgxa100 22.12.1
```

\$ sudo docker images

4. Using NVSM interactive mode, enter the firmware update module.

```
$ sudo nvsm
```

nvsm-> cd systems/localhost/firmware/install

5. Set the flags corresponding to the action you want to take.
 \$ nvsm(/system/localhost/firmware/install)-> set Flags=<option>

See the <u>Command and Argument Summary</u> section below for the list of common flags.

6. Set the container image to run.
\$ nvsm(/system/localhost/firmware/install)-> set DockerImageRef=nvfw-dgxa100:22.12.1

```
7. Run the command.
   $ nvsm(/system/localhost/firmware/install)-> start
```

2.2. Using docker run

The NVIDIA DGX A100 system software includes Docker software required to run the container.

- 1. Copy the tarball to a location on the DGX system.
- 2. From the directory where you copied the tarball, enter the following command to load the container image.

```
$ sudo docker load -i nvfw-dgxa100_22.12.1_221208.tar.gz
```

3. To verify that the container image is loaded, enter the following.

\$ sudo docker images

REPOSITORY TAG nvfw-dgxal00 22.12.1

4. Use the following syntax to run the container image.

```
$ sudo docker run --rm --privileged -ti -v /:/hostfs nvfw-dgxa100:22.12.1
<command> <[arg1] [arg2] ... [argn]</pre>
```

See the <u>Command and Argument List</u> section below for the list of common commands and arguments.



Note: If you do not have the tarball file, but you do have the .run file, you can extract the tarball from the .run file by issuing the following:

sudo nvfw-dgxa100_22.12.1_221208.run -x

2.3. Using the .run File

The update container is also available as a .run file. The .run file uses the Docker software if it is installed on the system, but can also be run without Docker installed.

- 1. After obtaining the .run file, make the file executable. \$ chmod +x nvfw-dgxa100_22.12.1_221208.run
- 2. Use the following syntax to run the container image. \$ sudo ./nvfw-dgxa100_22.12.1_221208.run <command> <[arg1] [arg2] ... [argn]</pre>

See the <u>Command and Argument Summary</u> section below for the list of common commands and arguments.

2.4. Command and Argument List

The following are common commands and arguments.

- Show the manifest show fw manifest
 - NVSM Example: \$ nvsm(/system/localhost/firmware/install) -> set Flags=show_fw_manifest
 - Docker Run Example:\$ sudo docker run --rm --privileged -ti -v /:/hostfs nvfw-dgxa100:22.12.1 show_fw_manifest
 - .run File Example: \$ sudo ./nvfw-dgxa100_22.12.1_221208.run show_fw_manifest
- Show version information show version
 - NVSM Example: \$ nvsm(/system/localhost/firmware/install) -> set Flags=show_version
 - Docker Run Example:\$ sudo docker run --rm --privileged -ti -v /:/hostfs nvfw-dgxa100:22.12.1 show_version
 - .run File Example: \$ sudo ./nvfw-dgxa100_22.12.1_221208.run show_version
- Check the onboard firmware against the manifest and update all down-level firmware. update_fw all
 - NVSM Example: \$ nvsm(/system/localhost/firmware/install) -> set Flags=update_fw\ all

For NVSM, an escape is needed before blank spaces when setting the flags.

- Docker Run Example:\$ sudo docker run --rm --privileged -ti -v /:/hostfs nvfw-dgxa100:22.12.1 update_fw all
- .run File Example: \$ sudo ./nvfw-dgxa100_22.12.1_221208.run update_fw all
- Check the specified onboard firmware against the manifest and update if down-level.

update_fw [fw]

Where [fw] corresponds to the specific firmware as listed in the manifest. Multiple components can be listed within the same command. The following are examples of updating the BMC and SBIOS.

NVSM Example: \$ nvsm(/system/localhost/firmware/install) -> set Flags=update_fw\ BMC\ SBIOS

For NVSM, an escape is needed before blank spaces when setting the flags.

- Docker Run Example:\$ sudo docker run --rm --privileged -ti -v /:/hostfs nvfw-dgxa100:22.12.1 update_fw BMC SBIOS
- .run File Example: \$ sudo ./nvfw-dgxa100_22.12.1_221208.run update_fw BMC SBIOS

```
    Run the DGX A100 firmware update in non-interactive mode.
set_flags auto=1
```

List of Arguments

```
Update flags:
   Updates all, a specified combination, or an individual firmware component
   if the image currently on the device is prior to the available version.
   syntax:
     update fw < firmware components >
     update fw < component [ -f | --force ] [ component options ] >
Update flag Definitions :
   --force For single component updates. Bypass the checks and upgrade regardless
 of the version.
  all
          Update firmware on all components. Cannot be used with the '--force'
 flag.
            syntax: update fw all
            Update the System BIOS firmware.
  SBTOS
            syntax: update_fw SBIOS [ -a | --active]
                                     [ -i | --inactive]
  BMC
            Update the firmware on all, or a specified Baseboard Management
            Controller.
            syntax: update fw BMC [ -i | --inactive]
                                   [ -b | --bmc-access-path <BMC
 IP:login id:password> ]
                                   [ -m | --intermediate-fw ]
                                   [ -t | --target-bmc <target BMC> ]
            where:
               --bmc-access-path <val> Non-default access parameters to the BMC
   SSD
            Update firmware on all, or a specified Solid State Drive.
            syntax: update fw SSD [ -s | --select-ssd <SSD target> ]
            where:
               --select-ssd <target> Name of the specific drive to update
            Update the firmware on all, or a specified Power Supply syntax: update_fw PSU [ -s | --select-psu <PSU number> ] [ -S | --
   PSU
select-slot <PSU slot> }
            where:
               --select-psu <target> Name of the specific PSU to update.
               --select-slot <slot> Name of the specific PSU slot to update
  VBIOS
          Update the Video BIOS firmware on all detected GPUs.
            It is not currently possible to update individual GPU devices.
            syntax: update fw VBIOS
```

FPGA	Update firmware on the FPGA devices on lower and upper GPU trays. syntax: update_fw FPGA
SWITCH	<pre>Update firmware on one, specific set, or all switch devices. syntax: update_fw SWITCH [-s select-switch <switch-model[:bdf]>]</switch-model[:bdf]></pre>
CEC	Update firmware on one or multiple CEC syntax: update_fw CEC [-s select-cec [MB_CEC Delta_CEC]
CPLD	Update MB CPLD / MID CPLD firmware syntax: update fw CPLD [-s select-cpld [MB CPLD MID CPLD]

2.5. Troubleshooting Update Issues

Missing Software Modules

The container may fail if any of these modules are not installed on the system.

- nvidia_vgpu_vfio
- nvidia-uvm
- nvidia-drm
- nvidia-modeset
- nv peer mem
- nvidia peermem
- nvidia
- i2c_nvidia_gpu
- ipmi_devintf
- ipmi_ssif
- acpi_ipmi
- 🕨 ipmi si
- ipmi msghandler

The following are examples of error messages:

```
Firmware update not started
 Following service(s)/process(es) are holding onto the resource about
 to be upgraded. These need to be manually stopped for firmware update to occur.
 If xorg is holding the resources, try to stop it by 'sudo systemctl stop <display
 manager>,'
 where the <display manager> can be acquired by 'cat /etc/X11/default-display-
 manager':
 process nvidia-persiste(pid 7554)
 • session-1.scope - Session 1 of user swqa
 Loaded: loaded (/run/system/session-1.scope; static; vendor preset:
 disabled)
 Transient: yes
   Drop-In: /run/systemd/system/session-1.scope.d
      50-After-systemd-logind\x2eservice.conf, 50-After-systemd-user-sessions
 \x2eservice.conf, 50-Description.conf, 50-SendSIGHUP.conf, 50-Slice.conf, 50-
 TasksMax.conf
 Active: active (running) since Wed 2021-11-17 00:36:22 EST; 1min 49s ago
```

```
CGroup: /user.slice/user-1000.slice/session-1.scope

modprobe: FATAL: Module nvidia not found in directory /lib/modules/5.4.0-80-

generic
```

To recover, perform an update of the DGX OS (refer to the <u>DGX OS User Guide</u> for instructions), then retry the firmware update.

Chapter 3. Using the DGX A100 Firmware Update ISO

This section describes how to use the DGX A100 firmware update ISO to efficiently update the firmware in a large fleet of DGX A100 systems.

3.1. About the Firmware Update Menu

Once the system boots up to the firmware update ISO, it sets up the environment and launches a firmware update menu. The menu can be used in the following three different modes:

Interactive

This displays a text-based UI with the following choices of actions to take:

Start the firmware update container

This runs the firmware update container using the update_fw all option.

Start the firmware update container with custom options

This runs the firmware update container using custom arguments that you enter into a text box. Separate multiple arguments by a space. Example update_fw BMC -f

See List of Arguments for available arguments.

Set up connection for automation and Exit

This sets up an SSH connection (default user name is fwui and default password is fw_update) so you can run automation scripts from a different system. For example, this lets you use Ansible automation.

Exit

Non-interactive

This reads the argument from kernel parameter (/proc/cmdline) and then runs the firmware update container automatically. See section "Updating the Firmware Automatically" in <u>Booting to the Firmware Update ISO from a USB Flash Drive</u>

Automation

This sets up an SSH connection. The default user name is fwui and default password is fw_update . From there you can use automation scripts (for example, Ansible) to perform the firmware update.

3.2. Booting to the Firmware Update ISO from a USB Flash Drive

This section describes how to boot to the DGX A100 firmware update ISO from a USB flash drive.

Basic Process

Download the ISO image and create a bootable USB drive that contains the ISO image.

Important: Do not use the virtual media from the BMC as the BMC will be reset during the update.

Updating the Firmware Automatically

To set up the firmware to update automatically when the system boots up,

1. Edit the GRUB menu parameters within the ISO at BOOT/GRUB/GRUB.CGF as follows.

Set fwuc-mode=noninteractive.

Set the following parameters as needed.

- fwuc-update_args=<arg1>,<arg2> ...
- fwuc-extra_args=<extra-arg1> ...

See List of Arguments for available arguments.

The following example boots the firmware update ISO in non-interactive mode and then updates the SBIOS without first checking the installed version, then reboots the system after the update.

```
menuentry "Start Firmware Update Environment (Non-interactive)" {
    linux /vmlinuz boot=live console=tty0 apparmor=0 elevator=noop nvme-
core.multipath=n nouveau.modeset=0 boot-live-env start-systemd-networkd fwuc-
mode=noninteractive fwuc-update_args=update_fw,SBIOS,-f fwuc-extra_args=reboot-
after-update
    initrd /initrd
```

- 2. Create a bootable USB drive that contains the updated ISO.
- 3. Boot to the USB drive.
- 4. If the NVMe drive firmware, the FPGA, or the CEC1712 (Delta_CEC) was updated, then perform a DC power cycle by issuing the following.

```
$ sudo ipmitool -I lanplus -H ${BMC_IP} -U ${BMC_USER} -P ${BMC_PW} chassis power
cycle
```

3.3. Booting to the Firmware Update ISO by PXE Boot

This section describes how to PXE boot to the DGX A100 firmware update ISO.

- 1. Refer to the information in <u>Setting Up DGX OS 5.0 for PXE Boot</u> for guidance on setting up the DGX A100 to PXE boot.
- 2. Download the ISO image and then mount it.

```
$ sudo mount -o loop ~/DGXA100_FWUI-22.12.1-2022-12-09-01-25-20.iso /mnt
```

- 3. Copy the filesystem.squashfs, initrd, and vmlinuz files to the http directory.
 - \$ sudo mkdir -p /local/http/firmware-update/

```
$ sudo cp /mnt/live/filesystem.squashfs /local/http/firmware-update/
```

- \$ sudo cp /mnt/{initrd,vmlinuz} /local/http/firmware-update/
- \$ umount /mnt

The new /local/http folder structure should look like this:

```
/local/http/

dgxbaseos-5.x.y

base_os_5.x.y.iso

initrd

vmlinuz

firmware-update

filesystem.squashfs

initrd

vmlinuz
```

4. Edit the /local/syslinux/efi64/pxelinux.cfg/default file to add the following menu option content for the Firmware Update OS.

```
label Firmware Update Container
  menu label Firmware Update Container
  kernel http://${SERVER_IP}/firmware-update/vmlinuz
  initrd http://${SERVER_IP}/firmware-update/initrd
  append vga=788 initrd=initrd boot=live console=tty0 console=ttyS1,115200n8
  apparmor=0 elevator=noop nvme-core.multipath=nouveau.modeset=0 boot-
live-env start-systemd-networkd fetch=http://${SERVER_IP}/firmware-update/
filesystem.squashfs
```

Important: If the system is booting from the LAN port connection (enp226s0), connections to slot 4 (enp225s0f0 and enp225s0f1) must be on the same domain as the LAN port. If they are not on the same domain, then add live-netdev=enp226s0 to the append line.

Example:

```
append vga=788 initrd=initrd boot=live console=tty0 apparmor=0 live-
netdev=enp226s0 elevator=noop nvme-core.multipath=n nouveau.modeset=0
boot-live-env start-systemd-networkd fetch=http://${SERVER_IP}/
filesystem.squashfs
```

5. (Optional) To set up the boot configuration to run the container automatically when booting, edit the following parameters at pxelinux.cfg/default:

Set fwuc-mode=noninteractive.

Set the following parameters as needed.

- fwuc-update_args=<arg1>,<arg2> ...
- fwuc-extra_args=<extra-arg1> ...

See List of Arguments for available arguments.

The following example boots the package in non-interactive mode and updates the SBIOS without first checking the installed version, then reboots the system after the update.

```
append vga=788 initrd=initrd boot=live console=tty0 apparmor=0 elevator=noop
nvme-core.multipath=n nouveau.modeset=0 fwuc-mode=noninteractive fwuc-
update_args=update_fw,SBIOS,-f fwuc-extra_args=reboot-after-updateboot-live-env
start-systemd-networkd fetch=http://${SERVER_IP}/filesystem.squashfs
```

6. Change permissions on /local.

\$ sudo chmod 755 -R /local

7. PXE boot by restarting the system using ipmitool.

```
$ ipmitool -I lanplus -H <DGX-BMC-IP> -U <username> -P <password> chassis bootdev
pxe options=efiboot
$ ipmitool -I lanplus -H <DGX-BMC-IP> -U <username> -P <password> chassis power
reset
```

When the system PXE menu comes up, choose the Firmware Update Container option. The firmware is updated automatically once the system has booted. If not set to update automatically, then follow the instructions to update the firmware.

8. If the NVMe drive firmware, the FPGA, or the CEC1712 (Delta_CEC) was updated, then perform a DC power cycle by issuing the following.

\$ sudo ipmitool -I lanplus -H \${BMC_IP} -U \${BMC_USER} -P \${BMC_PW} chassis power
cycle

Chapter 4. DGX A100 System Firmware Update Container Version 22.12.1

The DGX Firmware Update container version **22.12.1** is available.

- Package name: nvfw-dgxa100_22.12.1_221208.tar.gz
- Run file name: nvfw-dgxa100_22.12.1_221208.run
- Image name: nvfw-dgxa100:22.12.1
- ISO image: DGXA100_FWUI-22.12.1-2022-12-09-01-25-20.iso
- PXE netboot: pxeboot-DGXA100_FWUI-22.12.1.tgz

Highlights and Changes in this Release

This release is supported with the following DGX OS software:

DGX OS 5.4 or later.

- **Important:** This firmware update container does NOT support DGX OS 4.99.xx. To use the container on DGX A100 servers, update to DGX OS 5.1 or later.
- EL7-22.08 or later (See "Special Instructions for Red Hat Enterprise Linux 7" in the DGX A100 System Firmware Container Release Notes) EL8-21.08 Update 1 or later.
- EL8-22.08 or later

Fixed BMC issues

- Improved SNMP trap handling and updated SNMP MIB with additional description for better trap information.
- Handled a rare NTP server configuration settings issue from BMC WebUI.
- The BMC update includes software security enhancements. See the <u>NVIDIA Security</u> <u>Bulletin DGX - December 2022</u> for details.
- Improvements In Redfish

- Addressed a redfish URI timeout issue by appropriately handling the session authentication mechanism.
- Addressed a rare redfish URI connection failure issue by appropriately handling the Redfish session authentication mechanism.
- Fixed Redfish' chassis power state inconsistencies.
- Fixed redfish to fetch accurate values of thermal and power sensors states and readings.
- Revised redfish chassis to identify LED status reporting issue.
- Reduced frequency of UPNP (Universal Plug and Play) SSDP (Simple Service Discovery Protocol) advertisements from BMC
- Fixed SBIOS Issues
 - Fixed issues relating to redfish reporting of PCIe device types and speeds.
 - Removed unimplemented setup menu options for User Defaults and Boot NumLock State.
 - Updated AGESA to version 1.0.0.E.
 - The SBIOS update includes software security enhancements. See the <u>NVIDIA Security</u> <u>Bulletin DGX - December 2022</u> for details.
- Added Support
 - Added M.2 Micron 7400 Gen4 drive.
- Known Issues
 - For more information, see <u>Known Issues</u>.

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table.

- If you are updating from 21.11.4 the total update time is *approximately* sixty-eight (68) minutes.
- If you are updating from 22.5.5 the total update time is *approximately* sixty-one (61) minutes.

Component	Version	Key Changes	Update time from 21.11.4	Update Time from 22.5.5
BMC (via CEC)	00.19.07	Refer to DGX A100 BMC Changes	32	31
SBIOS	1.18	<u>See SBIOS</u> <u>changes section</u>	6	6

Broadcom 88096 PCIe switch board	0.2.0	No change	0	0
BMC CEC SPI (MB_CEC)	3.28	No change	0	0
PEX88064 Retimer	3.1.0	No change	1	0
PEX88080 Retimer (U225)	3.1.0	No change	1	0
PEX88080 Retimer (U666)	4.1.0	New update	1	1
NVSwitch BIOS	92.10.18.00.01	No change	0	0
VBIOS (A100 PG506 SKU200 (40GB))/VBIOS (A100 40GB)	92.00.45.00.03	No change	0	0
VBIOS (A100 PG506 SKU210 (80GB))/VBIOS (A100 80GB)	92.00.9E.00.01	New update	2	2
VBIOS (A800 PG506 SKU215 (80GB))	92.00.A4.00.01	New support	2	2
VBIOS (A100 PG510 SKU200 (40GB))	92.00.81.00.01	New support	2	2
VBIOS (A100 PG510 SKU210 (80GB))	92.00.9E.00.03	New support	2	2
VBIOS (A800 PG510 SKU215 (80GB))	92.00.A4.00.05	New support	2	2
VBIOS (A100 SystemB 80GB)	92.00.81.00.06	No change	0	0
U.2 NVMe (Samsung)	EPK9CB5Q	No change	0	0
U.2 NVMe (Kioxia)	105	No change	0	0
M.2 NVMe (Samsung version 1)	EDA7602Q	No change	0	0
M.2 NVMe (Samsung version 2)	GDC7302Q	No change	1	0
M.2 Micron 7400 Gen4	E1MU238V	New support	1	1
FPGA (GPU sled)	4.02	New update	20	20
CEC1712 SPI (GPU	4	No change	3	0
sled)				
PSU (Delta rev04)	Primary 1.7/ Secondary 1.7/ Community 1.7	No change	0	0

PSU (Delta rev03)	Primary 1.6/ Secondary 1.6/ Community 1.7	No change	0	0
PSU (Delta rev02)	Primary 1.6/ Secondary 1.6/ Community 1.7	No change	0	0
PSU (LiteOn)	908	No change	0	0

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image.

When using $update_fw$ all, the update container updates both active and inactive images.

BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image.

The update container can only update the inactive image, and will update it only if the *active* image needs to be updated. After the update is completed, the updated inactive image becomes the active image. Because the active image is now updated, subsequent update_fw all commands will not update the inactive image. To update the inactive image in this case, use update_fw BMC --inactive. Since the container does not support updating the active image directly, commands such as update_fw BMC -a -f will not work.

DO NOT UPDATE DGX A100 CPLD FIRMWARE UNLESS INSTRUCTED

When updating DGX A100 firmware using the Firmware Update Container, do not update the CPLD firmware unless the DGX A100 system is being upgraded from 320GB to 640GB.

The current DGX A100 Firmware Update Container will not automatically update the CPLD firmware (for example, when running update_fw all). It is possible to update the CPLD firmware using "update_fw CPLD"; however, it is strongly recommended that the CPLD firmware not be updated manually unless specifically instructed by <u>NVIDIA Enterprise Support</u> (or email <u>enterprisesupport@nvidia.com</u>). If the DGX A100 is upgraded from 320GB to 640GB, the CPLD firmware update should be performed as instructed.

4.1. Special Instructions for Red Hat Enterprise Linux 7

This section describes the actions that must be taken before updating firmware on DGX A100 systems installed with Red Hat Enterprise Linux. There are two options for meeting these requirements.

Option 1: Update to EL7-22.05

Refer to the <u>DGX Software for Red Hat Enterprise Linux 7 Release Notes</u> for more information.

Important: Updating the DGX software for Red Hat Enterprise Linux will update the Red Hat Enterprise Linux installation to 7.9 or later. If you do not want to update your Red Hat Enterprise Linux 7 installation, then choose Option 2.

Option 2: Install mpt3sas 31.101.01.00-0

These instructions apply if:

- > You do not want to update your Red Hat Enterprise Linux installation, and
- > Your system is currently installed with Red Hat Enterprise Linux 7.7 or later.

Note: If your system is installed with Red Hat Enterprise Linux 7.6 or earlier, contact NVIDIA Enterprise Support for assistance.

- 1. Perform this step if your system is no longer pointing to the NVIDIA DGX software repository.
 - a). On Red Hat Enterprise Linux, run the following commands to enable additional repositories required by the DGX software.

```
sudo subscription-manager repos --enable=rhel-7-server-extras-rpms
sudo subscription-manager repos --enable=rhel-7-server-optional-rpms
```

b). Run the following command to install the DGX software installation package and enable the NVIDIA DGX software repository.

ATTENTION: By running these commands you are confirming that you have read and agree to be bound by the <u>DGX Software License Agreement</u>. You are also confirming that you understand that any pre-release software and materials available that you elect to install in a DGX may not be fully functional, may contain errors or design flaws, and may have reduced or different security, privacy, availability, and reliability standards relative to commercial versions of NVIDIA software and materials, and that you use pre-release versions at your risk.

```
yum install -y \
https://international.download.nvidia.com/dgx/repos/rhel-files/dgx-repo-
setup-20.03-1.el7.x86_64.rpm
```

- Install mpt3sas 31.101.01.00-0. sudo yum install mpt3sas-dkms
- 3. Load the mpt3sas driver into the Red Hat Enterprise Linux kernel. sudo modprobe mpt3sas You can verify the correct mpt3sas version is installed by issuing the following. yum list installed

4.2. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container.

The commands use the .run file, but you can also use any method described in <u>Using the DGX</u> <u>A100 FW Update Utility</u>.

CAUTION:

- Do not log into the BMC dashboard UI while a firmware update is in progress.
- Stop all unnecessary system activities before attempting to update firmware.
- Stop all GPU activity, including accessing nvidia-smi, as this can prevent the VBIOS from updating.
- When issuing update_fw all, stop the following services if they are launched from Docker through the docker run command:
 - dcgm-exporter
 - nvidia-dcgm
 - nvidia-fabricmanager
 - nvidia-persistenced
 - xorg-setup
 - lightdm
 - nvsm-core
 - kubelet

The container will attempt to stop these services automatically, but will be unable to stop any that are launched from Docker.

- Do not add additional loads on the system (such as user jobs, diagnostics, or monitoring services) while an update is in progress. A high workload can disrupt the firmware update process and result in an unusable component.
- When initiating an update, the update software assists in determining the activity state of the DGX system and provides a warning if it detects that activity levels are above a predetermined threshold. If the warning is encountered, you are strongly advised to take action to reduce the workload before proceeding with the update.

1. Check if updates are needed by checking the installed versions.

\$ sudo ./nvfw-dgxa100_22.12.1_221208.run show_version

- If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
- If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 2. Perform the update for all firmware supported by the container.

```
$ sudo ./nvfw-dgxa100_22.12.1_221208.run update_fw all
```

Depending on the firmware that is updated, you may be prompted to either reboot the system or power cycle the system.

- If you are prompted to reboot, issue
 \$ sudo reboot
- If you are prompted to power cycle, you can issue the following two commands (there is no output with the first command).
 - \$ sudo ipmitool raw 0x3c 0x04
 - \$ sudo ipmitool chassis power cycle
- 3. After rebooting or power cycling the system, you may need to perform another update_fw all to update other firmware.
 - Either repeat Step 1 to check if updates are needed and then perform Step 2 if needed, or
 - ▶ Repeat Step 2 just in case updates are needed.

If you perform another update_fw all, you may be prompted again to either reboot the system or power cycle the system.

See <u>DGX A100 Firmware Update Process</u> for more information about the update process.

You can verify the update by issuing the following.

 $\$ sudo ./nvfw-dgxa100_22.12.1_221208.run show_version

Example output for a DGX A100 640GB system:

CEC							
==========	==						
			Onboa	rd Version	Manif	lest	up-to-
date							
MB_CEC(enal yes	bled)		3.28		3.28		
Delta_CEC(yes	enabled)		4.00		4.00		
BMC DGX							
Image Id		Status	Location	Onboard Ver	rsion	Manifest	up-
0:Active yes	Boot	Online	Local	00.17.07		00.19.07	
1:Inactive yes	Updatable		Local	00.17.07		00.19.07	
SBIOS							
Image Id			Onboard Version	Manifest		up-to-da	te
0:Active	Boot Upda	table	1.18	1.18		ves	
1:Inactive	Updatable		1.18	1.18		yes	

Swi	tches				
PCI B	====== us#	Model	Onboard Version	Manifest	FUB
Upda	ted? up-to-date	000CA Datiman	2 1 0	2 1 0	
DGX -	0000:91:00.0(0261)	88064_Retimer	3.1.0	3.1.0	
DGX - N/A	0000:88:00.0(U260) yes	88064_Retimer	3.1.0	3.1.0	
DGX -	0000:4f:00.0(U262)	88064_Retimer	3.1.0	3.1.0	
N/A	yes		0.1.0	0.1.0	
N/A	0000:48:00.0(0225) yes	88080_Retimer	3.1.0	3.1.0	
DGX -	0000:01:00.0(U1)	PEX88096	2.0	2.0	
N/A	yes				
DGX - N/A	0000:81:00.0(U3) yes	PEX88096	2.0	2.0	
DGX - N/A	0000:b1:00.0(U4)	PEX88096	2.0	2.0	
DGX - N/A	0000:41:00.0(U2) yes	PEX88096	2.0	2.0	
DGX -	0000:c4:00.0	LR10	92.10.18.00.01	92.10.18.00.01	
N/A	yes	1010	00 10 10 00 01	00 10 10 00 01	
DGX -	0000:C5:00.0	LRIU	92.10.18.00.01	92.10.18.00.01	
DGX -	0000:c6:00.0	LR10	92.10.18.00.01	92.10.18.00.01	
N/A	yes				
DGX -	0000:c7:00.0	LR10	92.10.18.00.01	92.10.18.00.01	
N/A	yes	1 0	00 10 10 00 01	00 10 10 00 01	
DGX -	0000:08:00.0	TKIO	92.10.18.00.01	92.10.18.00.01	
DGX -		TR10	92 10 18 00 01	92 10 18 00 01	
N/A	yes	DI(1.0	52.10.10.00.01	52.10.10.00.01	

Mass Storage				
Drive Name/Slot	Model Number	Onboard Version	Manifest	up-
nvme0n1 ves	Samsung MZWLJ3T8HBLS-00007	EPK9CB5Q	EPK9CB5Q	
nvmeln1 yes	Samsung MZWLJ3T8HBLS-00007	EPK9CB5Q	EPK9CB5Q	
nvme2n1 yes	Samsung MZ1LB1T9HALS-00007	EDA7602Q	EDA7602Q	
nvme3n1 yes	Samsung MZ1LB1T9HALS-00007	EDA7602Q	EDA7602Q	
nvme4n1 yes	Samsung MZWLJ3T8HBLS-00007	EPK9CB5Q	EPK9CB5Q	
nvme5n1 ves	Samsung MZWLJ3T8HBLS-00007	EPK9CB5Q	EPK9CB5Q	
nvme6n1 yes	Samsung MZWLJ3T8HBLS-00007	EPK9CB5Q	EPK9CB5Q	
nvme7n1 yes	Samsung MZWLJ3T8HBLS-00007	EPK9CB5Q	EPK9CB5Q	
nvme8n1 yes	Samsung MZWLJ3T8HBLS-00007	EPK9CB5Q	EPK9CB5Q	
nvme9n1 yes	Samsung MZWLJ3T8HBLS-00007	EPK9CB5Q	EPK9CB5Q	
Video BIOS ==========				

Bus	Model	Onboard Version	Manifest	FUB Updated?	up-
to-date				1	-
0000:07:00.0 yes	A100-SXM4-80GB	92.00.45.00.05	92.00.45.00.05	yes	
0000:0f:00.0 yes	A100-SXM4-80GB	92.00.45.00.05	92.00.45.00.05	yes	
0000:47:00.0 ves	A100-SXM4-80GB	92.00.45.00.05	92.00.45.00.05	yes	
0000:4e:00.0 ves	A100-SXM4-80GB	92.00.45.00.05	92.00.45.00.05	yes	
0000:87:00.0 ves	A100-SXM4-80GB	92.00.45.00.05	92.00.45.00.05	yes	
0000:90:00.0 ves	A100-SXM4-80GB	92.00.45.00.05	92.00.45.00.05	yes	
0000:b7:00.0 ves	A100-SXM4-80GB	92.00.45.00.05	92.00.45.00.05	yes	
0000:bd:00.0 yes	A100-SXM4-80GB	92.00.45.00.05	92.00.45.00.05	yes	

Power Supply

ID	Vendoi	r Model	MFR ID	Revision	Status
Onboard Version	Manifest	up-to-da	te		
PSU 0: Communication	Delta	ECD16010092	Delta	03	ok
01.07	01.07	yes			
PSU 0: Secondary	Delta	ECD16010092	Delta	03	ok
01.06	01.06	yes			
PSU 0: Primary	Delta	ECD16010092	Delta	03	ok
01.06	01.06	yes			
PSU 1: Communication	Delta	ECD16010092	Delta	03	ok
01.07	01.07	yes			
PSU 1: Secondary	Delta	ECD16010092	Delta	03	ok
01.06	01.06	yes			
PSU 1: Primary	Delta	ECD16010092	Delta	03	ok
01.06	01.06	yes	_		
PSU 2: Communication	Delta	ECD16010092	Delta	03	ok
01.07	01.07	yes			
PSU 2: Secondary	Delta	ECD16010092	Delta	03	ok
01.06	01.06	yes			
PSU 2: Primary	Delta	ECD16010092	Delta	03	OK
	UI.06	yes		0.0	- 1-
PSU 3: Communication	Delta	ECD10010092	Delta	03	OK
UL.U/	U1.U/	yes	Dalta	0.2	a la
ol of	Della	ECDI6010092	Della	03	OK
UI.UO DOU 2. Duimenu	UI.U0	yes		0.2	a la
ol of	Della	ECDI6010092	Della	03	OK
DCII 4. Communication	Dolto	yes ECD16010002	Dolto	0.2	o la
	01 07	ECDI0010092	Deila	0.5	0 K
PSU A. Socondary	Dolta	yes FCD16010092		03	ok
01 06	01 06	LCDI0010092	Derta	0.5	0K
PSIL A. Primary	Delta	FCD16010092		03	ok
01 06	01 06	UCDI0010092	Derea	00	0K
PSU 5. Communication	Delta	ECD16010092	Delta	03	ok
01 07	01 07	VAS	Derea	00	0 K
PSU 5. Secondary	Delta	ECD16010092	Delta	03	ok
01 06	01 06	Ves	Derea	00	0 A
PSU 5: Primary	Delta	ECD16010092	Delta	0.3	ok
01.06	01.06	Ves	20100		0.11
01.00	01.00	100			
CPLD					
			Onboard Version	Manifest	up-to-
date					1

MB_CPLD	1.05	1.05
MID_CPLD yes	1.03	1.03
* CPLD won't be updated by default (`update_ needed	fw all`), use `upda	ate_fw CPLD` if it's
FPGA		
03.0e Manifest up-to-date 03.0e 93.0e yes		

4.3. Known Issues

4.3.1. VBIOS cannot update due to running service processes

Issue

VBIOS update fails on *Red Hat Enterprise Linux 9* due to system service/process caching the resource to be upgraded.

Explanation

The following services (system processes) must be stopped manually for the firmware update to start:

- process nvidia-persistenced(pid 5372)
- process nv-hostengine(pid 2723)
- process cache_mgr_event(pid 5276)
- process cache_mgr_main(pid 5278)
- process dcgm_ipc(pid 5279)

If `xorg` is holding the resources, try to stop it by running \$ sudo systemct1 stop <display manager> where the (display manager) can be acquired by \$ cat /etc/X11/default-display-manager

4.3.2. [BCM users only] Firmware Update Completes with Error on Base Command Manager

Issue

When attempting to update the new -0R4 CPU Trays, a failure occurs during the update process where FWUC fails to list services:

Failure messages may include:

- Failed to install DGX 88064_Retimer dev 91 3.1.0
- Unable to unload NVIDIA drivers. The following process(es)/service(s) need to be stopped in order for switch firmware update to occur:
- `<blank>`

Workaround

1. Run:

\$ scontrol update NodeName=hostname State=drain Reason="FW update"

2. Wait for jobs on the host to complete and the status of node shows drained.

NOTE: if the output for the following command returns draining implies the node has jobs running and not ready; only proceed to step 2 only if the node status returns drained. \$ si\$ sinfo --state=drained | grep hostname

- 3. Stop `slurmd` service on compute node
 \$ ansible -i /opt/provisioning/inventory/ --become -m shell -a 'systemctl stop
 slurmd.service ' 'hostname'
- 4. Post firmware update: if host has been rebooted after firmware update, change host state to resume:

\$ scontrol update NodeName=hostname state=resume

Chapter 5. DGX A100 System Firmware Update Container Version 22.5.5

The DGX Firmware Update container version **22.5.5** is available.

- Package name:nvfw-dgxa100_22.5.5_220518.tar.gz
- Run file name: nvfw-dgxa100_22.5.5_220518.run
- Image name: nvfw-dgxa100:22.5.5
- ISO image: DGXA100_FWUI-22.5.5-2022-05-19-00-23-59.iso
- PXE netboot: pxeboot-DGXA100_FWUI-22.5.5.tgz

Highlights and Changes in this Release

- This release is supported with the following DGX OS software:
 - DGX OS 5.1 or later.
 - Important: This firmware update container does not support DGX OS 4.99.xx. To use the container on DGX A100 servers, update to DGX OS 5.1 or later.
 - EL7-21.10 or later (See <u>Special Instructions for Red Hat Enterprise Linux 7</u>)
 - EL8-21.08 Update 1 or later
- Fixed BMC issues
 - Fixed an issue so that certain sensors are now displaying in the BMC Web UI.
 - Fixed the graceful handling of system power loss, which prevents the BMC Flash file system consistency issue and improves recovery.
 - Fixed issues that caused the BMC usage to dramatically increase, which resulted in a POST failure with error code 91 or B4.

This fix also improves the error handling in the Redfish interface.

- Fixed the BMC Web UI security settings and page refresh during full screen mode.
- Fixed BMC SEL Event page, which was causing an error in certain SEL record parsing.

- Fixed an issue where the Power/Status LED was flashing continuously after the server was rebooted, and the Power/Status LED stayed on after the server was powered off.
- Added Redfish API support.
 - For more information, see Redfish API support in the <u>DGX A100 User Guide</u>.
 - For a list of known issues, see <u>Known Issues</u>.
- Fixed SBIOS issues
 - Fixed two issues that were causing boot order settings to not be saved to the BMC if applied out-of-band, causing settings to be lost after a subsequent firmware update.
 - Added interactive countdown messages during boot, to display the Setup Prompt
 Timeout configurable through the Boot > Setup Prompt Timeout configuration menu.
 - Added reporting of AGESA Version in SMBIOS.
 - Updated AGESA to version 1.0.0.D.

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table.

- If you are updating from 21.11.4 to 22.5.5, the total update time is approximately 1 hour and 3 minutes.
- If you are updating from 21.03.6 or earlier to 22.5.5, the total update time is approximately
 2 hours and 51 minutes.

The update time for each component is provided in the following table.

Component	Version	Key Changes	Update Time from 21.03.6 or earlier	Update Time from 21.11.4
BMC (via CEC)	00.17.07	Refer to <u>DGX A100 BMC</u> <u>Changes</u> for the list of changes.	31 minutes	31 minutes
SBIOS	1.13	Refer to <u>DGX A100 SBIOS</u> <u>Changes</u> for the list of changes.	6 minutes	6 minutes
Broadcom 88096 PCIe switch board	0.2.0	No change	1 minute	0 minute
BMC CEC SPI (mb_cec)	3.28	No change	7 minutes	0 minutes
PEX88064 Retimer	3.1.0	New support	1 minute	1 minutes
PEX88080 Retimer	3.1.0	New support	1 minute	1 minutes
NvSwitch BIOS	92.10.18.00.01	No change	2 minutes	0 minutes

Component	Version	Key Changes	Update Time from 21.03.6 or earlier	Update Time from 21.11.4	
VBIOS (A100 40GB)	92.00.45.00.03	Added security protection to the I2C interface.	2 minutes	0 minutes	
VBIOS (A100 80GB)	92.00.45.00.05	Added security protection to the I2C interface.			
VBIOS (A100 SystemB 80GB)	92.00.81.00.06	New support	N/A		
U.2 NVMe (Samsung)	EPK9CB5Q	Refer to <u>DGX A100 U.2</u> <u>NVMe Changes</u> for the list of changes.	5 minutes	0 minutes	
U.2 NVMe (Kioxia)	105	No change			
M.2 NVMe (Samsung version 1)	EDA7602Q	No change	0 minutes	0 minutes	
M.2 NVMe (Samsung version 2)	GDC7302Q	New support			
FPGA (GPU sled)	3.0e	New support	22 minutes	21 minutes	
CEC1712 SPI (GPU sled)	4.0	New support	3 minutes	3 minutes	
PSU (Delta rev04)	Primary 1.7/ Secondary 1.7/ Community 1.7	New support	0 minutes	0 minutes	
PSU (Delta rev03)	Primary 1.6/ Secondary 1.6/ Community 1.7	No change	90 minutes		
PSU (Delta rev02)	Primary 1.6/ Secondary 1.6/ Community 1.7	No change			
PSU (LiteOn)	908	No change	0 minutes		

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image.

When using $update_fw$ all, the update container updates both active and inactive images.

BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image.

The update container can only update the inactive image, and will update it only if the *active* image needs to be updated. After the update is completed, the updated inactive image becomes the active image. Because the active image is now updated, subsequent update_fw all commands will not update the inactive image. To update the inactive image in this case, use update_fw BMC --inactive. Since the container does not support updating the active image directly, commands such as update_fw BMC -a -f will not work.

DO NOT UPDATE DGX A100 CPLD FIRMWARE UNLESS INSTRUCTED

When updating DGX A100 firmware using the Firmware Update Container, do not update the CPLD firmware unless the DGX A100 system is being upgraded from 320GB to 640GB.

The current DGX A100 Firmware Update Container will not automatically update the CPLD firmware (for example, when running update_fw all). It is possible to update the CPLD firmware using "update_fw CPLD"; however, it is strongly recommended that the CPLD firmware not be updated manually unless specifically instructed by <u>NVIDIA Enterprise Support</u> (or email <u>enterprisesupport@nvidia.com</u>). If the DGX A100 is upgraded from 320GB to 640GB, the CPLD firmware update should be performed as instructed.

5.1. Special Instructions for Red Hat Enterprise Linux 7

This section describes the actions that must be taken before updating firmware on DGX A100 systems installed with Red Hat Enterprise Linux. There are two options for meeting these requirements.

Option 1: Update to EL7-22.05

Refer to the <u>DGX Software for Red Hat Enterprise Linux 7 Release Notes</u> for more information.

Important: Updating the DGX software for Red Hat Enterprise Linux will update the Red Hat Enterprise Linux installation to 7.9 or later. If you do not want to update your Red Hat Enterprise Linux 7 installation, then choose Option 2.

Option 2: Install mpt3sas 31.101.01.00-0

These instructions apply if:

- > You do not want to update your Red Hat Enterprise Linux installation, and
- > Your system is currently installed with Red Hat Enterprise Linux 7.7 or later.

Note: If your system is installed with Red Hat Enterprise Linux 7.6 or earlier, contact NVIDIA Enterprise Support for assistance.

- 1. Perform this step if your system is no longer pointing to the NVIDIA DGX software repository.
 - a). On Red Hat Enterprise Linux, run the following commands to enable additional repositories required by the DGX software.
 - \$ sudo subscription-manager repos --enable=rhel-7-server-extras-rpms
 - \$ sudo subscription-manager repos --enable=rhel-7-server-optional-rpms
 - b). Run the following command to install the DGX software installation package and enable the NVIDIA DGX software repository.

ATTENTION: By running these commands you are confirming that you have read and agree to be bound by the <u>DGX Software License Agreement</u>. You are also confirming that you understand that any pre-release software and materials available that you elect to install in a DGX may not be fully functional, may contain errors or design flaws, and may have reduced or different security, privacy, availability, and reliability standards relative to commercial versions of NVIDIA software and materials, and that you use pre-release versions at your risk.

```
$ yum install -y \
https://international.download.nvidia.com/dgx/repos/rhel-files/dgx-repo-
setup-20.03-1.el7.x86 64.rpm
```

2. Install mpt3sas 31.101.01.00-0.

\$ sudo yum install mpt3sas-dkms

3. Load the mpt3sas driver into the Red Hat Enterprise Linux kernel.

\$ sudo modprobe mpt3sas

You can verify the correct mpt3sas version is installed by issuing the following. \$ yum list installed

5.2. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container.

The commands use the .run file, but you can also use any method described in <u>Using the DGX</u> <u>A100 FW Update Utility</u>.

CAUTION:

- Do not log into the BMC dashboard UI while a firmware update is in progress.
- Stop all unnecessary system activities before attempting to update firmware.
- Stop all GPU activity, including accessing nvidia-smi, as this can prevent the VBIOS from updating.

- When issuing update_fw all, stop the following services if they are launched from Docker through the docker run command:
 - dcgm-exporter
 - nvidia-dcgm
 - nvidia-fabricmanager
 - nvidia-persistenced
 - xorg-setup
 - lightdm
 - nvsm-core
 - kubelet

The container will attempt to stop these services automatically, but will be unable to stop any that are launched from Docker.

- Do not add additional loads on the system (such as user jobs, diagnostics, or monitoring services) while an update is in progress. A high workload can disrupt the firmware update process and result in an unusable component.
- When initiating an update, the update software assists in determining the activity state of the DGX system and provides a warning if it detects that activity levels are above a predetermined threshold. If the warning is encountered, you are strongly advised to take action to reduce the workload before proceeding with the update.
- 1. Check if updates are needed by checking the installed versions.
 - \$ sudo ./nvfw-dgxa100_22.5.5_220518.run show_version
 - If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
 - If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 2. Perform the update for all firmware supported by the container.
 - \$ sudo ./nvfw-dgxa100_22.5.5_220518.run update_fw all

Depending on the firmware that is updated, you may be prompted to either reboot the system or power cycle the system.

- If you are prompted to reboot, issue
 \$ sudo reboot
- If you are prompted to power cycle, you can issue the following two commands (there
 is no output with the first command).
 - \$ sudo ipmitool raw 0x3c 0x04
 - \$ sudo ipmitool chassis power cycle
- 3. After rebooting or power cycling the system, you may need to perform another update_fw all to update other firmware.
 - Either repeat Step 1 to check if updates are needed and then perform Step 2 if needed, or
 - ▶ Repeat Step 2 just in case updates are needed.

If you perform another update_fw all, you may be prompted again to either reboot the system or power cycle the system.

See <u>DGX A100 Firmware Update Process</u> for more information about the update process.

You can verify the update by issuing the following.

\$ sudo ./nvfw-dgxa100_22.5.5_220518.run show_version

Example output for a DGX A100 640GB system

CEC =========							
			Onboar	d Version	Manife	st	up-to-
date MB_CEC(enabled)		3.28		3.28			
yes Delta_CEC(enabled) yes			4.00		4.00		
BMC DGX							
======= Image Id	Status	Locatio	n	Onboard Ver	sion 1	Manifest	up-
0:Active Boot	Online	Local		00.17.07		00.17.07	
1:Inactive Updatable yes		Local		00.17.07		00.17.07	
SBIOS							
Image Id 0:Active Boot Updat 1:Inactive Updatable	able	Onboard V 1.13 1.13	ersion	Manifest 1.13 1.13		up-to-dat yes yes	te
Switches							
============= PCI Bus#		Model	Onboar	d Version	Manife	st	FUB
Updated? up-to-date DGX - 0000:91:00.0(U2	e 261)	88064_Retimer	3.1.0		3.1.0		
DGX - 0000:88:00.0 (U2	260)	88064_Retimer	3.1.0		3.1.0		
DGX - 0000:4f:00.0(U2	262)	88064_Retimer	3.1.0		3.1.0		
DGX - 0000:48:00.0(U2 N/A yes	225)	88080_Retimer	3.1.0		3.1.0		
DGX - 0000:01:00.0(U1	L)	PEX88096	2.0		2.0		
N/A yes DGX - 0000:81:00.0(U3	3)	PEX88096	2.0		2.0		
N/A yes DGX - 0000:b1:00.0(U4	1)	PEX88096	2.0		2.0		
N/A yes DGX - 0000:41:00.0(U2 N/A yes	2)	PEX88096	2.0		2.0		
DGX - 0000:c4:00.0		LR10	92.10.	18.00.01	92.10.	18.00.01	
N/A yes DGX - 0000:c5:00.0		LR10	92.10.	18.00.01	92.10.	18.00.01	
N/A yes DGX - 0000:c6:00.0 N/A yes		LR10	92.10.	18.00.01	92.10.	18.00.01	
DGX -	0000:c7:00.0	LR10	92.10.18.00.01	92.10.18.00.01			
-------	--------------	------	----------------	----------------			
N/A	yes						
DGX -	0000:c8:00.0	LR10	92.10.18.00.01	92.10.18.00.01			
N/A	yes						
DGX -	0000:c9:00.0	LR10	92.10.18.00.01	92.10.18.00.01			
N/A	ves						

Mass Storage							
Drive Name/Slot	t Model N	lumber	Onboa	ard Version	Manifest	ι	ıp-
nvmeOn1 ves	Samsung MZWLJ3	T8HBLS-00007	EPK9	CB5Q	EPK9CB5Q		
nvmeln1 yes	Samsung MZWLJ3	T8HBLS-00007	EPK90	CB5Q	EPK9CB5Q		
nvme2n1 yes	Samsung MZ1LB1	T9HALS-00007	EDA7	602Q	EDA7602Q		
nvme3n1 yes	Samsung MZ1LB1	T9HALS-00007	EDA7	602Q	EDA7602Q		
nvme4n1 yes	Samsung MZWLJ3	T8HBLS-00007	EPK90	CB5Q	EPK9CB5Q		
nvme5n1 yes	Samsung MZWLJ3	T8HBLS-00007	EPK90	CB5Q	EPK9CB5Q		
nvme6n1 yes	Samsung MZWLJ3	T8HBLS-00007	EPK90	CB5Q	EPK9CB5Q		
nvme7n1 yes	Samsung MZWLJ3	T8HBLS-00007	EPK90	CB5Q	EPK9CB5Q		
nvme8n1 yes	Samsung MZWLJ3	T8HBLS-00007	EPK90	CB5Q	EPK9CB5Q		
nvme9n1 yes	Samsung MZWLJ3	T8HBLS-00007	EPK90	CB5Q	EPK9CB5Q		
Video BIOS							
Bus to-date	Model	Onboard Vers	ion	Manifest	FUB U	pdated?	up-
0000:07:00.0 ves	A100-SXM4-80GB	92.00.45.00.	05	92.00.45.00.	05	yes	
0000:0f:00.0 yes	A100-SXM4-80GB	92.00.45.00.	05	92.00.45.00.	05	yes	
0000:47:00.0 yes	A100-SXM4-80GB	92.00.45.00.	05	92.00.45.00.	05	yes	
0000:4e:00.0 yes	A100-SXM4-80GB	92.00.45.00.	05	92.00.45.00.	05	yes	
0000:87:00.0 yes	A100-SXM4-80GB	92.00.45.00.	05	92.00.45.00.	05	yes	
0000:90:00.0 yes	A100-SXM4-80GB	92.00.45.00.	05	92.00.45.00.	05	yes	
0000:b7:00.0 yes	A100-SXM4-80GB	92.00.45.00.	05	92.00.45.00.	05	yes	
0000:bd:00.0 yes	A100-SXM4-80GB	92.00.45.00.	05	92.00.45.00.	05	yes	

Power Supply					
============					
ID	Vendor	Model	MFR ID	Revision	Status
Onboard Version	Manifest	up-to-da	te		
PSU 0: Communication	Delta	ECD16010092	Delta	03	ok
01.07	01.07	yes			
PSU 0: Secondary	Delta	ECD16010092	Delta	03	ok
01.06	01.06	yes			
PSU 0: Primary	Delta	ECD16010092	Delta	03	ok
01.06	01.06	yes			

PSU 1:	Communication	Delta 01.07	ECD16010092	Delta	03	ok
PSU 1:	Secondary	Delta	ECD16010092	Delta	03	ok
PSU 1:	Primary	Delta	ECD16010092	Delta	03	ok
PSU 2:	Communication	Delta	ECD16010092	Delta	03	ok
PSU 2:	Secondary	Delta	ECD16010092	Delta	03	ok
PSU 2:	Primary	Delta	ECD16010092	Delta	03	ok
PSU 3:	Communication	Delta	ECD16010092	Delta	03	ok
PSU 3:	Secondary	Delta 01.06	ECD16010092 ves	Delta	03	ok
PSU 3: 01.06	Primary	Delta 01.06	ECD16010092 ves	Delta	03	ok
PSU 4: 01.07	Communication	Delta 01.07	ECD16010092 ves	Delta	03	ok
PSU 4: 01.06	Secondary	Delta 01.06	ECD16010092 ves	Delta	03	ok
PSU 4: 01.06	Primary	Delta 01.06	ECD16010092 yes	Delta	03	ok
PSU 5: 01.07	Communication	Delta 01.07	ECD16010092 yes	Delta	03	ok
PSU 5: 01.06	Secondary	Delta 01.06	ECD16010092 yes	Delta	03	ok
PSU 5: 01.06	Primary	Delta 01.06	ECD16010092 yes	Delta	03	ok
CPLD						
				Onboard Version	Manifest	up-to-
date MB_CPLI)			1.05	1.05	
yes MID_CPI yes	D			1.03	1.03	
* CPLD needec	won't be updat 1	ted by defa	ault (`update_	fw all`), use `upo	late_fw CPLD`	if it's

FPGA

======Onboard versionManifest up-to-date03.0e03.0eyes

5.3. Known Issues

5.3.1. Chassis Power State Remains On

Issue

When the system completes a GracefulShutdown and is queried by using Redfish, the Chassis Power State remains On, but the system power status will be correctly reported by using IPMI and in the BMC Web UI.

The system can be powered on by using the IPMI command or by using BMC Web UI.

5.3.2. Incorrect Thermal and Voltage Sensor and Fan RPM Values are Displayed

Issue

Some thermal and voltage sensors and FAN RPMs might show incorrect (Zero reading) values when retrieved by using the Redfish APIs.

Explanation

This issue is currently under investigation.

5.3.3. Processor Power Limit and Power Metrics are Not Supported

Issue

Some thermal sensor reading and FAN RPMs might show incorrect (a zero reading) value when they are retrieved through the Redfish API.

Explanation

This issue is currently under investigation.

5.3.4. IndicatorLED Status Might Display an Incorrect State

lssue

The IndicatorLED status in Redfish might display an incorrect state for the system and disk resources.

Explanation

This issue is currently under investigation.

5.3.5. Unable to Update BMC Firmware

lssue

To run Firmware Update Container Version 22.5.5, you must use MB_CEC version 3.28.

Explanation

If you are using an MB_CEC version that is earlier than 3.28, you must first update to firmware update container version 21.03.6 or later.

5.3.6. Firmware Update Container Unable to Recover PSU with Corrupted Firmware

lssue

The firmware update container cannot recover the PSU firmware when the container cannot determine the hardware revision of the PSU.

Explanation

To recover a PSU that is revision 00-03, use firmware update container version 21.11.4.

5.3.7. Setting Up Active Directory Settings Might Fail with "Invalid Domain Name" Error

Issue

After logging into the BMC dashboard UI and setting up and enabling Active Directory Authentication, an "Invalid Domain Name" error may occur.

Explanation

If you encounter this error, set up the DNS manually as follows:

- 1. Login to the BMC UI dashboard.
- 2. Navigate to Settings > Network Settings > DNS Configuration > "Domain Name Server Setting"
- 3. Find "Domain Name Server Setting" and change "Automatic" to "Manual".
- 4. Replace "DNS Server 1" IP to "8.8.8" (the IP is dns.google)
- 5. Click **Save** and accept the alert to restart the BMC network.

5.3.8. NVSM Incorrectly Reports the Delta PSU Part Number Instead of the Model Numbers

Issue

When issuing show_version or show_fw_manifest, the number associated with the Delta PSU is the part number instead of the model number.

Explanation

This will be resolved in a future release.

5.3.9. BMC KVM Screen May Show "No Signal" Under Certain Conditions

Issue

When attempting to view the DGX A100 console from the BMC Web UI KVM, the screen might show No Signal if you cold reset the BMC and reboot the server. This is due to a rare condition between BMC and the SBIOS.

For example, the issue might occur after performing the following:

- Issue the command to cold reset the BMC.
 \$ sudo ipmitool mc reset cold
- Wait about 30 seconds and issue the command to reboot the system.
 \$ sudo reboot

Explanation

You can recover the system by issuing a hard reset from the Web UI.

5.3.10. SBIOS "Bootup NumLock State" not Enforced

Issue

When turning NumLock to OFF after setting "**Boot NumLock State**" to ON from the SBIOS setup menu, NumLock remains off after rebooting the server. Similarly, when turning NumLock to ON after setting "**Boot NumLock State**" to OFF from the SBIOS setup menu, NumLock remains on after rebooting the server.

Explanation

This feature is currently not implemented in the DGX A100 SBIOS.

5.3.11. NVSM Fails to Run the FWUC show_version Command

Issue

This is an issue with NGC access without entering an email address for authentication

Explanation

To resolve this issue, upgrade to NVSM version 20.09.37 and later.

5.3.12. NVSM Exits With an Error Message When Updating Firmware by Using NVSM

Issue

When the firmware update container uses NVSM to update the firmware, after a few minutes, NVSM exits with the following message:

('Connection broken: IncompleteRead(0 bytes read)', IncompleteRead(0 bytes read)).

In the nvidia-fw.log, the update process continues in the background until it has completed.

Explanation

The system can be powered on by using the IPMI command or by using BMC Web UI.

5.3.13. After an FPGA Update, BMC Sel Log Shows Sensor-Related Errors

Issue

After a firmware update, the BMC sel log might show sensor-related errors.

Explanation

These errors can be safely ignored. To resolve this issue, upgrade to DGX OS 5.3 and later.

5.3.14. After a Firmware Update, Only the Delta Manifest Version Displays

Issue

After a firmware update, the Delta PSU version and the Delta manifest version should be displayed, but only the Delta manifest version appears.

Explanation

This issue will be fixed in a future release.

5.3.15. PSUs Sometimes Display an Error after an Update

lssue

When you run show_version, you might see ERR:retries in the container output and components might be listed as not-supported.

Explanation

To see the correct firmware versions and component status, run show_version again.

5.3.16. Force FPGA Update Sometimes Fails

lssue

When you force-update FPGA firmware, the update might fail, and the Auto updates are not allowed on a busy system message is displayed.

Explanation

This issue will be fixed in a future release.

5.3.17. Updating to Firmware Container Version 22.5.5 Fails for SSDs

Issue

The firmware container version 22.5.5 fails to update SSDs on systems where NVMe multipathing is enabled.

If the container fails to update a device that has c<number>, for example nvme0c0n1, in its name. This is because the device was a multipath device.

Disabling multipathing depends on the type of multipathing and the way it was enabled. As a result, you can update each SSD individually without disabling multipathing by running the following command:

update_fw SSD --select-ssd <ssd_name>

For example, here is a system with the following devices in show version:

Mass Storage				
Drive Name/Slot	Model Number	Onboard Version	Manifest	up-
nvme0n1	Samsung MZWLJ3T8HBLS-00007	EPK9CB5Q	EPK9CB5Q	
nvmeln1	Samsung MZ1LB1T9HALS-00007	EDA7602Q	EDA7602Q	
nvme2n1 ves	Samsung MZ1LB1T9HALS-00007	EDA7602Q	EDA7602Q	

To update nvmeOn1, run the following command:

update_fw SSD --select-ssd nvmeOn1

Chapter 6. DGX A100 System Firmware Update Container Version 21.11.4

The DGX Firmware Update container version 21.11.4 is available.

- Package name:nvfw-dgxa100_21.11.4_211111.tar.gz
- Run file name: nvfw-dgxa100_21.11.4_211111.run
- Image name: nvfw-dgxa100:21.11.4
- ISO image: DGXA100_FWUI-21.11.4-2021-11-12-09-20-53.iso
- PXE netboot: pxeboot-DGXA100-FWUI-21.11.4.tgz

Highlights and Changes in this Release

- This release is supported with the following DGX OS software -
 - DGX OS 5.0.1 or later
 - Important: This firmware update container does not support DGX OS 4.99.xx. To use the container on DGX A100 servers, update to DGX OS 5.0.1 or later.
 - EL7-21.04 or later (See <u>Special Instructions for Red Hat Enterprise Linux 7</u>)
 - EL8-20.11 or later
- Fixed BMC issues
 - Fixed incorrect temperatures reported for sensors on the NVIDIA Networking ConnectX-6 single-port and dual-port VPI cards.
 - Fixed BMC user data (username, password, privileges) getting lost after BMC upgrade.
 - Added ability to set the BMC to local time instead of the default UTC.
 - Added authentication capabilities to the BMC RESTful API.
 - Added new capabilities to identify firmware update in the System Event Log (SEL) on the BMC.

- Fixed the bug to ensure that the BMC will boot to the latest version updated on the system.
- Fixed SBIOS issues
 - Added Memory correctable ECC Error leaky bucket, preventing unnecessary replacement of working system DIMMs.
 - Fixed PXE boot configuration not persisting, helpful for multiple DGX A100 nodes.
 - Fixed inability to enter SBIOS Admin/User password from the Serial over LAN console.
- Fixed U.2 NVMe driver issues
 - Improved write performance while performing drive wear-leveling.
- Addressed the needs of security-conscious customers who no longer support Python 2.7 by using Python 3 in the NVIDIA containerless .run file.
- IPMITool: "ipmitool -I lan" is no longer supported. Instead, use "ipmitool -I lanplus".

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table.

- ▶ If updating from 21.05.7 or 21.03.6, the total update time is approximately 44 minutes.
- If updating from 20.12.3.3 or earlier, the total update time is approximately 3 hours and 22 minutes.

The update time for each component is provided in the following table.

Component	Version	Key Changes	Update Time from 20.12.3.3 or earlier	Update Time from 21.05.7 or 21.03.6
BMC (via CEC)	00.16.09	Refer to <u>DGX A100 BMC</u> <u>Changes</u> for the list of changes.	32 minutes	32 minutes
SBIOS	1.09	Refer to <u>DGX A100 SBIOS</u> <u>Changes</u> for the list of changes.	5 minutes	5 minutes
Broadcom 88096 PCIe switch board	0.2.0	No change	1 minute	0 minute
BMC CEC SPI	v3.28	No change	22 minutes	0 minutes
PEX88064 Retimer	1.2f	No change	1 minute	0 minutes
PEX88080 Retimer	1.2f	No change	1 minute	0 minutes
NvSwitch BIOS	92.10.18.00.01	No change	2 minutes	0 minutes

Component	Version	Key Changes	Update Time from 20.12.3.3 or earlier	Update Time from 21.05.7 or 21.03.6
VBIOS (A100 40GB)	92.00.45.00.03	Added security protection to the I2C interface.	7 minutes	3 minutes
VBIOS (A100 80GB)	92.00.45.00.05	Added security protection to the I2C interface.		
U.2 NVMe (Samsung)	EPK9CB5Q	Refer to <u>DGX A100 U.2</u> <u>NVMe Changes</u> for the list of changes.	4 minutes	4 minutes
U.2 NVMe (Kioxia)	0105	No change		
M.2 NVMe (Samsung version 1)	EDA7602Q	No change	4 minutes	0 minutes
M.2 NVMe (Samsung version 2)	GDC7202Q	New support		
FPGA (GPU sled)	2.A5	No change	22 minutes	0 minutes
CEC1712 SPI (GPU sled)	3.9	No change	3 minutes	0 minutes
PSU (Delta)	Primary 1.6/ Secondary 1.6/ Community 1.7	No change	90 minutes	0 minutes
PSU (LiteOn)	v0908	New support		

BMC 00.16.12 on Newer CPU Motherboards

Newer CPU motherboards are manufactured and shipped with BMC version 00.16.12. This BMC version provides an updated PCIe setting that is required by the newer (-004) motherboards. Do not attempt to downgrade the BMC on these motherboards using the firmware update container.

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. When using update_fw all, the update container updates both active and inactive images.

BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image, and will update it only if the *active* image needs to be updated. After the update is completed, the updated inactive image becomes the active image. Because the active image is now updated, subsequent update_fw all commands will not update the inactive image. To update the inactive image in this case, use update_fw BMC --inactive. Since the container does not support updating the active image directly, commands such as update_fw BMC -a -f will not work.

Updating the PSU FW

- If the PSU update fails due to a failure in the PSU recovery, power cycle the PSU and then perform the PSU update again. The following are some methods for power cycling the PSU:
 - Remove power from the failed PSU by turning off the rack PDU output to that PSU and then turning it back on after a few moments. (If necessary, run the container using the show_version option to determine which PSU is reported as "not-ok").
 - Physically disconnect power to the PSU by disconnecting one end of the PSU power cord and then reconnect after a few moments. (If necessary, run the container using the show_version option to determine which PSU is reported as "not-ok").
 - AC power cycle the server.
 \$ sudo ipmitool raw 0x3c 0x04
 \$ sudo ipmitool chassis power cycle

DO NOT UPDATE DGX A100 CPLD FIRMWARE UNLESS INSTRUCTED

When updating DGX A100 firmware using the Firmware Update Container, do not update the CPLD firmware unless the DGX A100 system is being upgraded from 320GB to 640GB.

The current DGX A100 Firmware Update Container will not automatically update the CPLD firmware (for example, when running update_fw all). It is possible to update the CPLD firmware using "update_fw CPLD"; however, it is strongly recommended that the CPLD firmware not be updated manually unless specifically instructed by <u>NVIDIA Enterprise Support</u> (or email <u>enterprisesupport@nvidia.com</u>). If the DGX A100 is upgraded from 320GB to 640GB, the CPLD firmware update should be performed as instructed.

6.1. Special Instructions for Red Hat Enterprise Linux 7

This section describes the actions that must be taken before updating firmware on DGX A100 systems installed with Red Hat Enterprise Linux. There are two options for meeting these requirements.

Option 1: Update to EL7-21.01 or later

Refer to the <u>DGX Software for Red Hat Enterprise Linux 7 Release Notes</u> for more information.

Important: Updating the DGX software for Red Hat Enterprise Linux will update the Red Hat Enterprise Linux installation to 7.9 or later. If you do not want to update your Red Hat Enterprise Linux 7 installation, then choose Option 2.

Option 2: Install mpt3sas 31.101.01.00-0

These instructions apply if

- > You do not want to update your Red Hat Enterprise Linux installation, and
- > Your system is currently installed with Red Hat Enterprise Linux 7.7 or later.

Note: If your system is installed with Red Hat Enterprise Linux 7.6 or earlier, contact NVIDIA Enterprise Support for assistance.

- 1. Perform this step if your system is no longer pointing to the NVIDIA DGX software repository.
 - a). On Red Hat Enterprise Linux, run the following commands to enable additional repositories required by the DGX software.
 sudo subscription-manager repos --enable=rhel-7-server-extras-rpms

```
sudo subscription manager repos --enable=rhel-7-server-optional-rpms
```

- b). Run the following command to install the DGX software installation package and enable the NVIDIA DGX software repository.
 - **ATTENTION:** By running these commands you are confirming that you have read and agree to be bound by the <u>DGX Software License Agreement</u>. You are also confirming that you understand that any pre-release software and materials available that you elect to install in a DGX may not be fully functional, may contain errors or design flaws, and may have reduced or different security, privacy, availability, and reliability standards relative to commercial versions of NVIDIA software and materials, and that you use pre-release versions at your risk.

```
yum install -y \
https://international.download.nvidia.com/dgx/repos/rhel-files/dgx-repo-
setup-20.03-1.el7.x86_64.rpm
```

2. Install mpt3sas 31.101.01.00-0.

sudo yum install mpt3sas-dkms

3. Load the mpt3sas driver into the Red Hat Enterprise Linux kernel.

sudo modprobe mpt3sas

You can verify the correct mpt3sas version is installed by issuing the following. yum list installed

6.2. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container. The commands use the .run file, but you can also use any method described in <u>Using the DGX A100 FW Update Utility</u>.

CAUTION:

- Do not log into the BMC dashboard UI while a firmware update is in progress.
- Stop all unnecessary system activities before attempting to update firmware.
- Stop all GPU activity, including accessing nvidia-smi, as this can prevent the VBIOS from updating.
- When issuing update_fw all, stop the following services if they are launched from Docker through the docker run command:
 - dcgm-exporter
 - nvidia-dcgm
 - nvidia-fabricmanager
 - nvidia-persistenced
 - xorg-setup
 - lightdm
 - nvsm-core
 - kubelet

The container will attempt to stop these services automatically, but will be unable to stop any that are launched from Docker.

- Do not add additional loads on the system (such as user jobs, diagnostics, or monitoring services) while an update is in progress. A high workload can disrupt the firmware update process and result in an unusable component.
- When initiating an update, the update software assists in determining the activity state of the DGX system and provides a warning if it detects that activity levels are above a predetermined threshold. If the warning is encountered, you are strongly advised to take action to reduce the workload before proceeding with the update.
- 1. Check if updates are needed by checking the installed versions.
 - \$ sudo ./nvfw-dgxa100:21.11.4_211111.run show_version
 - If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
 - If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 2. Perform the update for all firmware supported by the container.

\$ sudo ./nvfw-dgxa100:21.11.4_211111.run update_fw all

Depending on the firmware that is updated, you may be prompted to either reboot the system or power cycle the system.

- If you are prompted to reboot, issue
 \$ sudo reboot
- If you are prompted to power cycle, you can issue the following two commands (there
 is no output with the first command).
 - \$ sudo ipmitool raw 0x3c 0x04
 - \$ sudo ipmitool chassis power cycle
- 3. After rebooting or power cycling the system, you may need to perform another update_fw all to update other firmware.
 - Either repeat Step 1 to check if updates are needed and then perform Step 2 if needed, or
 - ▶ Repeat Step 2 just in case updates are needed.

If you perform another update_fw all, you may be prompted again to either reboot the system or power cycle the system.

See <u>DGX A100 Firmware Update Process</u> for more information about the update process.

You can verify the update by issuing the following.

Ś	sudo	/nvfw-dqxa100.21 11 4	211111 run	show version	
Ŷ	Suuo	./ HVIW UgAaroo.21.11.4		SHOW_VEISION	

Example output for a DGX A100 320GB system

CEC				
MB_CEC(enabled) Delta_CEC(enabled)		Onboard Version 3.28 3.09	Manifest 3.28 3.09	up-to-date yes yes
BMC DGX =======				
Image Id Si O:Active Boot On 1:Inactive Updatable	tatus Locatic nline Local Local	on Onboard Versior 00.16.09 00.16.09	Manifest 00.16.09 00.16.09	up_to_date yes yes
SBIOS ======				
Image Id 0:Inactive Updatable 1:Active Boot Updatab	le	Onboard Versior 1.09 1.09	Manifest 1.09 1.09	up_to_date yes yes
Switches =========				
PCI Bus# date	Model On	board Version Manife	st FUB Updat	ed? up-to-
DGX - 0000:91:00.0(U261) DGX - 0000:88:00.0(U260) DGX - 0000:4f:00.0(U262) DGX - 0000:4f:00.0(U225)) 88064_Retimer) 88064_Retimer) 88064_Retimer) 88080_Retimer	1.2.0 1.2.0 1.2.0 1.2.0 1.2.0 1.2.0 1.2.0 1.2.0 1.2.0 1.2.0	N/A N/A N/A N/A	yes yes yes yes
DGX - 0000:01:00.0(U1) DGX - 0000:b1:00.0(U4) DGX - 0000:41:00.0(U2) DGX - 0000:81:00.0(U3)	PEX88096 PEX88096 PEX88096 PEX88096	2.02.02.02.02.02.02.02.0	N/A N/A N/A N/A	yes yes yes yes

DGX - 0000:c4:	00.0	LR10 9	2.10.	18.00	.01	92.10	.18.00	.01 N	J/A	yes
DGX - 0000:c5:	00.0	LR10 9	2.10.	.18.00	.01	92.10	.18.00	.01 N	J/A	yes
DGX - 0000:c8:	00.0	LR10 9	2.10.	.18.00	.01	92.10	.18.00	.01 N	J/A	yes
DGX - 0000:c6:	00.0	LR10 9	2.10.	.18.00	.01	92.10	.18.00	.01 N	J/A	yes
DGX - 0000:c9:	00.0	LR10 9	2.10.	.18.00	.01	92.10	.18.00	.01 N	J/A	yes
DGX - 0000:c7:	00.0	LR10 9	2.10.	.18.00	.01	92.10	.18.00	.01 N	J/A	yes
Mass Storage										
================										
Drive Name/Slo	t M	Iodel Numbe	r	C	nboa	ard Ver	sion	Manif	lest up	-to-date
nvmeOnl	Samsung	MZWLJ3T8HE	LS-00	0007	EPK9	CB5Q		EPK9C	CB5Q	yes
nvmelnl	Samsung	MZILBIT9HA	LS-00	0007	EDA /	602Q		EDA/6	502Q	yes
nvmezni numežni	Samsung	MZILBIT9HA	LS-UU		EDA /	CDEO		EDA / 6	DUZQ	yes
nymo/n1	Samsung	MZWLUJIOHE		007	EFN3	CBJQ		EFRAC	263Q 7850	yes
nvme5n1	Samsung	MZWLJ3T8HE	LS-00	007	EPK9	CB50		EPK9C	CB50	ves
	2 411.2 411.9		20 00					221000	202	100
Video BIOS										
Bus	Model	Onb	oard	Versi	on	Manif	est	FUB	Updated?	up-to-
date									-	-
0000:07:00.0	A100-SXM4-	40GB 92.	00.45	5.00.0	3	92.00.	45.00.	03 ye	es	yes
0000:0f:00.0	A100-SXM4-	40GB 92.	00.45	5.00.0	3	92.00.	45.00.	03 ye	es	yes
0000:47:00.0	A100-SXM4-	-40GB 92.	00.45	00.0	13	92.00.	45.00.	03 Ye	es	yes
0000:40:00.0	A100-SXM4-	40GB 92.	00.45		3	92.00.	45.00.	03 Ye	es	yes
	A100-SXM4-	40GB 92.	00.45	5.00.0	3	92.00.	45.00.	03 Ye	es	yes
0000.90.00.0	A100-SXM4-	40GB 92.	00.40	5.00.0	3	92.00.	45.00.	03 ye	-5	yes
0000:bd:00.0	A100-SXM4-	-40GB 92.	00.45	5.00.0	3	92.00.	45.00.	03 ye	es	yes
FPGA										
	n Manif		date							
02 a5		est up-to	-dale	2						
02.43	02.ac	, уе	5							
Power Supply										
							On	board		
ТD	Vendo	or Model		MFR T	D S	Status	Vers	ion	Manifest	-ot-au
date	Venac	, nouci				cucub	VCID	1011	1141111000	up co
PSU 0: Primary	Delta	ECD160100	92	Delta	L	ok	01	.06	01.06	ves
PSU 0: Seconda	ry Delta	ECD160100	92	Delta	L	ok	01	.06	01.06	yes
PSU 0: Communi	ty Delta	ECD160100	92	Delta	L	ok	01	.07	01.07	yes
PSU 1: Primary	Delta	ECD160100	92	Delta	L	ok	01	.06	01.06	yes
PSU 1: Seconda	ry Delta	ECD160100	92	Delta	L	ok	01	.06	01.06	yes
PSU 1: Communi	ty Delta	ECD160100	92	Delta	L	ok	01	.07	01.07	yes
PSU 2: Primary	Delta	ECDI60100	92	Delta	L	ok	01	.06	01.06	yes
PSU 2: Seconda	ry Delta	ECD160100	92	Delta	L	ok	01	.06	01.06	yes
PSU 2: Communi	ty Delta Delta	ECDI60100	92	Delta	L	OK al-	01	.07	01.07	yes
PSU 3: Primary	Delta	ECD160100	92	Delta		ok	01	.06	01.06	yes
PSU 3. Seconda	ty Della	ECD160100	92	Delta	<u>.</u>	ok	01	.00	01.00	yes
PSU 4. Primary	Deile Deile	ECD160100	92	Delta		ok	01	.06	01 06	yes
PSU 4: Seconda	rv Delta	ECD160100	92	Delta		ok	01	.06	01.06	Ves
PSU 4: Communi	ty Delta	ECD160100	92	Delta		ok	01	.07	01.07	ves
PSU 5: Primary	Delta	ECD160100	92	Delta	L	ok	01	.06	01.06	yes
PSU 5: Seconda	ry Delta	ECD160100	92	Delta	L	ok	01	.06	01.06	yes
PSU 5: Communi	ty Delta	ECD160100	92	Delta	L	ok	01	.07	01.07	yes
CPLD										
				0.1						
MID CDID				Unbo	ard	Versio	n Ma 1	nitest	: u	p-to-date
MB CDID MID CLTD				1.03			⊥. 1	03		yes
LID_CLTD				1.03			⊥.	0.5		yes

```
* CPLD won't be updated by default (`update_fw all`), use `update_fw CPLD` if it's needed
```

6.3. Known Issues

6.3.1. BMC Incorrectly Reports CPU Motherboard Overvoltage

Issue

The BMC incorrectly reports that the sensors for 3.3V and 5V_STBY on the CPU motherboard exceed the non-critical thresholds. The assertion is reported in the SEL logs.

Explanation

This is an issue with the BMC where it is not interpreting the sensor information properly. The SEL gets filled with voltage messages but otherwise there is no functional impact. The values reported in the SEL confirm that the threshold has not been exceeded.

6.3.2. TEMP_IO0_IB0_P0 Reading not Reported in BMC "Disabled Sensors" List

Issue

The TEMP_IO0_IB0_P0 sensor does not appear in the BMC web UI when it is disabled.

Explanation

This is an issue with the BMC web UI and will be resolved in the future release. You can issue ipmitool sensor or ipmitool sdr list to see information on disabled sensors.

6.3.3. nvipmitool Reports PCIe Correctable Errors as "Asserted"

Issue

The nvipmitool includes an Asserted text when reporting PCIe correctable errors without further explanation.

Explanation

"Asserted" just means that correctable errors were found in the test.

6.3.4. KVM "Power On Server" Option is Grayed Out

lssue

If the system is powered off, you may not be able to "power on" the system using the BMC KVM ("Power On Server" option is grayed out).

Explanation

To work around, log in to the BMC Web UI, then navigate to the Power Control dialog and select "**Power On**".

6.3.5. BMC Web UI Performance Drop

lssue

Several BMC web UI tasks - such as BMC login, getting SEL lists, or getting SDR lists - may be slower to complete compared to previous BMC versions.

Explanation

NVIDIA is investigating this issue.

6.3.6. SOL Cannot be Activated for a Newly Created User Account

Issue

After created a new user account, attempts to activate SOL for that account fail.

Explanation

NVIDIA is investigating the issue. To work around, enable the SOL payload for the new user.

Example:

\$ sudo ipmitool sol payload enable 1 5
Then retry activating SOL again.

6.3.7. Unable to Set Static IPv6 Address Using BMC Web UI

Issue

1. From the BMC web UI, navigate to **Settings -> Network -> Network IP Settings**.

2. Deselect **Enable IPv6 DHCP** and input an IPv6 Address and Subnet Prefix length, then click **Save**.

The changes are not made.

Explanation

To work around, set the IPv6 address using the command line.

6.3.8. The BMC KVM May Stop Accepting Keyboard Input on the OS Command Line

lssue

When this occurs, the terminal will hang or not accepting any key strokes. After continuing to press keys, an error message appears indicating the HID queue is getting full.

Explanation

This may occur if the USB service is not enabled. To resolve, enable USB in the kernel and try again. The following is an example on Red Hat Enterprise Linux:

- 1. Remove "nousb" from /boot/efi/EFI/redhat/grub.cfg.
- 2. Configure grub using grub2-mkconfig -o /boot/efi/EFI/redhat/grub.cfg.
- 3. Reboot.
- 4. Verify USB is enabled by using the command "lsscsi -H | grep usb-storage".
- 5. Try KVM console.

6.3.9. BMC Kernel Panic Upon Power Cycle then BMC Reset Sequence

Issue

BMC kernel panic may occur when performing the following:

- 1. Issue'ipmitool chassis power cycle'.
- 2. Wait several seconds.
- 3. Issue'impitool mc reset cold'

Explanation

This is a timing issue that results in the loss of IRQ 8, resulting in the kernel panic. The BMC will continue to reboot until it is successful.

6.3.10. REDUNDANCY_PSU Sensor May Report 0x0a80 for Sensor Status

Issue

The REDUNDANCY_PSU sensor status of 0x0a80 indicates that redundancy is lost.

Explanation

NVIDIA is investigating this issue. The reported sensor status is misleading but has no functional impact.

6.3.11. SBIOS "Bootup NumLock State" not Enforced

lssue

When turning NumLock to OFF after setting "**Boot NumLock State**" to ON from the SBIOS setup menu, NumLock remains off after rebooting the server. Similarly, when turning NumLock to ON after setting "**Boot NumLock State**" to OFF from the SBIOS setup menu, NumLock remains on after rebooting the server.

Explanation

This feature is currently not implemented in the DGX A100 SBIOS.

6.3.12. Updating only Active or Inactive SBIOS Can Cause Internal Compatibility Issues

Issue

If you use the -a (active image only) or -i (inactive image only) option when updating the SBIOS, the fail-safe flag may get set and not removed upon reboot.

Explanation

When updating the SBIOS, both active and inactive SBIOS images must be updated. Do not use the -a or -i option. Instead, let the firmware update container automatically update both active and inactive images by using either "update_fw all" or "update_fw SBIOS".

6.3.13. IPMITool "Persistent" Flag Does not Work

lssue

The ipmitool persistent flag does not take effect when using the standard command format; for example,

ipmitool chassis bootdev options=persistent, efiboot

The persistent flag does work when part of the raw command.

Explanation

This is an issue with IPMITool. To use the persistent flag, use in conjunction with a raw command.

Example: The following raw command corresponds to the example command in the issue description:

ipmitool raw 01 05 e0 04 00 00 00 "e0" specifies PXE boot with EFI.

6.3.14. User is Logged Out of the BMC Web UI After Powering On the System

Issue

To reproduce the issue:

- 1. AC power cycle the system.
- 2. Log into the BMC web UI and then power on the system, such as through the BMC KVM.

The user is logged out of the BMC web UI.

Explanation

This behavior is the result of the BMC erroneously concluding that the BMC was idle for too long. The AC power cycle resets the BMC RTC to the default value (1999). After powering on the system, the current time is compared to the BMC RTC value and the difference exceeds the timeout value. This is a limitation in the DGX A100 BMC.

6.3.15. SBIOS Versions Might not be Reported After BMC Cold Reboot

Issue

After performing a BMC cold boot, the SBIOS versions (both primary and secondary) are reported as "0" either in the BMC web UI or on the command line.

Explanation

To work around, perform the following.

- 1. Reboot
- 2. Verify that the active SBIOS version is populated: \$ sudo ipmitool raw 0x3c 0x24 (\$ sudo ipmitool raw 0x3c 0x22)
- 3. Switch to the inactive SBIOS.
 \$ sudo ipmitool raw 0x3c 0x23 \$((\$(sudo ipmitool raw 0x3c 0x22)^1))
- 4. Reboot again.
- 5. Verify that both active and inactive SBIOS versions are populated.
 \$ sudo ipmitool raw 0x3c 0x24 0 && sudo ipmitool raw 0x3c 0x24 1

6.3.16. NVSM Incorrectly Reports the Delta PSU Part Number Instead of the Model Numbers

lssue

When issuing show_version or show_fw_manifest, the number associated with the Delta PSU is the part number instead of the model number.

Explanation

This will be resolved in a future release.

6.3.17. BMC KVM Screen May Show "No Signal" Under Certain Conditions

Issue

When attempting to view the DGX A100 console from the BMC Web UI KVM, the screen may show "No Signal" if you cold reset the BMC and then reboot the server.

For example, the issue might occur after performing the following.

1. Issue the command to cold reset the BMC.

```
$ sudo ipmitool mc reset cold
```

Wait about 30 seconds, then issue the command to reboot the system.
 \$ sudo reboot

Explanation

This is due to a rare race condition between BMC and the SBIOS, and will be resolved in a future update.

6.3.18. "Power On Server" Option in KVM is Grayed Out

Issue

If the system is powered off, you may not be able to "power on" the system using the BMC KVM ("Power On Server" option is grayed out).

Explanation

To work around, log in to the BMC Web UI, then navigate to the Power Control dialog and select "**Power On**".

6.3.19. BMC SEL Log May Show a Negative Value for Sensor "TEMP_MB_AD_CARD" During AC/ DC/Warm reboot

Issue

After any kind of reboot (AC/DC/warm reboot), the BMC SEL log may show a negative value for "Temperature TEMP_MB_AD_CARDO".

Explanation

This issue will be resolved in a future release.

6.3.20. Setting Up Active Directory Settings May Fail with "Invalid Domain Name" Error

Issue

After logging into the BMC dashboard UI and setting up and enabling Active Directory Authentication, an "Invalid Domain Name" error may occur.

If you encounter this error, set up the DNS manually as follows:

- 1. Login to the BMC UI dashboard.
- 2. Navigate to Settings > Network Settings > DNS Configuration > "Domain Name Server Setting"
- 3. Find "Domain Name Server Setting" and change "Automatic" to "Manual".
- 4. Replace "DNS Server 1" IP to "8.8.8" (the IP is dns.google)
- 5. Click **Save** and accept the alert to restart the BMC network.

6.3.21. Systems Won't PXE Boot After BMC and CEC FW Update

Issue

After updating the BMC and CEC firmware, the system may fail to PXE boot.

Explanation

If you encounter this issue, perform a factory reset of the BMC and reconfigure usernames and passwords.

Using the BMC web UI

- Navigate to Maintenance > Preserve Configuration, then clear all check boxes and click Save.
- 2. Navigate to Maintenance > Restore Factory Defaults, then click Save.

Using the IPMITool OEM Commands

- 1. Specify "do not preserve configuration". sudo ipmitool raw 0x32 0xba 0x00 0x00
- Restore defaults. sudo ipmitool raw 0x32 0x66

6.3.22. BMC UI May not be Accessible from Mac OS

lssue

When attempting to connect to the DGX A100 BMC from a system with Mac OS, a "Your connection is not private" message appears that prevents access to the BMC.

Starting with version 0.13.6, the BMC provides a self-signed certificate which Mac OS flags in the browser. Most browsers will let you either accept the risk and continue, or add the certificate to the keychain and continue. The Chrome and Opera browsers, however, do not provide these options and so Mac OS users will not be able to access the BMC from the Chrome or Opera browser.

To access the DGX A100 BMC, Mac OS users can use Safari or Firefox, which provide an access path.

6.3.23. Unable to Launch BMC Dashboard under Pre-84.01 Firefox

Issue

After updating the BMC, attempts to access the BMC dashboard using Firefox versions earlier than 84.01 fail with a "Secure Connection Fail" message.

Explanation

To work around, update Firefox to version 84.01 or later.

6.3.24. The system starts the POST process several times during boot after updating the SBIOS.

Issue

After updating the SBIOS and rebooting the system, the NVIDIA splash screen appears and disappears several times before boot is completed.

Explanation

After updating the SBIOS, several component states are cleared and the system may reboot automatically 3-4 times to reset all the components. This is expected behavior.

6.3.25. Restoring BMC Default Affects Power LED

Issue

After restoring the factory default settings using the BMC,

- The Power/Status LED flashes continuously after the rebooting the server.
- The Power/Status LED stays on after powering off the server.

NVIDIA is investigating this issue. There is no functional impact.

6.3.26. The "Relative Mouse Mode" Option is grayed out in the KVM Menu

lssue

In the BMC Remote KVM, the Mouse > Relative Mouse Mode option is grayed out and unavailable.

Explanation

To work around, enable Relative Mouse Mode from the BMC web UI as follows:

Navigate to **Settings > KVM Mouse Setting,** then select "**Relative Positioning (Linux)**" from the Mouse Mode Configuration dialog and click **Save**.

Chapter 7. DGX A100 System Firmware Update Container Version 21.05.7

The DGX Firmware Update container version 21.05.7 is available.

- Package name:nvfw-dgxa100_21.05.7_210519.tar.gz
- Run file name: nvfw-dgxa100_21.05.7_210519.run
- Image name: nvfw-dgxa100:21.05.7
- ISO image: DGXA100_FWUI-21.05.7-2021-05-19-07-26-16.iso
- PXE netboot: pxeboot-dgxa100-21.05.7.tgz

Highlights and Changes in this Release

- This release is supported with the following DGX OS software -
 - DGX OS 5.0 or later
 - Important: This firmware update container does not support DGX OS 4.99.xx. To use the container on DGX A100 servers, update to DGX OS 5.0 or later.
 - EL7-21.01 or later (See <u>Special Instructions for Red Hat Enterprise Linux</u>)
 - EL8-20.11 or later
- Eliminated the need for the workaround when updating the CEC 1712 SPI from 3.5 to 3.9.
- Fixed OW reporting issue with Delta PSU.

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table. The update time for each component is provided for reference. Total update time if all components are updated is approximately 2 hours and 20 minutes.

Component	Version	Key Changes	Update Time
BMC (via CEC)	00.14.17	See <u>DGX A100 BMC Changes</u>	25 minutes
SBIOS	0.34	No change	7 minutes
Broadcom 88096 PCIe switch board	0.2.0	No change	8 minutes
BMC CEC SPI	v3.28	No change	8 minutes
PEX88064 Retimer	1.2f	No change	7 minutes
PEX88080 Retimer	1.2f	No change	7 minutes
NvSwitch BIOS	92.10.18.00.01	No change	8 minutes
VBIOS (A100 40GB)	92.00.36.00.04	No change	7 minutes
VBIOS (A100 80GB)	92.00.36.00.01	No change	
U.2 NVMe (Samsung)	EPK99B5Q	No change	6 minutes
U.2 NVMe (Kioxia)	0105	No change	
M.2 NVMe (Samsung)	EDA7602Q	No change	3 minutes
FPGA (GPU sled)	2.A5	No change	40 minutes
CEC1712 SPI (GPU sled)	3.9	No change	7 minutes
PSU (Delta)	Primary 1.6 / Secondary 1.6 / Community 1.7	Added to container	90 minutes

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

- SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. When using update_fw all, the update container updates both active and inactive images.
- BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image, and will update it only if the *active* image needs to be updated. After the update is completed, the updated inactive image becomes the active image. Because the active image is now updated, subsequent update_fw all commands will not update the inactive image. To update the inactive image in this case, use update fw BMC --inactive.

Updating the PSU FW

If one of the PSU firmware slots (primary, secondary, or community) is corrupted, updating the PSU firmware will fail if attempts are made to update other slots.

- If you know the slot that is corrupted, then update that slot as follows (where <psu> is 0, 1, 2, 3, 4, or 5; <Slot> is Primary, Secondary, Or Community); \$ sudo ./nvfw-dgxa100_21.05.7_210519.run update_fw PSU -s <psu> -S <Slot> -f
- If you do not know which slot is corrupted, then use the SKIP_FAIL flag to update all three slots.

```
$ sudo ./nvfw-dgxa100_21.05.7_210519.run set_flags SKIP_FAIL=1 update_fw PSU -s
<psu> -f
```

The FWUC may display a message about the PSU update failing in the non-corrupted slots, but the PSU should actually be recovered because the corrupted slot is successfully updated.

DO NOT UPDATE DGX A100 CPLD FIRMWARE UNLESS INSTRUCTED

When updating DGX A100 firmware using the Firmware Update Container, do not update the CPLD firmware unless the DGX A100 system is being upgraded from 320GB to 640GB.

The current DGX A100 Firmware Update Container will not automatically update the CPLD firmware (for example, when running update_fw all). It is possible to update the CPLD firmware using "update_fw CPLD"; however, it is strongly recommended that the CPLD firmware not be updated manually unless specifically instructed by <u>NVIDIA Enterprise Support</u> (or email <u>enterprisesupport@nvidia.com</u>). If the DGX A100 is upgraded from 320GB to 640GB, the CPLD firmware update should be performed as instructed.

7.1. Special Instructions for Red Hat Enterprise Linux

This section describes the actions that must be taken before updating firmware on DGX A100 systems installed with Red Hat Enterprise Linux. There are two options for meeting these requirements.

Option 1: Update to EL7-21.01 or later

Refer to the <u>DGX Software for Red Hat Enterprise Linux 7 Release Notes</u> for more information.

Important: Updating the DGX software for Red Hat Enterprise Linux will update the Red Hat Enterprise Linux installation to 7.9 or later. If you do not want to update your Red Hat Enterprise Linux 7 installation, then choose Option 2.

Option 2: Install mpt3sas 31.101.01.00-0

These instructions apply if

- > You do not want to update your Red Hat Enterprise Linux installation, and
- > Your system is currently installed with Red Hat Enterprise Linux 7.7 or later.

If your system is installed with Red Hat Enterprise Linux 7.6 or earlier, contact NVIDIA Enterprise Support for assistance.

- 1. Perform this step if your system is no longer pointing to the NVIDIA DGX software repository.
 - a). On Red Hat Enterprise Linux, run the following commands to enable additional repositories required by the DGX software.
 sudo subscription-manager repos --enable=rhel-7-server-extras-rpms

```
sudo subscription-manager repos --enable=rhel-7-server-extras-rpms
sudo subscription-manager repos --enable=rhel-7-server-optional-rpms
```

- b). Run the following command to install the DGX software installation package and enable the NVIDIA DGX software repository.
 - ATTENTION: By running these commands you are confirming that you have read and agree to be bound by the <u>DGX Software License Agreement</u>. You are also confirming that you understand that any pre-release software and materials available that you elect to install in a DGX may not be fully functional, may contain errors or design flaws, and may have reduced or different security, privacy, availability, and reliability standards relative to commercial versions of NVIDIA software and materials, and that you use pre-release versions at your risk.

```
yum install -y \
https://international.download.nvidia.com/dgx/repos/rhel-files/dgx-repo-
setup-20.03-1.el7.x86_64.rpm
```

2. Install mpt3sas 31.101.01.00-0.

sudo yum install mpt3sas-dkms

3. Load the ${\tt mpt3sas}$ driver into the Red Hat Enterprise Linux kernel.

sudo modprobe mpt3sas

```
You can verify the correct mpt3sas version is installed by issuing the following. yum list installed
```

7.2. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container. It includes instructions for performing a transitional update for systems that require it. The commands use the .run file, but you can also use any method described in <u>Using the DGX A100 FW Update Utility</u>.

CAUTION:

Stop all unnecessary system activities before attempting to update firmware.

- Stop all GPU activity, including accessing nvidia-smi, as this can prevent the VBIOS from updating.
- Do not add additional loads on the system (such as user jobs, diagnostics, or monitoring services) while an update is in progress. A high workload can disrupt the firmware update process and result in an unusable component.
- When initiating an update, the update software assists in determining the activity state of the DGX system and provides a warning if it detects that activity levels are above a predetermined threshold. If the warning is encountered, you are strongly advised to take action to reduce the workload before proceeding with the update.
- 1. Check if updates are needed by checking the installed versions.
 - \$ sudo ./nvfw-dgxa100:21.05.7_210519.run show_version
 - If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
 - If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 2. Perform the update for all firmware supported by the container.

\$ sudo ./nvfw-dgxa100:21.05.7_210519.run update_fw all

Depending on the firmware that is updated, you may be prompted to either reboot the system or power cycle the system.

- If you are prompted to reboot, issue
 \$ sudo reboot
- If you are prompted to power cycle, you can issue the following two commands (there is no output with the first command).
 - \$ sudo ipmitool raw 0x3c 0x04
 - \$ sudo ipmitool chassis power cycle
- 3. After rebooting or power cycling the system, you may need to perform another update_fw all to update other firmware.
 - Either repeat Step 1 to check if updates are needed and then perform Step 2 if needed, or
 - ▶ Repeat Step 2 just in case updates are needed.

If you perform another update_fw all, you may be prompted again to either reboot the system or power cycle the system.

See <u>DGX A100 Firmware Update Process</u> for more information about the update process.

You can verify the update by issuing the following.

\$ sudo ./nvfw-dgxa100:21.05.7_210519.run show_version

Example output for a DGX A100 320GB system

CEC			
MB_CEC(enabled) Delta_CEC(enabled)	Onboard Version 3.28 3.09	Manifest 3.28 3.09	up-to-date yes yes
BMC DGX			

Image Id 0:Active Boot 1:Inactive Upda	Sta C Onl atable	itus I ine I I	Location Local Local	Onboa 00.14 00.14	rd Version .17 .17	Manifest 00.14.17 00.14.17	up_to_date yes yes
SBIOS							
Image Id 0:Inactive Upda 1:Active Boot	atable Updatable	2		Onboa 0.34 0.34	rd Version	Manifest 0.34 0.34	up_to_date yes yes
Switches							
PCI Bus#		Model	Onbo	ard Vers	ion Manifest	FUB Update	ed? up-to-
DGX - 0000:91:0 DGX - 0000:88:0 DGX - 0000:4f:0 DGX - 0000:48:0	00.0(U261) 00.0(U260) 00.0(U262) 00.0(U225)	88064_F 88064_F 88064_F 88080_F	Retimer Retimer Retimer Retimer	1.2.0 1.2.0 1.2.0 1.2.0	1.2.0 1.2.0 1.2.0 1.2.0	N/A N/A N/A N/A	yes yes yes yes
DGX - 0000:01:(DGX - 0000:b1:(DGX - 0000:41:(DGX - 0000:81:(00.0(U1) 00.0(U4) 00.0(U2) 00.0(U3)	PEX8809 PEX8809 PEX8809 PEX8809	96 96 96 96	2.0 2.0 2.0 2.0	2.0 2.0 2.0 2.0	N/A N/A N/A N/A	yes yes yes yes
DGX - 0000:c4:(DGX - 0000:c5:(DGX - 0000:c8:(DGX - 0000:c6:(DGX - 0000:c9:(DGX - 0000:c7:(00.0 00.0 00.0 00.0 00.0 00.0	LR10 LR10 LR10 LR10 LR10 LR10	92.10.1 92.10.1 92.10.1 92.10.1 92.10.1 92.10.1	8.00.01 8.00.01 8.00.01 8.00.01 8.00.01 8.00.01	92.10.18.00 92.10.18.00 92.10.18.00 92.10.18.00 92.10.18.00 92.10.18.00	.01 yes .01 yes .01 yes .01 yes .01 yes .01 yes	yes yes yes yes yes
Mass Storage							
Drive Name/Slot nvme0n1 nvme1n1 nvme2n1 nvme3n1 nvme4n1 nvme5n1	Samsung Samsung Samsung Samsung Samsung Samsung	Iodel Num MZWLJ3T8 MZ1LB1T9 MZ1LB1T9 MZWLJ3T8 MZWLJ3T8 MZWLJ3T8	nber 3HBLS-000 9HALS-000 9HALS-000 3HBLS-000 3HBLS-000 3HBLS-000	Onboa 07 EPK9 07 EDA7 07 EDA7 07 EPK9 07 EPK9 07 EPK9	rd Version 9B5Q 602Q 602Q 9B5Q 9B5Q 9B5Q	Manifest EPK99B5Q EDA7602Q EDA7602Q EPK99B5Q EPK99B5Q EPK99B5Q	up-to-date yes yes yes yes yes yes
Video BIOS ======							
Bus date 0000:07:00.0	Model	-40GB 9	Onboard V 92.00.36.	/ersion	Manifest	FUB Updat	ves
0000:0f:00.0 0000:47:00.0 0000:4e:00.0 0000:87:00.0 0000:90:00.0 0000:b7:00.0 0000:bd:00.0	A100-SXM4- A100-SXM4- A100-SXM4- A100-SXM4- A100-SXM4- A100-SXM4- A100-SXM4-	-40GB 9 -40GB 9 -40GB 9 -40GB 9 -40GB 9 -40GB 9 -40GB 9	92.00.36. 92.00.36. 92.00.36. 92.00.36. 92.00.36. 92.00.36. 92.00.36.	00.04 00.04 00.04 00.04 00.04 00.04 00.04 00.04	92.00.36.00.0 92.00.36.00.0 92.00.36.00.0 92.00.36.00.0 92.00.36.00.0 92.00.36.00.0 92.00.36.00.0	04 yes 04 yes	yes yes yes yes yes yes yes
FPGA							
Onboard version	n Manif 02.a5	fest up-	-to-date yes				
Power Supply							

			Onboard					
ID		Vendor Model	MFR ID	Status	Version	Manifest	up-to-	
date								
PSU 0	: Primary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU O	: Secondary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU O	: Community	Delta ECD16010092	Delta	ok	01.07	01.07	yes	
PSU 1	: Primary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU 1	: Secondary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU 1	: Community	Delta ECD16010092	Delta	ok	01.07	01.07	yes	
PSU 2	: Primary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU 2	: Secondary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU 2	: Community	Delta ECD16010092	Delta	ok	01.07	01.07	yes	
psu 3	: Primary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU 3	: Secondary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
psu 3	: Community	Delta ECD16010092	Delta	ok	01.07	01.07	yes	
PSU 4	: Primary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU 4	: Secondary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU 4	: Community	Delta ECD16010092	Delta	ok	01.07	01.07	yes	
PSU 5	: Primary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU 5	: Secondary	Delta ECD16010092	Delta	ok	01.06	01.06	yes	
PSU 5	: Community	Delta ECD16010092	Delta	ok	01.07	01.07	yes	
CPL	D							
			Onhoar	d Voraion	Manifor	+ 110	-to-dato	
MTD C	ם זם		1 03	u version	1 03	ւ սբ	voa	
MB CD	םם חם		1 03		1.03		yes	
MD_CP.			1.03		1.05		уез	
* CPL	D won't be up	odated by default (`u	pdate_fw	all`), us	e `update_	fw CPLD` i	f it's	
need	ea							

7.3. Known Issues

7.3.1. BMC UI May not be Accessible from Mac OS

Issue

When attempting to connect to the DGX A100 BMC from a system with Mac OS, a "Your connection is not private" message appears that prevents access to the BMC.

Explanation

Starting with version 0.13.6, the BMC provides a self-signed certificate which Mac OS flags in the browser. Most browsers will let you either accept the risk and continue, or add the certificate to the keychain and continue. The Chrome and Opera browsers, however, do not provide these options and so Mac OS users will not be able to access the BMC from the Chrome or Opera browser.

To access the DGX A100 BMC, Mac OS users can use Safari or Firefox, which provide an access path.

7.3.2. Boot Order in the SBIOS Reverts to the Default

Issue

After updating the SBIOS, any changes in the boot order that you have made are not preserved and the boot order specified in the SBIOS reverts to the following.

Boot Option #1 [Hard Disk] Boot Option #2 [NVME] Boot Option #3 [USB CD/DVD] Boot Option #4 [USB Hard Disk] Boot Option #5 [USB Key] Boot Option #6 [Network]

Explanation

You will need to prepare for the change when restarting the system, and then enter the SBIOS setup to edit the boot order as needed.

7.3.3. Unable to Launch BMC Dashboard under Pre-84.01 Firefox

lssue

After updating the BMC, attempts to access the BMC dashboard using Firefox versions earlier than 84.01 fail with a "Secure Connection Fail" message.

Explanation

To work around, update Firefox to version 84.01 or later.

7.3.4. The system starts the POST process several times during boot after updating the SBIOS.

lssue

After updating the SBIOS and rebooting the system, the NVIDIA splash screen appears and disappears several times before boot is completed.

Explanation

After updating the SBIOS, several component states are cleared and the system may reboot automatically 3-4 times to reset all the components. This is expected behavior.

Chapter 8. DGX A100 System Firmware Update Container Version 21.03.6

The DGX Firmware Update container version 21.03.6 is available.

- Package name:nvfw-dgxa100_21.03.6_210321.tar.gz
- Run file name: nvfw-dgxa100_21.03.6_210321.run
- Image name: nvfw-dgxa100:21.03.6
- ISO image: DGXA100_FWUI-21.03.6-2021-03-23-22-03-47.iso
- PXE netboot: pxeboot-dgxa100-21.03.6.tgz

Highlights and Changes in this Release

- This release is supported with the following DGX OS software -
 - DGX OS 4.99.11
 - ► DGX OS 5.0 or later
 - EL7-21.01 or later (See <u>Special Instructions for Red Hat Enterprise Linux</u>)
 - EL8-20.11 or later
- Added ISO and netboot package for efficiently updating multiple systems.
- Added code to prevent use of hardware that is being updated, such as NVIDIA GPUs.

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table. The update time for each component is provided for reference. Total update time if all components are updated is approximately 2 hours and 20 minutes.

Component	Version	Key Changes	Update Time
BMC (via CEC)	00.14.16	See DGX A100 BMC Changes	25 minutes
SBIOS	0.34	See DGX A100 SBIOS Changes	7 minutes

Component	Version	Key Changes	Update Time
Broadcom 88096 PCIe switch board	0.2.0	See <u>DGX A100 Broadcom 88096 PCIe</u> <u>Switchboard Changes</u>	8 minutes
BMC CEC SPI	v3.28	See DGX A100 BMC CEC Changes	8 minutes
PEX88064 Retimer	1.2f	See <u>DGX A100 Broadcom 880xx Retimer</u> <u>Changes</u>	7 minutes
PEX88080 Retimer	1.2f	See <u>DGX A100 Broadcom 880xx Retimer</u> <u>Changes</u>	7 minutes
NvSwitch BIOS	92.10.18.00.01	See DGX A100 BMC Changes	8 minutes
VBIOS (A100 40GB)	92.00.36.00.04	See <u>A100 VBIOS Changes</u>	7 minutes
VBIOS (A100 80GB)	92.00.36.00.01 No change		
U.2 NVMe (Samsung)	EPK99B5Q	No change	6 minutes
U.2 NVMe (Kioxia)	0105	Added to the container	
M.2 NVMe (Samsung)	EDA7602Q	Added to the container	3 minutes
FPGA (GPU sled)	2.A5	See DGX A100 FPGA Release Notes	40 minutes
CEC1712 SPI (GPU sled)	3.9	See DGX A100 BMC CEC SPI Changes	7 minutes

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

- SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. When using update_fw all, the update container updates both active and inactive images.
- BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image, and will update it only if the *active* image needs to be updated. After the update is completed, the updated inactive image becomes the active image. Because the active image is now updated, subsequent update_fw all commands will not update the inactive image. To update the inactive image in this case, use update_fw BMC --inactive.

Updating the CEC 1712 (Delta-CEC)

The firmware update container may fail to update the Delta_CEC. To work around, perform the following.

- 1. sudo ./nvfw-dgxa100_21.03.6_210321.run update_fw CEC -s Delta_CEC -m
- 2 sudo ipmitool chassis power cycle
3. sudo ./nvfw-dgxa100_21.03.6_210321.run update_fw all

DO NOT UPDATE DGX A100 CPLD FIRMWARE UNLESS INSTRUCTED

When updating DGX A100 firmware using the Firmware Update Container, do not update the CPLD firmware unless the DGX A100 system is being upgraded from 320GB to 640GB.

The current DGX A100 Firmware Update Container will not automatically update the CPLD firmware (for example, when running update_fw all). It is possible to update the CPLD firmware using "update_fw CPLD"; however, it is strongly recommended that the CPLD firmware not be updated manually unless specifically instructed by <u>NVIDIA Enterprise Support</u> (or email <u>enterprisesupport@nvidia.com</u>). If the DGX A100 is upgraded from 320GB to 640GB, the CPLD firmware update should be performed as instructed.

8.1. Special Instructions for Red Hat Enterprise Linux

This section describes the actions that must be taken before updating firmware on DGX A100 systems installed with Red Hat Enterprise Linux. There are two options for meeting these requirements.

Option 1: Update to EL7-21.01 or later

Refer to the <u>DGX Software for Red Hat Enterprise Linux 7 Release Notes</u> for more information.

Important: Updating the DGX software for Red Hat Enterprise Linux will update the Red Hat Enterprise Linux installation to 7.9 or later. If you do not want to update your Red Hat Enterprise Linux 7 installation, then choose Option 2.

Option 2: Install mpt3sas 31.101.01.00-0

These instructions apply if

- > You do not want to update your Red Hat Enterprise Linux installation, and
- > Your system is currently installed with Red Hat Enterprise Linux 7.7 or later.

If your system is installed with Red Hat Enterprise Linux 7.6 or earlier, contact NVIDIA Enterprise Support for assistance.

- 1. Perform this step if your system is no longer pointing to the NVIDIA DGX software repository.
 - a). On Red Hat Enterprise Linux, run the following commands to enable additional repositories required by the DGX software.

```
sudo subscription-manager repos --enable=rhel-7-server-extras-rpms
sudo subscription-manager repos --enable=rhel-7-server-optional-rpms
```

b). Run the following command to install the DGX software installation package and enable the NVIDIA DGX software repository.

ATTENTION: By running these commands you are confirming that you have read and agree to be bound by the <u>DGX Software License Agreement</u>. You are also confirming that you understand that any pre-release software and materials available that you elect to install in a DGX may not be fully functional, may contain errors or design flaws, and may have reduced or different security, privacy, availability, and reliability standards relative to commercial versions of NVIDIA software and materials, and that you use pre-release versions at your risk.

```
yum install -y \
https://international.download.nvidia.com/dgx/repos/rhel-files/dgx-repo-
setup-20.03-1.el7.x86_64.rpm
```

- 2. Install mpt3sas 31.101.01.00-0.
 - sudo yum install mpt3sas-dkms
- Load the mpt3sas driver into the Red Hat Enterprise Linux kernel. sudo modprobe mpt3sas

You can verify the correct mpt3sas version is installed by issuing the following. yum list installed

8.2. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container. It includes instructions for performing a transitional update for systems that require it. The commands use the .run file, but you can also use any method described in <u>Using the DGX A100 FW Update Utility</u>.

CAUTION:

- Stop all unnecessary system activities before attempting to update firmware.
- Stop all GPU activity, including accessing nvidia-smi, as this can prevent the VBIOS from updating.
- Do not add additional loads on the system (such as user jobs, diagnostics, or monitoring services) while an update is in progress. A high workload can disrupt the firmware update process and result in an unusable component.
- When initiating an update, the update software assists in determining the activity state of the DGX system and provides a warning if it detects that activity levels are above a predetermined threshold. If the warning is encountered, you are strongly advised to take action to reduce the workload before proceeding with the update.
- 1. Check if updates are needed by checking the installed versions.
 - \$ sudo ./nvfw-dgxa100:21.03.6_210321.run show_version
 - If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.

- If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 2. Perform the update for all firmware supported by the container.

\$ sudo ./nvfw-dgxa100:21.03.6_210321.run update_fw all

Depending on the firmware that is updated, you may be prompted to either reboot the system or power cycle the system.

- If you are prompted to reboot, issue
 \$ sudo reboot
- If you are prompted to power cycle, you can issue the following two commands (there
 is no output with the first command).
 - \$ sudo ipmitool raw 0x3c 0x04

\$ sudo ipmitool chassis power cycle

- 3. After rebooting or power cycling the system, you may need to perform another update_fw all to update other firmware.
 - Either repeat Step 1 to check if updates are needed and then perform Step 2 if needed, or
 - Repeat Step 2 just in case updates are needed.

If you perform another $update_fw$ all, you may be prompted again to either reboot the system or power cycle the system.

See <u>DGX A100 Firmware Update Process</u> for more information about the update process.

You can verify the update by issuing the following.

\$ sudo ./nvfw-dgxa100:21.03.6_210321.run show_version

Example output for a DGX A100 320GB system

CEC						
MB_CEC(enabled) Delta_CEC(enabled)			Onboard 3.28 3.09	Version	Manifest 3.28 3.09	up-to-date yes yes
BMC DGX						
Image Id 0:Active Boot 1:Inactive Updatable	Status Online	Location Local Local	Onboard 00.14.1 00.14.1	Version 6 6	Manifest 00.14.16 00.14.16	up_to_date yes yes
SBIOS ======						
Image Id 0:Inactive Updatable 1:Active Boot Updata	able		Onboard 0.34 0.34	Version	Manifest 0.34 0.34	up_to_date yes yes
Switches						
PCI Bus# date	Model	Onb	oard Versio	n Manifes	t FUB Updat	ted? up-to-
DGX - 0000:91:00.0 (U2) DGX - 0000:88:00.0 (U2) DGX - 0000:4f:00.0 (U2) DGX - 0000:4f:00.0 (U2)	61) 88064 60) 88064 62) 88064 25) 88080	_Retimer _Retimer _Retimer _Retimer	1.2f 1.2f 1.2f 1.2f	1.2f 1.2f 1.2f 1.2f	N/A N/A N/A N/A	yes yes yes
DGX - 0000:01:00.0(U1)	PEX88	096	2.0	2.0	N/A	yes

DGX - 0000:b1: DGX - 0000:41:	00.0(U4) 00.0(U2)	PEX88096 PEX88096	2.0 2.0	2.0 2.0	N/A N/A	yes yes
DGX - 0000:81:	00.0(U3)	PEX88096	2.0	2.0	N/A	yes
DGX - 0000:c4:	00.0	LR10 92	.10.18.00.01	92.10.18.0	0.01 yes	yes
DGX - 0000:c8:	00.0	LR10 92	.10.18.00.01	92.10.18.0	0.01 yes	yes
DGX - 0000:c6:	00.0	LR10 92	.10.18.00.01	92.10.18.0	0.01 yes	yes
DGX - 0000:c9: DGX - 0000:c7:	00.0	LR10 92 LR10 92	.10.18.00.01	92.10.18.0	0.01 yes 0.01 yes	yes yes
Mass Storage						
Drive Name/Slo	t Mc Samsung M	del Number IZWII3T8HBI.	0nboa 5-00007 EPK	ard Version 99850	Manifest EPK99B50	up-to-date ves
nvme1n1	Samsung M	IZ1LB1T9HAL	5-00007 EDA	7202Q	EDA7202Q	yes
nvme2n1	Samsung M	IZ1LB1T9HAL	S-00007 EDA	7202Q	EDA7202Q	yes
nvme3n1 nvme4n1	Samsung M Samsung M	IZWLJ3T8HBL IZWLJ3T8HBL	S-00007 EPKS S-00007 EPKS	99B5Q 99B50	EPK99B5Q EPK99B50	yes ves
nvme5n1	Samsung M	IZWLJ3T8HBL	5-00007 EPK	99B5Q	EPK99B5Q	yes
Video BIOS						
======================================	Model	Onho	ard Version	Manifest	FIIB Undat	ed? un-to-
date	MODEL	011003	alu version	Manifiest	rob opdat	eu: up co
0000:07:00.0	A100-SXM4-4	0GB 92.0	0.36.00.04	92.00.36.00	.04 yes	yes
0000:0f:00.0	A100-SXM4-4	0GB 92.0	0.36.00.04	92.00.36.00	.04 yes	yes
0000:47.00.0 0000:4e:00.0	A100-SXM4-4	0GB 92.0	0.36.00.04	92.00.36.00	.04 yes .04 yes	yes
0000:87:00.0	A100-SXM4-4	0GB 92.0	0.36.00.04	92.00.36.00	.04 yes	yes
0000:90:00.0	A100-SXM4-4	0GB 92.0	0.36.00.04	92.00.36.00	.04 yes	yes
0000:bd:00.0	A100-SXM4-4 A100-SXM4-4	0GB 92.0	0.36.00.04	92.00.36.00	.04 yes .04 yes	yes yes
FPGA						
	n Manife	st un-to-	late			
02.A5	02.A5	yes				
CPLD						
			Ophoard	Version M	anifest	un-to-dato
MID CPLD			1.05	1 version M	.05	yes
MB_CPLD			1.05	1	.05	yes
* CPLD won't b needed	e updated by	default (`update_fw al	ll`), use `u	pdate_fw CPL	D` if it's

8.3. Known Issues

8.3.1. BMC UI May not be Accessible from Mac OS

Issue

When attempting to connect to the DGX A100 BMC from a system with Mac OS, a "Your connection is not private" message appears that prevents access to the BMC.

Explanation

Starting with version 0.13.6, the BMC provides a self-signed certificate which Mac OS flags in the browser. Most browsers will let you either accept the risk and continue, or add the certificate to the keychain and continue. The Chrome and Opera browsers, however, do not provide these options and so Mac OS users will not be able to access the BMC from the Chrome or Opera browser.

To access the DGX A100 BMC, Mac OS users can use Safari or Firefox, which provide an access path.

8.3.2. Boot Order in the SBIOS Reverts to the Default

Issue

After updating the SBIOS, any changes in the boot order that you have made are not preserved and the boot order specified in the SBIOS reverts to the following.

Boot Option #1 [Hard Disk] Boot Option #2 [NVME] Boot Option #3 [USB CD/DVD] Boot Option #4 [USB Hard Disk] Boot Option #5 [USB Key] Boot Option #6 [Network]

Explanation

You will need to prepare for the change when restarting the system, and then enter the SBIOS setup to edit the boot order as needed.

8.3.3. Unable to Launch BMC Dashboard under Pre-84.01 Firefox

lssue

After updating the BMC, attempts to access the BMC dashboard using Firefox versions earlier than 84.01 fail with a "Secure Connection Fail" message.

Explanation

To work around, update Firefox to version 84.01 or later.

8.3.4. The system starts the POST process several times during boot after updating the SBIOS.

Issue

After updating the SBIOS and rebooting the system, the NVIDIA splash screen appears and disappears several times before boot is completed.

Explanation

After updating the SBIOS, several component states are cleared and the system may reboot automatically 3-4 times to reset all the components. This is expected behavior.

Chapter 9. DGX A100 System Firmware Update Container Version 20.12.3.3

The DGX Firmware Update container version 20.12.3.3 is available.

- Package name:nvfw-dgxa100_20.12.3.3_210205.tar.gz
- Run file name: nvfw-dgxa100_20.12.3.3_210205.run
- Image name: nvfw-dgxa100:20.12.3.3

Highlights and Changes in this Release

- This release is supported with the following DGX OS software -
 - DGX OS 4.99.11
 - DGX OS 5.0 or later
 - EL7-21.01 or later (See <u>Special Instructions for Red Hat Enterprise Linux</u>)
 - EL8-20.11 or later
- Fixed the mishandling of correctable PCIe errors.

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table. The update time for each component is provided for reference. Total update time if all components are updated is approximately 2 hours and 20 minutes.

Component	Version	Key Changes	Update Time
BMC (via CEC)	00.13.16	No change	25 minutes
SBIOS	0.33	See DGX A100 SBIOS Changes	7 minutes
Broadcom 88096 PCIe switch board	0.1.8	No change	8 minutes
BMC CEC SPI	v3.25	No change	8 minutes

Component	Version	Key Changes	Update Time
PEX88064 Retimer	0.F.0	No change	7 minutes
PEX88080 Retimer	0.F.0	No change	7 minutes
NvSwitch BIOS	92.10.14.00.01	No change	8 minutes
VBIOS (A100 40GB)	92.00.19.00.10	No change	7 minutes
VBIOS (A100 80GB)	92.00.36.00.01	No change	
U.2 NVMe (Samsung)	EPK99B5Q	No change	6 minutes
FPGA (GPU sled)	2.9c	No change	40 minutes
CEC1712 SPI (GPU sled)	3.5	No change	7 minutes

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

- SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. When using update_fw all, the update container updates both active and inactive images.
- BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image, and will update it only if the *active* image needs to be updated. After the update is completed, the updated inactive image becomes the active image. Because the active image is now updated, subsequent update_fw all commands will not update the inactive image. To update the inactive image in this case, use update_fw BMC --inactive --force.

9.1. Special Instructions for Red Hat Enterprise Linux

This section describes the actions that must be taken before updating firmware on DGX A100 systems installed with Red Hat Enterprise Linux. There are two options for meeting these requirements.

Option 1: Update to EL7-21.01 or later

Refer to the <u>DGX Software for Red Hat Enterprise Linux 7 Release Notes</u> for more information.

Important: Updating the DGX software for Red Hat Enterprise Linux will update the Red Hat Enterprise Linux installation to 7.9 or later. If you do not want to update your Red Hat Enterprise Linux 7 installation, then choose Option 2.

Option 2: Install mpt3sas 31.101.01.00-0

These instructions apply if

- > You do not want to update your Red Hat Enterprise Linux installation, and
- > Your system is currently installed with Red Hat Enterprise Linux 7.7 or later.

If your system is installed with Red Hat Enterprise Linux 7.6 or earlier, contact NVIDIA Enterprise Support for assistance.

- 1. Perform this step if your system is no longer pointing to the NVIDIA DGX software repository.
 - a). On Red Hat Enterprise Linux, run the following commands to enable additional repositories required by the DGX software.
 sudo subscription-manager repos --enable=rhel-7-server-extras-rpms sudo subscription-manager repos --enable=rhel-7-server-optional-rpms
 - b). Run the following command to install the DGX software installation package and enable the NVIDIA DGX software repository.
 - **ATTENTION:** By running these commands you are confirming that you have read and agree to be bound by the <u>DGX Software License Agreement</u>. You are also confirming that you understand that any pre-release software and materials available that you elect to install in a DGX may not be fully functional, may contain errors or design flaws, and may have reduced or different security, privacy, availability, and reliability standards relative to commercial versions of NVIDIA software and materials, and that you use pre-release versions at your risk.

```
yum install -y \
https://international.download.nvidia.com/dgx/repos/rhel-files/dgx-repo-
setup-20.03-1.el7.x86 64.rpm
```

- Install mpt3sas 31.101.01.00-0. sudo yum install mpt3sas-dkms
- 3. Load the mpt3sas driver into the Red Hat Enterprise Linux kernel.
 - sudo modprobe mpt3sas

You can verify the correct mpt3sas version is installed by issuing the following. yum list installed

9.2. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container. It includes instructions for performing a transitional update for systems that require it. The commands use the .run file, but you can also use any method described in <u>Using the DGX A100 FW Update Utility</u>.

CAUTION:

- Stop all unnecessary system activities before attempting to update firmware.
- Stop all GPU activity, including accessing nvidia-smi, as this can prevent the VBIOS from updating.
- Do not add additional loads on the system (such as user jobs, diagnostics, or monitoring services) while an update is in progress. A high workload can disrupt the firmware update process and result in an unusable component.
- When initiating an update, the update software assists in determining the activity state of the DGX system and provides a warning if it detects that activity levels are above a predetermined threshold. If the warning is encountered, you are strongly advised to take action to reduce the workload before proceeding with the update.
- 1. Check if updates are needed by checking the installed versions.
 - \$ sudo ./nvfw-dgxa100_20.12.3.3_210205.run show_version
 - If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
 - If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 2. Perform the update for all firmware supported by the container.

\$ sudo ./nvfw-dgxa100_20.12.3.3_210205.run update_fw all

Depending on the firmware that is updated, you may be prompted to either reboot the system or power cycle the system.

- If you are prompted to reboot, issue
 \$ sudo reboot
- If you are prompted to power cycle, you can issue the following two commands (there is no output with the first command).
 - \$ sudo ipmitool raw 0x3c 0x04
 - \$ sudo ipmitool chassis power cycle
- 3. After rebooting or power cycling the system, you may need to perform another update_fw all to update other firmware.
 - Either repeat Step 1 to check if updates are needed and then perform Step 2 if needed, or
 - Repeat Step 2 just in case updates are needed.

If you perform another update_fw all, you may be prompted again to either reboot the system or power cycle the system.

See <u>DGX A100 Firmware Update Process</u> for more information about the update process.

You can verify the update by issuing the following.

\$ sudo ./nvfw-dgxa100_20.12.3.3_210205.run show_version

Example output for a DGX A100 320GB system

CEC						
			Onboar	d Version	Manifest	up-to-
date MB_CEC(enabled)			3.25		3.25	
yes Delta_CEC(enabled) yes			3.05		3.05	
BMC DGX =======						
Image Id	Status	Locatio	n	Onboard Ver	sion Man	ifest
0:Active Boot ves	Online	Local		00.13.16	00.	13.16
1:Inactive Updatabl yes	Le	Local		00.13.16	00.	13.16
SBIOS ======						
Image Id 0:Inactive Updatabl 1:Active Boot Upo	le datable	Onboard V 0.33 0.33	ersion	Manifest 0.33 0.33	up_	to_date yes yes
Switches						
PCI Bus#		Model	Onboar	d Version	Manifest	FUB
Updated? up-to-da DGX - 0000:91:00.0 N/A ves	ate (U261)	88064_Retimer	0.F.O		0.F.O	
DGX - 0000:88:00.0	(U260)	88064_Retimer	0.F.O		0.F.O	
N/A yes DGX - 0000:4f:00.0 N/A ves	(U262)	88064_Retimer	0.F.O		0.F.O	
DGX - 0000:48:00.0 N/A yes	(U225)	88080_Retimer	0.F.O		0.F.O	
DGX - 0000:01:00.0	(U1)	PEX88096	1.8		1.8	
DGX - 0000:b1:00.0	(U4)	PEX88096	1.8		1.8	
N/A yes DGX - 0000:41:00.0 N/A yes	(U2)	PEX88096	1.8		1.8	
DGX - 0000:81:00.0 N/A yes	(U3)	PEX88096	1.8		1.8	
DGX - 0000:c4:00.0		LR10	92.10.	14.00.01	92.10.14.	00.01
yes yes DGX - 0000:c5:00.0		LR10	92.10.	14.00.01	92.10.14.	00.01
DGX - 0000:c8:00.0		LR10	92.10.	14.00.01	92.10.14.	00.01
DGX - 0000:c6:00.0 ves ves		LR10	92.10.	14.00.01	92.10.14.	00.01
DGX - 0000:c9:00.0		LR10	92.10.	14.00.01	92.10.14.	00.01
DGX - 0000:c7:00.0 yes yes		LR10	92.10.	14.00.01	92.10.14.	00.01

Mass Storage		Terral and the	Quality		March		
to-date	e Model I	umber	Unbo	ard version	Maniiest	1	up-qu
nvmeOn1	Samsung MZWLJ3	3T8HBLS-00007	EPKS	9B5Q	EPK99B5Q		
nvmeln1 ves	Samsung MZ1LB	T9HALS-00007	EDA7	202Q	EDA7202Q		
nvme2n1 ves	Samsung MZ1LB2	LT9HALS-00007	EDA7	202Q	EDA7202Q		
nvme3n1	Samsung MZWLJ3	3T8HBLS-00007	EPKS	9B5Q	EPK99B5Q		
nvme4n1 ves	Samsung MZWLJ3	3T8HBLS-00007	EPKS	9B5Q	EPK99B5Q		
nvme5n1 yes	Samsung MZWLJ3	3T8HBLS-00007	EPKS	9B5Q	EPK99B5Q		
Video BIOS							
Bus	Model	Onboard Vers	ion	Manifest	FUB U	Jpdated?	up-
to-date 0000:07:00.0	A100-SXM4-40GB	92.00.19.00.	10	92.00.19.00.	.10	yes	
0000:0f:00.0	A100-SXM4-40GB	92.00.19.00.	10	92.00.19.00.	.10	yes	
yes 0000:47:00.0	A100-SXM4-40GB	92.00.19.00.	10	92.00.19.00.	.10	yes	
0000:4e:00.0	A100-SXM4-40GB	92.00.19.00.	10	92.00.19.00.	.10	yes	
0000:87:00.0	A100-SXM4-40GB	92.00.19.00.	10	92.00.19.00.	.10	yes	
0000:90:00.0	A100-SXM4-40GB	92.00.19.00.	10	92.00.19.00.	.10	yes	
0000:b7:00.0	A100-SXM4-40GB	92.00.19.00.	10	92.00.19.00.	.10	yes	
0000:bd:00.0 yes	A100-SXM4-40GB	92.00.19.00.	10	92.00.19.00.	.10	yes	
FPGA =======							
Onboard version 02.9c	n Manifest u 02.9c	up-to-date yes					
CPLD							
			Onbc	ard Version	Manifest	սյ	p-to-
date MID_CPLD			1.03	5	1.03		
yes MB_CPLD yes			1.03	;	1.03		
MB_CPLD yes * CPLD won't be	e updated by defa	ault (`update	1.03 fw al	l`), use `upo	1.03 date fw CPI	LD` if i	t's

needed

9.3. Known Issues

9.3.1. BMC UI May not be Accessible from Mac OS

Issue

When attempting to connect to the DGX A100 BMC from a system with Mac OS, a "Your connection is not private" message appears that prevents access to the BMC.

Explanation

Starting with version 0.13.6, the BMC provides a self-signed certificate which Mac OS flags in the browser. Most browsers will let you either accept the risk and continue, or add the certificate to the keychain and continue. The Chrome and Opera browsers, however, do not provide these options and so Mac OS users will not be able to access the BMC from the Chrome or Opera browser.

To access the DGX A100 BMC, Mac OS users can use Safari or Firefox, which provide an access path.

9.3.2. Update Timeout Reported for Motherboard CEC

lssue

The update progress output reports "Update_timeout" for the motherboard CEC (MB_CEC) when using the .run file without Docker installed.

Example

+ 	!!!!! Firmware Update In Status: reflash BMC	Progress !!!! firmware	+
	Onboard	Manifest	Update Status
MB_CEC	3.05	3.25	Update timeout

Explanation

This message can be ignored provided that the MB_CEC update is successful.

Example success message:

Success: Installed firmware 3.25 on MB_CEC

9.3.3. Boot Order in the SBIOS Reverts to the Default

Issue

After updating the SBIOS, any changes in the boot order that you have made are not preserved and the boot order specified in the SBIOS reverts to the following.

Boot Option #1 [Hard Disk] Boot Option #2 [NVME] Boot Option #3 [USB CD/DVD] Boot Option #4 [USB Hard Disk] Boot Option #5 [USB Key] Boot Option #6 [Network]

Explanation

You will need to prepare for the change when restarting the system, and then enter the SBIOS setup to edit the boot order as needed.

Chapter 10. DGX A100 System Firmware Update Container Version 20.12.3

The DGX Firmware Update container version 20.12.3 is available.

- Package name:nvfw-dgxa100_20.12.3_201209.tar.gz
- Run file name: nvfw-dgxa100_20.12.3_201209.run
- Image name: nvfw-dgxa100:20.12.3

Highlights and Changes in this Release

- This release is supported with the following DGX OS software -
 - ▶ DGX OS 4.99.11
 - ▶ DGX OS 5.0 or later
- Fixed an issue where running the container generated an overly large log file.

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table. The update time for each component is provided for reference. Total update time if all components are updated is approximately 2 hours and 20 minutes.

Component	Version	Key Changes	Update Time
BMC (via CEC)	00.13.16	No change	25 minutes
SBIOS	0.30	No change	7 minutes
Broadcom 88096 PCIe switch board	0.1.8	No change	8 minutes
BMC CEC SPI	v3.25	No change	8 minutes
PEX88064 Retimer	0.F.0	No change	7 minutes
PEX88080 Retimer	0.F.0	No change	7 minutes

Component	Version	Key Changes	Update Time
NvSwitch BIOS	92.10.14.00.01	No change	8 minutes
VBIOS (A100 40GB)	92.00.19.00.10	No change	7 minutes
VBIOS (A100 80GB)	92.00.36.00.01	No change	
U.2 NVMe (Samsung)	EPK99B5Q	No change	6 minutes
FPGA (GPU sled)	2.9c	No change	40 minutes
CEC1712 SPI (GPU sled)	3.5	No change	7 minutes

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

- SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. When using update_fw all, the update container updates both active and inactive images.
- BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image, and will update it only if the *active* image needs to be updated. After the update is completed, the updated inactive image becomes the active image. Because the active image is now updated, subsequent update_fw all commands will not update the inactive image. To update the inactive image in this case, use update_fw BMC --inactive --force.

10.1. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container. It includes instructions for performing a transitional update for systems that require it. The commands use the .run file, but you can also use any method described in <u>Using the DGX A100 FW Update Utility</u>.

CAUTION:

- Stop all unnecessary system activities before attempting to update firmware.
- Stop all GPU activity, including accessing nvidia-smi, as this can prevent the VBIOS from updating.
- Do not add additional loads on the system (such as user jobs, diagnostics, or monitoring services) while an update is in progress. A high workload can disrupt the firmware update process and result in an unusable component.

- When initiating an update, the update software assists in determining the activity state of the DGX system and provides a warning if it detects that activity levels are above a predetermined threshold. If the warning is encountered, you are strongly advised to take action to reduce the workload before proceeding with the update.
- 1. Check if updates are needed by checking the installed versions.
 - \$ sudo nvfw-dgxa100_20.12.3_201209.run show_version
 - If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
 - If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 2. Perform the update for all firmware supported by the container.

\$ sudo nvfw-dgxa100_20.12.3_201209.run update_fw all

Depending on the firmware that is updated, you may be prompted to either reboot the system or power cycle the system.

- If you are prompted to reboot, issue
 - \$ sudo reboot
- If you are prompted to power cycle, you can issue the following two commands (there is no output with the first command).
 - \$ sudo ipmitool raw 0x3c 0x04
 - \$ sudo ipmitool chassis power cycle
- 3. After rebooting or power cycling the system, you may need to perform another update_fw all to update other firmware.
 - Either repeat Step 1 to check if updates are needed and then perform Step 2 if needed, or
 - ▶ Repeat Step 2 just in case updates are needed.

If you perform another update_fw all, you may be prompted again to either reboot the system or power cycle the system.

See <u>DGX A100 Firmware Update Process</u> for more information about the update process.

You can verify the update by issuing the following.

\$ sudo nvfw-dgxa100_20.12.3_201209.run show_version

Example output for a DGX A100 320GB system

BMC DGX					
Image Id 0:Active Boot 1:Inactive Updata	Status Online able	Location Local Local	Onboard Version 00.13.16 00.13.16	Manifest 00.13.16 00.13.16	up_to_date yes yes
CEC					
MB_CEC(enabled)			Onboard Version 3.25	Manifest 3.25	up-to-date yes
SBIOS ======					
Image Id	M	lethod	Onboard Version	Manifest	up_to_date

0:Inactive 1:Active	e Upda Boot	tabl	afulnx	0.30 0.30	0.30 0.30	yes yes
Video BIO)S					
Bus 0000:07:00 0000:47:00 0000:42:00 0000:87:00 0000:90:00 0000:b7:00 0000:bd:00 Switches).0).0).0).0).0).0).0).0).0	Model A100-SXM4-4 A100-SXM4-4 A100-SXM4-4 A100-SXM4-4 A100-SXM4-4 A100-SXM4-4 A100-SXM4-4	0 GB 0 GB 0 GB 0 GB 0 GB 0 GB 0 GB	Onboard Version 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10	Manifest up-to 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10	o-date yes yes yes yes yes yes yes
PCI Bus# DGX - 0000 DGX - 0000 DGX - 0000	===):91:0):88:0):4f:0	00.0(U261) 00.0(U260) 00.0(U262)	Model 88064_Retim 88064_Retim 88064_Retim	Onboard Version mer 0.F.0 mer 0.F.0 mer 0.F.0	Manifest up- 0.F.0 0.F.0 0.F.0	to-date yes yes yes
DGX - 0000 DGX - 0000 DGX - 0000 DGX - 0000 DGX - 0000 DGX - 0000 DGX - 0000):48:0):c4:0):c5:0):c2:0):c6:0):c3:0):c7:0	00.0(U225) 00.0 00.0 00.0 00.0 00.0 00.0 00.0	88080_Retim LR10 LR10 LR10 LR10 LR10 LR10	<pre>her 0.F.0 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01</pre>	0.F.0 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01	yes yes yes yes yes yes yes
DGX - 0000 DGX - 0000 DGX - 0000 DGX - 0000):01:0):81:0):41:0):b1:0	00.0(U1) 00.0(U3) 00.0(U2) 00.0(U4)	PEX88096 PEX88096 PEX88096 PEX88096	1.8 1.8 1.8 1.8	1.8 1.8 1.8 1.8	yes yes yes yes

10.2. Known Issues

10.2.1. BMC UI May not be Accessible from Mac OS

Issue

When attempting to connect to the DGX A100 BMC from a system with Mac OS, a "Your connection is not private" message appears that prevents access to the BMC.

Explanation

Starting with version 0.13.6, the BMC provides a self-signed certificate which Mac OS flags in the browser. Most browsers will let you either accept the risk and continue, or add the certificate to the keychain and continue. The Chrome and Opera browsers, however, do not provide these options and so Mac OS users will not be able to access the BMC from the Chrome or Opera browser.

To access the DGX A100 BMC, Mac OS users can use Safari or Firefox, which provide an access path.

10.2.2. Update Timeout Reported for Motherboard CEC

Issue

The update progress output reports "Update_timeout" for the motherboard CEC (MB_CEC) when using the .run file without Docker installed.

Example

```
+-----+

|+-----+|

|| !!!! Firmware Update In Progress !!!!! ||

|| Status: reflash BMC firmware ||

+----+|

| Update Status |

MB_CEC 3.05 3.25 Update timeout |
```

Explanation

This message can be ignored provided that the MB_CEC update is successful.

Example success message:

```
Success:
Installed firmware 3.25 on MB CEC
```

10.2.3. Boot Order in the SBIOS Reverts to the Default

Issue

After updating the SBIOS, any changes in the boot order that you have made are not preserved and the boot order specified in the SBIOS reverts to the following.

Boot Option #1 [Hard Disk] Boot Option #2 [NVME] Boot Option #3 [USB CD/DVD] Boot Option #4 [USB Hard Disk] Boot Option #5 [USB Key] Boot Option #6 [Network]

Explanation

You will need to prepare for the change when restarting the system, and then enter the SBIOS setup to edit the boot order as needed.

Chapter 11. DGX A100 System Firmware Update Container Version 20.11.3

The DGX Firmware Update container version 20.11.3 is available.

- Package name:nvfw-dgxa100_20.11.3_201124.tar.gz
- Run file name: nvfw-dgxa100_20.11.3_201124.run
- Image name: nvfw-dgxa100:20.11.3

Highlights and Changes in this Release

- This release is supported with the following DGX OS software -
 - ▶ DGX OS 4.99.11
 - ▶ DGX OS 5.0 or later
- Includes firmware updates to resolve PCIe advanced error reporting (AER) issues.
- ▶ The BMC update includes software security enhancements.

See the <u>NVIDIA Security Bulletin 5010</u> for details.

- Changed the policy for updating the active/inactive BMC images. See Updating Components with Secondary Images.
- Removed the need to manually stop certain services before updating on DGX OS 5.0.
- See <u>DGX A100 System Firmware Changes</u> for the list of changes in individual components.

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table. The update time for each component is provided for reference. Total update time if all components are updated is approximately 2 hours and 20 minutes.

Component	Version	Key Changes	Update Time
BMC (via CEC)	00.13.16	The BMC update includes software security enhancements.	25 minutes
		See the <u>NVIDIA Security Bulletin 5010</u> for details.	
SBIOS	0.30	See <u>SBIOS Release Notes</u>	7 minutes
Broadcom 88096 PCIe switch board	0.1.8	Updated preset values to address PCIe advanced error reporting (AER) issues.	8 minutes
BMC CEC SPI	v3.25	Improved BMC update time and reliability.	8 minutes
PEX88064 Retimer	0.F.0	Improved error handling of downstream switches.	7 minutes
PEX88080 Retimer	0.F.0	Improved error handling of downstream switches.	7 minutes
NvSwitch BIOS	92.10.14.00.01	Added support for a new out-of-band SMBPBI query to retrieve FUB revocation status.	8 minutes
VBIOS (A100 40GB)	92.00.19.00.10	Improved VBIOS compatibility.	7 minutes
VBIOS (A100 80GB)	92.00.36.00.01	New addition to the container.	
U.2 NVMe (Samsung)	EPK99B5Q	Enabled Relaxed Ordering.	6 minutes
FPGA (GPU sled)	2.9c	Added to the container. Implements miscellaneous bug fixes.	40 minutes
CEC1712 SPI (GPU sled)	3.5	Added to the container. Improved update time and reliability.	7 minutes

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

- SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. When using update_fw all, the update container updates both active and inactive images.
- BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image, and will update it only if the *active* image needs to be updated. After the update is completed, the updated inactive image becomes the active image. Because the active image is now updated, subsequent update_fw all commands will not update the inactive image. To update the inactive image in this case, use update_fw BMC --inactive --force.

11.1. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container. It includes instructions for performing a transitional update for systems that require it. The commands use the .run file, but you can also use any method described in <u>Using the DGX A100 FW Update Utility</u>.

CAUTION: Stop all unnecessary system activities before attempting to update firmware, and do not add additional loads on the system (such as Kubernetes jobs or other user jobs or diagnostics) while an update is in progress. A high GPU workload can disrupt the firmware update process and result in an unusable component.

1. Check if updates are needed by checking the installed versions.

\$ sudo nvfw-dgxa100_20.11.3_201124.run show_version

- If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
- If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 2. Perform the update for all firmware supported by the container.

\$ sudo nvfw-dgxa100_20.11.3_201124.run update_fw all

Depending on the firmware that is updated, you may be prompted to either reboot the system or power cycle the system.

- ▶ If you are prompted to reboot, issue
 - \$ sudo reboot
- If you are prompted to power cycle, you can issue the following two commands (there is no output with the first command).
 - \$ sudo ipmitool raw 0x3c 0x04
 - \$ sudo ipmitool chassis power cycle
- 3. After rebooting or power cycling the system, you may need to perform another update_fw all to update other firmware.
 - Either repeat Step 1 to check if updates are needed and then perform Step 2 if needed, or
 - Repeat Step 2 just in case updates are needed.

If you perform another update_fw all, you may be prompted again to either reboot the system or power cycle the system.

See <u>DGX A100 Firmware Update Process</u> for more information about the update process.

4. Rename the firmware update log file (the update generates /var/log/nvidia-fw.log which you should rename).

Example:

\$ sudo mv /var/log/nvidia-fw.log /var/log/nvidia-fw-large.log

Refer to <u>Firmware Update Log File Size Impacts nvsm dump health</u> for more information.

You can verify the update by issuing the following.

\$ sudo nvfw-dgxa100_20.11.3_201124.run show_version

Example output for a DGX A100 320GB system

BMC DGX				
Image Id S 0:Active Boot C 1:Inactive Updatable	tatus Locatio nline Local Local	n Onboard Version 00.13.16 00.13.16	Manifest u 00.13.16 00.13.16	p_to_date yes yes
CEC				
MB_CEC(enabled)		Onboard Version 3.25	Manifest u 3.25	p-to-date yes
SBIOS				
Image Id 0:Inactive Updatabl 1:Active Boot	Method afulnx	Onboard Version 0.30 0.30	Manifest v 0.30 0.30	p_to_date yes yes
Video BIOS				
Bus Model 0000:07:00.0 A100-SX 0000:0f:00.0 A100-SX 0000:47:00.0 A100-SX 0000:47:00.0 A100-SX 0000:87:00.0 A100-SX 0000:90:00.0 A100-SX 0000:90:00.0 A100-SX 0000:b7:00.0 A100-SX 0000:b7:00.0 A100-SX 0000:b7:00.0 A100-SX	M4-40GB M4-40GB M4-40GB M4-40GB M4-40GB M4-40GB M4-40GB M4-40GB	Onboard Version 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10 92.00.19.00.10	Manifest 92.00.19.00. 92.00.19.00. 92.00.19.00. 92.00.19.00. 92.00.19.00. 92.00.19.00. 92.00.19.00.	up-to-date 10 yes 10 yes 10 yes 10 yes 10 yes 10 yes 10 yes 10 yes
Switches ==========				
PCI Bus# DGX - 0000:91:00.0(U26 DGX - 0000:88:00.0(U26 DGX - 0000:4f:00.0(U26	Model 1) 88064_Retin 0) 88064_Retin 2) 88064_Retin	Onboard Version mer 0.F.0 mer 0.F.0 mer 0.F.0	Manifest 0.F.0 0.F.0 0.F.0	up-to-date yes yes yes
DGX - 0000:48:00.0(U22	5) 88080_Reti	mer 0.F.O	0.F.O	yes
DGX - 0000:c4:00.0 DGX - 0000:c5:00.0 DGX - 0000:c2:00.0 DGX - 0000:c6:00.0 DGX - 0000:c3:00.0 DGX - 0000:c7:00.0	LR10 LR10 LR10 LR10 LR10 LR10	92.10.14.00.01 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01 92.10.14.00.01	92.10.14.00. 92.10.14.00. 92.10.14.00. 92.10.14.00. 92.10.14.00. 92.10.14.00. 92.10.14.00.	01 yes 01 yes 01 yes 01 yes 01 yes 01 yes
DGX - 0000:01:00.0(U1) DGX - 0000:81:00.0(U3) DGX - 0000:41:00.0(U2) DGX - 0000:b1:00.0(U4)	PEX88096 PEX88096 PEX88096 PEX88096	1.8 1.8 1.8 1.8	1.8 1.8 1.8 1.8	yes yes yes yes

11.2. Known Issues

11.2.1. Firmware Update Log File Size Impacts nvsm dump health

Issue

After running the container, the generated log file (/var/log/nvidia-fw.log) can grow to up to tens of gigabytes in size, depending on the firmware that gets updated. If, at a later time, you run nvsm dump health, the command might time out and fail if the file size is too large.

Explanation

To avoid problems running nvsm dump health, rename the generated firmware update log file after updating the firmware.

Example:

\$ sudo mv /var/log/nvidia-fw.log /var/log/nvidia-fw-large.log

11.2.2. BMC UI May not be Accessible from Mac OS

Issue

When attempting to connect to the DGX A100 BMC from a system with Mac OS, a "Your connection is not private" message appears that prevents access to the BMC.

Explanation

Starting with version 0.13.6, the BMC provides a self-signed certificate which Mac OS flags in the browser. Most browsers will let you either accept the risk and continue, or add the certificate to the keychain and continue. The Chrome and Opera browsers, however, do not provide these options and so Mac OS users will not be able to access the BMC from the Chrome or Opera browser.

To access the DGX A100 BMC, Mac OS users can use Safari or Firefox, which provide an access path.

11.2.3. Update Timeout Reported for Motherboard CEC

Issue

The update progress output reports "Update_timeout" for the motherboard CEC (MB_CEC) when using the .run file without Docker installed.

Example

+			+
+			+
İ.I.	!!!!! Firmware Update In	Progress !!!!!	
11	Status: reflash BMC	firmware	
+			+
1	Onboard	Manifest	Update Status
MB_CEC	3.05	3.25	Update timeout

Explanation

This message can be ignored provided that the MB_CEC update is successful.

Example success message:

Success: Installed firmware 3.25 on MB CEC

11.2.4. Boot Order in the SBIOS Reverts to the Default

Issue

After updating the SBIOS, any changes in the boot order that you have made are not preserved and the boot order specified in the SBIOS reverts to the following.

Boot Option #1 [Hard Disk] Boot Option #2 [NVME] Boot Option #3 [USB CD/DVD] Boot Option #4 [USB Hard Disk] Boot Option #5 [USB Key] Boot Option #6 [Network]

Explanation

You will need to prepare for the change when restarting the system, and then enter the SBIOS setup to edit the boot order as needed.

Chapter 12. DGX A100 System Firmware Update Container Version 20.05.12.3

The DGX Firmware Update container version 20.05.12.3 is available.

- Package name:nvfw-dgxa100_20.05.12.3_200716.tar.gz
- Run file name: nvfw-dgxa100_20.05.12.3_200716.run
- Image name: nvfw-dgxa100:20.05.12.3

Highlights and Changes in this Release

- This release is supported with the following DGX OS software -
 - DGX OS 4.99.9 or later
 - DGX OS 5.0.x

Before using the container to update firmware on DGX OS 5.0.x or later, first stop certain NVIDIA services. See <u>Updating Firmware on DGX Systems Installed with DGX</u> <u>OS Release 5.0 or Later</u>.

Fixed an issue where the DGX A100 fans would run at high speed when the optional dualport network card was not installed.

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table.

Component	Version	Key Changes	Update Time
BMC (via CEC)	00.12.06	Fixed high fan speed bug.	31 minutes
SBIOS	0.25	No change	7 minutes
Broadcom 88096 PCIe switch board	1.3	No change	8 minutes

Component	Version	Key Changes	Update Time
BMC CEC SPI	v3.05	No change	8 minutes
PEX88064 Retimer	0.13.0	No change	7 minutes
PEX88080 Retimer	0.13.0	No change	7 minutes
NvSwitch BIOS	92.10.12.00.01	No change	8 minutes
VBIOS	92.00.19.00.01	No change	7 minutes

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

- SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image. After reboot, the updated image becomes the active image. You can perform the update again to update the current inactive image so that both images are updated.
- BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image. After the update is completed, the updated image becomes the active image. You can perform the update again to update the current inactive image so that both images are updated.

12.1. Updating Firmware on DGX Systems Installed with DGX OS Release 5.0 or Later

You need to stop certain NVIDIA services before using the container to update firmware on systems installed with DGX OS 5.0.x or later

If you run the container using either the docker run or .run file method, then stop services first by issuing the following.

\$ sudo systemctl stop nvsm dcgm nvidia-fabricmanager nvidia-persistenced.service

 If you run the container using NVSM CLI, then stop services first by issuing the following (does not include stopping nvsm).

\$ sudo systemctl stop dcgm nvidia-fabricmanager nvidia-persistenced.service

12.2. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container. It includes instructions for performing a transitional update for systems that require it. The commands use the .run file, but you can also use any method described in <u>Using the DGX A100 FW Update Utility</u>.

CAUTION: Stop all unnecessary system activities before attempting to update firmware, and do not add additional loads on the system (such as Kubernetes jobs or other user jobs or diagnostics) while an update is in progress. A high GPU workload can disrupt the firmware update process and result in an unusable component.

1. Perform a transitional update if needed.

Depending on the BMC and MB_CEC versions on the system, you may need to perform a transitional update before updating the BMC and SBIOS to the latest versions.

a). Check if the transitional update is needed.

```
$ sudo nvfw-dgxa100_20.05.12.3_200716.run run_script --command "fw_transition.py
show_version"
```

The following message appears if a transition update is needed.

```
BMC/MB_CEC firmware needs update to Active/Inactive, secure boot mode
This is a one-time update required for DGXA100. All future updates require BMC
in this mode
```

- If the one-time update is required, continue with the next step to perform the transitional update.
- If the one-time update is not required, then skip to step 2.
- b). Refer to <u>Updating Firmware on DGX Systems Installed with DGX OS Release 5.0 or</u> <u>Later</u>to see if services need to be stopped and how to do it.
- c). Perform the transitional update.

```
$ sudo nvfw-dgxa100_20.05.12.3_200716.run run_script --command "fw_transition.py
update_fw"
$ sudo reboot
```

d). Verify that BMC (both images) and the MB_CEC are up to date.

\$ sudo nvfw-dgxa100_20.05.12.3_200716.run run_script --command "fw_transition.py show_version"

2. Check if other updates are needed by checking the installed versions.

 $\$ sudo nvfw-dgxa100_20.05.12.3_200716.run show_version

- If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
- If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 3. Perform the final update for all firmware supported by the container and reboot the system.
 - a). Refer to <u>Updating Firmware on DGX Systems Installed with DGX OS Release 5.0 or</u> <u>Later</u>to see if services need to be stopped and how to do it.
 - b). Perform the update.
 - \$ sudo nvfw-dgxa100_20.05.12.3_200716.run update_fw all

\$ sudo reboot



Note: The update_fw all command updates the inactive BMC and SBIOS images only. After rebooting the system, the updated images become "active". You can then update the inactive images using nvfw-dgxa100_20.05.12.3_200716.run update_fw [BMC] [SBIOS] as needed.

You can verify the update by issuing the following.

$\$ sudo nvfw-dgxa100_20.05.12.3_200716.run show_version

Expected output.

PMC DCY						
BMC DGX						
Image Id 0:Active Boo	Status t Online	Location Local	Onboard Version 00.12.06	Manifest 00.12.06	up_to_da ye	ite es
1:Inactive opu	alabie	LOCAL	00.12.00	00.12.06	Уe	:5
CEC						
				March		
MB_CEC(enabled)		3.05	3.05	up-co-da ye	es
SBIOS						
====== Imago Id		Mothod	Onhoard Vorgion	Manifost	un to dr	a+ 0
0:Inactive Upd	atabl	afulnx	0.25	0.25	up_to_de ve	ice is
1:Active Boo	t		0.25	0.25	Уe	es
Video BIOS						
	Madal		Onheard Maraian	Manifact	up to c	dat a
0000:07:00.0	A100-SXM4-40	GB	92.00.19.00.01	92.00.19.00	up-co-c	ves
0000:0f:00.0	A100-SXM4-40	GB	92.00.19.00.01	92.00.19.00	.01 y	zes
0000:47:00.0	A100-SXM4-40	GB	92.00.19.00.01	92.00.19.00	.01 5	<i>y</i> es
0000:4e:00.0	A100-SXM4-40	GB	92.00.19.00.01	92.00.19.00	.01 y	<i>i</i> es
0000:8/:00.0	A100-SXM4-40	GB	92.00.19.00.01 92.00.19.00.01	92.00.19.00	.01 y	7es
0000:b7:00.0	A100-SXM4-40	GB	92.00.19.00.01	92.00.19.00	.01 y	ves
0000:bd:00.0	A100-SXM4-40	GB	92.00.19.00.01	92.00.19.00	.01 5	zes
Switches						
======== PCT_Bus#	Μ	odel	Onboard Version	Manifest	un-to-	-date
DGX - 0000:91:	00.0(U261) 8	8064 Retim	er 0.13.0	0.13.0	up 00	yes
DGX - 0000:88:	00.0(U260) 8	8064 Retim	er 0.13.0	0.13.0		yes
DGX - 0000:4f:	00.0(U262) 8	8064_Retim	er 0.13.0	0.13.0		yes
DGX - 0000:48:	00.0(U225) 8	8080_Retim	er 0.13.0	0.13.0		yes
DGX - 0000:c4:	00.0 L	R10	92.10.12.00.01	92.10.12.00	.01	ves
DGX - 0000:c5:	00.0 L	R10	92.10.12.00.01	92.10.12.00	.01	yes
DGX - 0000:c2:	00.0 L	R10	92.10.12.00.01	92.10.12.00	.01	yes
DGX - 0000:c6:	00.0 L	R10	92.10.12.00.01	92.10.12.00	.01	yes
DGX - 0000:c3: DGX - 0000:c7:	00.0 L	R10 R10	92.10.12.00.01	92.10.12.00	.01	yes yes
		T V00000	1 0	1 2		1
DGX = 0000:01:	UU.U(U1) P	EX88096	1.3	1.3		yes
DGX = 0000:81: DGX = 0.000:41.	00.0(03) P 00.0(12) P	EX88096	1.3	1.3		yes
DGX - 0000:b1:	00.0(U4) P	EX88096	1.3	1.3		yes

Chapter 13. DGX A100 System Firmware Update Container Version 20.05.12.2

The DGX Firmware Update container version 20.05.12.2 is available.

- Package name:nvfw-dgxa100_20.05.12.2_200630.tar.gz
- Run file name: nvfw-dgxa100_20.05.12.2_200630.run
- Image name: nvfw-dgxa100:20.05.12.2

Highlights and Changes in this Release

- This release is supported with the following DGX OS software -
 - ► DGX OS 4.99.9 or later
- Restored ability to view hidden options in the SBIOS setup screens.

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table.

Component	Version	Key Changes	Update Time
BMC (via CEC)	00.12.05	No change.	31 minutes
SBIOS	0.25	 Restored Hidden Options 	7 minutes
Broadcom 88096 PCIe switch board	1.3	No change	8 minutes
BMC CEC SPI	v3.05	No change	8 minutes
PEX88064 Retimer	0.13.0	No change	7 minutes
PEX88080 Retimer	0.13.0	No change	7 minutes
NvSwitch BIOS	92.10.12.00.01	No change	8 minutes

Component	Version	Key Changes	Update Time
VBIOS	92.00.19.00.01	No change	7 minutes

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

- SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image. After reboot, the updated image becomes the active image. You can perform the update again to update the current inactive image so that both images are updated.
- BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image. After the update is completed, the updated image becomes the active image. You can perform the update again to update the current inactive image so that both images are updated.

13.1. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container. It includes instructions for performing a transitional update for systems that require it. The commands use the .run file, but you can also use the container image directly.

1. Perform a transitional update if needed.

Depending on the BMC and MB_CEC versions on the system, you may need to perform a transitional update before updating the BMC and SBIOS to the latest versions.

a). Check if the transitional update is needed.

```
$ sudo nvfw-dgxa100_20.05.12.2_200630.run run_script --command "fw_transition.py
show_version"
```

The following message appears if a transition update is needed.

```
BMC/MB_CEC firmware needs update to Active/Inactive, secure boot mode
This is a one-time update required for DGXA100. All future updates require BMC
in this mode
```

- If the one-time update is required, continue with the next step to perform the transitional update.
- ▶ If the one-time update is not required, then skip to step 2.
- b). Perform the transitional update.

```
$ sudo nvfw-dgxa100_20.05.12.2_200630.run run_script --command "fw_transition.py
update_fw"
$ sudo reboot
```

c). Verify that BMC (both images) and the MB_CEC are up to date.

\$ sudo nvfw-dgxa100_20.05.12.2_200630.run run_script --command "fw_transition.py show_version"

2. Check if other updates are needed.

 $\$ sudo nvfw-dgxa100_20.05.12.2_200630.run show_version

- If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
- If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 3. Perform the final update for all firmware supported by the container and reboot the system.

```
$ sudo nvfw-dgxa100_20.05.12.2_200630.run update_fw all
```

```
$ sudo reboot
```



Note: The update_fw all command updates the inactive BMC and SBIOS images only. After rebooting the system, the updated images become "active". You can then update the inactive images using nvfw-dgxa100_20.05.12.2_200630.run update_fw [BMC] [SBIOS] --inactive as needed.

You can verify the update by issuing the following.

$\$ sudo nvfw-dgxa100_20.05.12.2_200630.run show_version

Expected output.

BMC DGX					
Image Id 0:Active Boot 1:Inactive Upda	Status t Online atable	Location Local Local	Onboard Version 00.12.05 00.12.05	Manifest 00.12.05 00.12.05	up_to_date yes yes
CEC					
MB_CEC(enabled))		Onboard Version 3.05	Manifest 3.05	up-to-date yes
SBIOS ======					
Image Id 0:Inactive Upda 1:Active Boot	atabl t	Method afulnx	Onboard Version 0.25 0.25	Manifest 0.25 0.25	up_to_date yes yes
Video BIOS					
Bus 0000:07:00.0 0000:0f:00.0 0000:47:00.0 0000:4e:00.0 0000:87:00.0 0000:90:00.0 0000:b7:00.0 0000:bd:00.0	Model A100-SXM4-40 A100-SXM4-40 A100-SXM4-40 A100-SXM4-40 A100-SXM4-40 A100-SXM4-40 A100-SXM4-40 A100-SXM4-40	GB GB GB GB GB GB	Onboard Version 92.00.19.00.01 92.00.19.00.01 92.00.19.00.01 92.00.19.00.01 92.00.19.00.01 92.00.19.00.01 92.00.19.00.01 92.00.19.00.01	Manifest 92.00.19.0 92.00.19.0 92.00.19.0 92.00.19.0 92.00.19.0 92.00.19.0 92.00.19.0 92.00.19.0	up-to-date 0.01 yes 0.01 yes 0.01 yes 0.01 yes 0.01 yes 0.01 yes 0.01 yes 0.01 yes
Switches					
PCI Bus# DGX - 0000:91:0 DGX - 0000:88:0	M 00.0(U261) 8 00.0(U260) 8	odel 8064_Retim 8064_Retim	Onboard Version er 0.13.0 er 0.13.0	Manifest 0.13.0 0.13.0	up-to-date yes yes

DGX - 0000:4f:00.0(U262)	88064_Retime	er 0.13.0	0.13.0	yes
DGX - 0000:48:00.0(U225)	88080_Retime	er 0.13.0	0.13.0	yes
DGX - 0000:c4:00.0	LR10	92.10.12.00.01	92.10.12.00.01	yes
DGX - 0000:c5:00.0	LR10	92.10.12.00.01	92.10.12.00.01	yes
DGX - 0000:c2:00.0	LR10	92.10.12.00.01	92.10.12.00.01	yes
DGX - 0000:c6:00.0	LR10	92.10.12.00.01	92.10.12.00.01	yes
DGX - 0000:c3:00.0	LR10	92.10.12.00.01	92.10.12.00.01	yes
DGX - 0000:c7:00.0	LR10	92.10.12.00.01	92.10.12.00.01	yes
DGX - 0000:01:00.0(U1)	PEX88096	1.3	1.3	yes
DGX - 0000:81:00.0(U3)	PEX88096	1.3	1.3	yes
DGX - 0000:41:00.0(U2)	PEX88096	1.3	1.3	yes
DGX - 0000:b1:00.0(U4)	PEX88096	1.3	1.3	yes

Chapter 14. DGX A100 System Firmware Update Container Version 20.05.12

The DGX Firmware Update container version 20.05.12 is available.

- Package name:nvfw-dgxa100_20.05.12_200603.tar.gz
- Run file name: nvfw-dgxa100_20.05.12_200603.run
- Image name: nvfw-dgxa100:20.05.12

Highlights and Changes in this Release

- This release is supported with the following DGX OS software -
 - ▶ DGX OS 4.99.8 or later
- Enabled BMC Secure Flash
- Enabled PCI-Compliant DPC and AER error propagation
- Implemented critical VBIOS fixes

Contents of the DGX A100 System Firmware Container

This container includes the firmware binaries and update utilities for the firmware listed in the following table.

Component	Version	Key Changes	Update Time
BMC (via CEC)	00.12.05	Added to container. BMC now recognizes the level of CEC	31 minutes
		installed, and enforces Secure Flash if the CEC supports it.	
		 Removed the ability to update the BMC via the UI. 	

Component	Version	Key Changes	Update Time
		 Added micro-controller assist (MCA) SEL, downloadable from the UI. 	
		 Added Logs & Reports > Debug Log > Download Debug log control to BMC UI. 	
SBIOS	0.23	 Added to container Removed Hidden Options and made TPM Configuration options visible Fixed NVSM Show Health Errors related to DIMMs and DIMM population Fixed system getting stuck at POST after enabling and then disabling drive encryption 	7 minutes
Broadcom 88096 PCIe switch board	1.3	Added to containerDisabled hot-plug and hot-plug surprise capability	8 minutes
BMC CEC SPI	v3.05	Added to container	8 minutes
PEX88064 Retimer	0.13.0	Updated	7 minutes
PEX88080 Retimer	0.13.0	Updated	7 minutes
NvSwitch BIOS	92.10.12.00.01	No change	8 minutes
VBIOS	92.00.19.00.01	Updated	7 minutes
		 Fixed Xid 64 (Row Remapper Error) 	

Updating Components with Secondary Images

Some firmware components provide a secondary image as backup. The following is the policy when updating those components:

- SBIOS: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image. After reboot, the updated image becomes the active image. You can perform the update again to update the current inactive image so that both images are updated.
- BMC: The two images are referred to as active and inactive, where the active is the currently running image and the inactive is the backup image. The update container can only update the inactive image. After the update is completed, the updated image becomes the active image. You can perform the update again to update the current inactive image so that both images are updated.

14.1. Instructions for Updating Firmware

This section provides a simple way to update the firmware on the system using the firmware update container. It includes instructions for performing a transitional update for systems that require it. The commands use the .run file, but you can also use the container image directly.

1. Perform a transitional update if needed.

Depending on the BMC and MB_CEC versions on the system, you may need to perform a transitional update before updating the BMC and SBIOS to the latest versions.

a). Check if the transitional update is needed.

\$ sudo nvfw-dgxa100_20.05.12_2006003.run run_script --command "fw_transition.py show_version"

The following message appears if a transition update is needed.

BMC/MB_CEC firmware needs update to Active/Inactive, secure boot mode This is a one-time update required for DGXA100. All future updates require BMC in this mode

- If the one-time update is required, continue with the next step to perform the transitional update.
- ▶ If the one-time update is not required, then skip to step 2.
- b). Perform the transitional update.

```
$ sudo nvfw-dgxa100_20.05.12_2006003.run run_script --command "fw_transition.py
update_fw"
$ sudo reboot
```

c). Verify that BMC (both images) and the MB_CEC are up to date.

\$ sudo nvfw-dgxa100_20.05.12_2006003.run run_script --command "fw_transition.py show_version"

2. Check if other updates are needed.

\$ sudo nvfw-dgxa100_20.05.12_2006003.run show_version

- If there is "no" in any up-to-date column for updatable firmware, then continue with the next step.
- If all up-to-date column entries are "yes", then no updates are needed and no further action is necessary.
- 3. Perform the final update for all firmware supported by the container and reboot the system.

```
$ sudo nvfw-dgxa100_20.05.12_2006003.run update_fw all
```

```
$ sudo reboot
```

Note: The update_fw all command updates the inactive BMC and SBIOS images only. After rebooting the system, the updated images become "active". You can then update the inactive images using nvfw-dgxa100_20.05.12_2006003.run update_fw [BMC] [SBIOS] --inactive as needed.

You can verify the update by issuing the following.
\$ sudo nvfw-dgxa100_20.05.12_2006003.run show_version

Expected output.

BMC DGX							
Image Id 0:Active Boot 1:Inactive Updatal	Status Online ole	Location Local Local	Onboar 00.12 00.12	d Version .05 .05	Manifest 00.12.05 00.12.05	up_to_	_date yes yes
CEC							
		0	nhoard	Version	Manifest	un-to-	-date
MB_CEC(enabled)		Ū	3.05		3.05	ap co	yes
SBIOS							
Image Id	Me	thod 0	nboard	Version	Manifest	up t.o	date
0:Inactive Updata 1:Active Boot	ol af	ulnx	0.24 0.24		0.24 0.24	- <u>-</u> <u>-</u>	yes yes
Video BIOS							
Bus Mod	del	0	nboard	Version	Manifest	up-to	o-date
0000:07:00.0 A1	00-SXM4-40GB	9	2.00.19	.00.01	92.00.19.	00.01	yes
0000:0f:00.0 A1	00-SXM4-40GB	9	2.00.19	.00.01	92.00.19.	00.01	yes
0000:47:00.0 A1	00-SXM4-40GB	9	2.00.19	.00.01	92.00.19.	00.01	yes
0000:4e:00.0 Al	00-SXM4-40GB	9	2.00.19	.00.01	92.00.19.	00.01	yes
0000:90:00.0 A1	00-3xm4-40Gb 00-8xm4-40Gb	9	2.00.19	.00.01	92.00.19.	00.01	ves
0000:b7:00.0 A1	00-SXM4-40GB	9	2.00.19	.00.01	92.00.19.	00.01	yes
0000:bd:00.0 A1	00-SXM4-40GB	9	2.00.19	.00.01	92.00.19.	00.01	yes
Switches							
PCI Bus#	Mod	el	Onboard	Version	Manifest	up-1	to-date
DGX - 0000:91:00.	0(U261) 880	64_Retime	r 0.13	.0	0.13.0		yes
DGX - 0000:88:00.	0(U260) 880	64_Retime	r 0.13	.0	0.13.0		yes
DGX - 0000:41:00.0	0(0262) 880	64_Retime	r 0.13	.0	0.13.0		yes
DGX - 0000:48:00.	0(U225) 880	80_Retime	r 0.13	.0	0.13.0		yes
DGX - 0000:c4:00.	0 LR1	0	92.10.1	2.00.01	92.10.12.	00.01	yes
DGX - 0000:c5:00.	0 LR1	0	92.10.1	2.00.01	92.10.12.	00.01	yes
DGX - 0000:c2:00.	0 LR1	0	92.10.1	2.00.01	92.10.12.	00.01	yes
DGX - 0000:c6:00.	U LR1	0	92.10.1	2.00.01	92.10.12.	00.01	yes
DGX = 0000:C3:00.0 DGX = 0000:C7:00.0	0 LRI 0 LRI	0	92.10.1	2.00.01	92.10.12.	00.01	yes yes
DGX - 0000:01:00.	0(U1) PEX	88096	1.3		1.3		yes
DGX - 0000:81:00.	0(U3) PEX	88096	1.3		1.3		yes
DGX - 0000:41:00.	0(U2) PEX	88096	1.3		1.3		yes
DGX - 0000:b1:00.	U(U4) PEX	88096	1.3		1.3		yes

Chapter 15. DGX A100 Firmware Changes

This chapter contains the list of changes for the following DGX A100 firmware components.

15.1. DGX A100 BMC Changes

Changes in 00.19.07

- Added a new version of GPU baseboard support.
- Improved SNMP trap handling and updated SNMP MIB with additional description for better trap information.
- Handled a rare NTP server configuration settings issue from BMC WebUI.
- The BMC update includes software security enhancements. See the <u>NVIDIA Security</u> <u>Bulletin DGX - December 2022</u> for details.

Changes in 00.18.03

Added a new version of GPU baseboard support.

Changes in 00.17.07

- Fixed an issue so that certain sensors are now displayed in the BMC Web UI.
- Fixed the graceful handling of system power loss, which prevents the BMC Flash file system consistency issue and improves recovery.
- Fixed issues that caused the BMC usage to dramatically increase, which resulted in a POST failure with error code 91 or B4.
- Improves Redfish interface error handling.
- Fixed the BMC Web UI security settings and page refresh during full screen mode.
- Fixed BMC SEL Event page, which was causing an error in certain SEL record parsing.
- Fixed an issue where the Power/Status LED was flashing continuously after the server was rebooted, and the Power/Status LED stayed on after the server was powered off.

Changes in 00.16.09

- Fixed incorrect temperatures reported for sensors on the NVIDIA Networking ConnectX-6 single-port and dual-port VPI cards.
- Fixed a bug to ensure that the BMC will boot to the latest version updated on the system.
- Fixed SEL log not showing the correct BMC or SBIOS version after an update.
- Added ability to set the BMC to local time instead of default UTC.
- Added ability to sync local time to NTP servers. (enable NTP time sync).
- Removed unnecessary SEL log messages pointing to high CPU power consumption.
- Fixed "/" character not allowed in BMC web UI LDAP Role Group settings.
- Added authentication capabilities to the RESTful API.
- Added new capabilities to identify firmware updates in the System Event Log (SEL) via "NVIDIA-firmware" event.

Adds SEL information for BMC (end), BIOS, CPLD, and PSU.

Changes in 00.14.17

Added support for second source SPI ROM.

Changes in 00.14.16

- Fixed an issue where a cold boot might put the BMC in a non-bootable state.
- ▶ Fixed BMC update failing with "Error flashing Inactive image 2: rc = 0x-9",
- Fixed occasionally needing to log into the BMC WebUI twice.
- Fixed the BMC dashboard system event filter not working.
- Added ability to monitor Mellanox card transceiver temperatures and increase fan speeds.
- Fixed inability to update the BMC after unexpected interruption.
- Fixed missing memory, NIC and storage drive information.

Changes in 00.13.16

• The BMC update includes software security enhancements.

See the <u>NVIDIA Security Bulletin 5010</u> for details.

Changes in 00.13.04

Resolved increased fan speed that occurred when optional components are not installed, even when the system is idle.

15.2. DGX A100 SBIOS Changes

Changes in 1.18

- Added a new version of GPU baseboard support.
- Fixed issues relating to redfish reporting of PCIe device types and speeds.
- Removed unimplemented setup menu options for User Defaults and Boot NumLock State.
 Updated AGESA to version 1.0.0.E

The SBIOS update includes software security enhancements. See the <u>NVIDIA Security</u> <u>Bulletin DGX - December 2022</u> for details.

Changes in 1.13

- Fixed two issues that were causing boot order settings to not be saved to the BMC if applied out-of-band, causing settings to be lost after a subsequent firmware update.
- Added interactive countdown messages during boot, to display the Setup Prompt Timeout configurable through the Boot > Setup Prompt Timeout configuration menu.
- Added reporting of AGESA Version in SMBIOS.
- Updated AGESA to version 1.0.0.D.

Changes in 1.09

- Fixed an issue where changes in the boot order are not preserved after updating the SBIOS.
- Fixed inability to enter the SBIOS Admin/User password from the Serial Over LAN (SOL) console.
- Fixed PXE boot configuration not persisting; helpful for multiple DGX A100 nodes.
- Added Memory correctable ECC Error leaky bucket; prevents unnecessary replacement of working system DIMMs.
- Fixed SBIOS Setup > Main page showing incorrect Admin/User Access level.

Changes in 0.34

 Removed warning message that occurred when the system contained DIMMs from different vendors.

Changes in 0.33

Fixed mishandling of correctable PCIe errors.

Changes in 0.30

- Added support for HTTP boot.
- Updated DSP/USP preset values to address PCIe advanced error reporting (AER) issues.

- Changed the following default settings.
 - Determinism Control > [Manual]
 - Determinism Slider > [Power]
 - cTDP Control > [Manual]
 - ▶ cTDP > [240]
 - Package Power Limit Control > [Manual]
 - Package Power Limit > [240]
 - DF Cstates > [Disabled]

15.3. DGX A100 U.2 NVMe Changes

Changes in EPK9CB5Q

- Fixed drive going into read-only mode if there is a sudden power cycle while performing live firmware update.
- Improved write performance while performing drive wear-leveling; shortens wear-leveling process time.
- Fixed drive going into failed mode when a high number of uncorrectable ECC errors occurred.

15.4. DGX A100 Broadcom 88096 PCIe Switchboard Changes

Changes in 0.2.0

• Fixed the incorrect setting of the switch's Upstream Port Number as Port 0.

Changes in 1.8

Implemented tuning to address PCIe advanced error reporting (AER) issues.

Changes in 1.3

Disabled hot-plug and hot-plug surprise capability.

15.5. DGX A100 Broadcom 880xx Retimer Changes

Release notes for the DGX A100 Broadcom 88080 and 88064 retimers.

Changes in 1.2f

Fixed an issue that caused NVQual to hang while loading the MODS driver.

Changes in 0.F.0

Improved error handling of downstream switches.

This change modifies the PCIe topology and mapping. Refer to the <u>DGX A100 User Guide</u> for PCIe mapping details.

Changes in 0.13.0

Fixed DPC Notification behavior for Firmware First Platform.

15.6. A100 VBIOS Changes

Changes in 92.00.45.00.03/05

Added security protection to the I2C interface.

Changes in 92.00.36.00.04

- Fixed an issue allocating the BAR1 size across resets.
- Fixed MIG capability not being reported correctly if the driver is not loaded; for example, if accessed out-of-band.

Changes in 92.00.19.00.10

• Expanded support for potential alternate HBM sources.

Changes in 92.00.19.00.01

Fixed Xid 64 (Row Remapper Error)

15.7. DGX A100 BMC CEC Changes

Changes in 3.28

- Fixed the update progress output reporting "Update_timeout" for the motherboard CEC (MB_CEC) when using the .run file without Docker installed.
- Fixed the user's configuration getting lost if the BMC updated failed.

15.8. DGX A100 BMC CEC SPI Changes

Changes in 01.05.12

- Added LDAPS (secure LDAP) support.
- Resolved network connection getting lost when connected to virtual media.
- Resolved an issue where occasionally the BMC UI would stop responding.

Changes in 01.05.10

- Fixed an issue with BMC 01.05.07 that potentially affected SBIOS stability.
- Fixed BMC configuration settings not getting applied to both primary and secondary images.
- Fixed corrupted primary BMC failing to recover when primary and secondary images are different versions.
- Fixed issue recovering corrupted firmware on Delta PSU.
- Fixed BMC web UI reporting BIOS information incorrectly.
- Fixed BMC Web UI reporting backup BMC version incorrectly.
- Fixed cryptic BMC entries.
- Added BMC capture logs from CPLD/FPGA during power on.
- Added IPMI OEM command to GET and SET which image the SBIOS is pointing to (Change the PIN).
- Fixed MaxP/MaxQ System unable to boot after BMC-initiated shutdown with four or more PSU failures.
- Fixed SEL logs to indicate that a bad fan (or fan speed of zero) may have caused the system to shut down due to GPU overtemp.
- Fixed how the BMC responds when it cannot read a temperature sensor.
- Fixed the IPMI log event decoding through ipmitool to show the same events as the GUI.
- Fixed the BMC to provide more meaningful and useful SEL logs.

- Fixed the GPU sensor name on baseboard 2 to match the service label.
- Changed the naming of U.2 SSDs from "NVME" to "U.2".-
- Resolved BMC SNMP community string limitations.

Changes in 01.04.03

- Fixed BMC Update Timeout issue.
- Fixed BMC configuration backup/restore function not working properly.
- Fixed system not shutting down when all fans in Fan Zone 2 or 3 are not detected.
- Fixed system fans all running at 80% after hot-unplugging/hot-plugging a PSU.
- Fixed system fans running at 80% after hot-plugging an NVMe drive.
- Fixed system shutting down after hot-unplugging one of the fans.
- Fixed system unable to boot after updating BMC image while one BMC module is removed.
- Fixed incorrect SEL timestamp after executing ipmi mc reset cold.
- Fixed missing firmware information in the BMC dashboard. Information is available on the Maintenance->Firmware Information page.
- Fixed missing DIMM information in the BMC dashboard.
- Fixed blinking amber-colored power LED.
- Fixed BMC update freeze while updating using Yafuflash.
- ► Fixed issues responding to 3.3V/5V/12V sensors.
- Fixed incorrect responses to GPU temperature assertion Fan Zone 1 goes to 80% and DIMM temperature reports 'device disabled'.
- The BMC now saves CPU MCA registers when it detects a fatal MCA error.

Changes in 01.00.01

- Fixed BMC update via dashboard erroneously preserving the configuration.
- Fixed Network Link Configuration and Network IP Settings pages on the BMC dashboard to reflect changes only when saved.
- Added dual FPGA image container update support.
- Added PSU firmware container update support.
- Enhanced SMBPBI support for GPU sensors, thermal polling and FAN control to avoid anomalous sensor reading for GPU sensors and corresponding thermal actions.
- Added support for FPGA update of Image #1 to the BMC dashboard.
- Added VLAN support to the BMC dashboard.

15.9. DGX A100 BMC Changes

Changes in 01.05.12

- Added LDAPS (secure LDAP) support.
- Resolved network connection getting lost when connected to virtual media.
- Resolved an issue where occasionally the BMC UI would stop responding.

Changes in 01.05.10

- Fixed an issue with BMC 01.05.07 that potentially affected SBIOS stability.
- Fixed BMC configuration settings not getting applied to both primary and secondary images.
- Fixed corrupted primary BMC failing to recover when primary and secondary images are different versions.
- Fixed issue recovering corrupted firmware on Delta PSU.
- Fixed BMC web UI reporting BIOS information incorrectly.
- Fixed BMC Web UI reporting backup BMC version incorrectly.
- Fixed cryptic BMC entries.
- Added BMC capture logs from CPLD/FPGA during power on.
- Added IPMI 0EM command to GET and SET which image the SBI0S is pointing to (Change the PIN).
- Fixed MaxP/MaxQ System unable to boot after BMC-initiated shutdown with four or more PSU failures.
- Fixed SEL logs to indicate that a bad fan (or fan speed of zero) may have caused the system to shut down due to GPU overtemp.
- Fixed how the BMC responds when it cannot read a temperature sensor.
- Fixed the IPMI log event decoding through ipmitool to show the same events as the GUI.
- Fixed the BMC to provide more meaningful and useful SEL logs.
- Fixed the GPU sensor name on baseboard 2 to match the service label.
- Changed the naming of U.2 SSDs from "NVME" to "U.2".-
- Resolved BMC SNMP community string limitations.

Changes in 01.04.03

- Fixed BMC Update Timeout issue.
- Fixed BMC configuration backup/restore function not working properly.
- Fixed system not shutting down when all fans in Fan Zone 2 or 3 are not detected.

- Fixed system fans all running at 80% after hot-unplugging/hot-plugging a PSU.
- Fixed system fans running at 80% after hot-plugging an NVMe drive.
- Fixed system shutting down after hot-unplugging one of the fans.
- Fixed system unable to boot after updating BMC image while one BMC module is removed.
- Fixed incorrect SEL timestamp after executing ipmi mc reset cold.
- Fixed missing firmware information in the BMC dashboard. Information is available on the Maintenance->Firmware Information page.
- Fixed missing DIMM information in the BMC dashboard.
- Fixed blinking amber-colored power LED.
- Fixed BMC update freeze while updating using Yafuflash.
- ► Fixed issues responding to 3.3V/5V/12V sensors.
- Fixed incorrect responses to GPU temperature assertion Fan Zone 1 goes to 80% and DIMM temperature reports 'device disabled'.
- The BMC now saves CPU MCA registers when it detects a fatal MCA error.

Changes in 01.00.01

- Fixed BMC update via dashboard erroneously preserving the configuration.
- Fixed Network Link Configuration and Network IP Settings pages on the BMC dashboard to reflect changes only when saved.
- Added dual FPGA image container update support.
- Added PSU firmware container update support.
- Enhanced SMBPBI support for GPU sensors, thermal polling and FAN control to avoid anomalous sensor reading for GPU sensors and corresponding thermal actions.
- Added support for FPGA update of Image #1 to the BMC dashboard.
- Added VLAN support to the BMC dashboard.

15.10. DGX A100 FPGA Release Notes

Features

- Changes in 03.14
 - FPGA (GPU sled)3.0e: this version of FPGA fixes a GPU Tray failing to power ON during system power cycle (LLC failures will be reported in SEL logs. System fails to boot or comes up with no GPUs). The new versions of FPGA and CEC (GB sled) address this issue and we recommend every customer upgrade these components.
- Changes in 01.05.07

- Fixed BMC configuration settings not getting applied to both primary and secondary images.
- Fixed corrupted primary BMC failing to recover when primary and secondary images are different versions.
- Fixed issue recovering corrupted firmware on Delta PSU.
- Fixed BMC web UI reporting BIOS information incorrectly.
- Fixed BMC Web UI reporting backup BMC version incorrectly.
- Fixed cryptic BMC entries.
- Added BMC capture logs from CPLD/FPGA during power on.
- Added IPMI OEM command to GET and SET which image the SBIOS is pointing to (Change the PIN).
- Fixed MaxP/MaxQ System unable to boot after BMC-initiated shutdown with four or more PSU failures.
- Fixed SEL logs to indicate that a bad fan (or fan speed of zero) may have caused the system to shut down due to GPU overtemp.
- Fixed how the BMC responds when it cannot read a temperature sensor.
- Fixed the IPMI log event decoding through ipmitool to show the same events as the GUI.
- Fixed the BMC to provide more meaningful and useful SEL logs.
- Fixed the GPU sensor name on baseboard 2 to match the service label.
- Changed the naming of U.2 SSDs from "NVME" to "U.2".
- BMC SNMP Support on DGX-2
- Changes in 01.04.03
 - Fixed BMC Update Timeout issue.
 - Fixed BMC configuration backup/restore function not working properly.
 - Fixed system not shutting down when all fans in Fan Zone 2 or 3 are not detected.
 - Fixed system fans all running at 80% after hot-unplugging/hot-plugging a PSU.
 - Fixed system fans running at 80% after hot-plugging an NVMe drive.
 - Fixed system shutting down after hot-unplugging one of the fans.
 - Fixed system unable to boot after updating BMC image while one BMC module is removed.
 - Fixed incorrect SEL timestamp after executing ipmi mc reset cold.
 - Fixed missing firmware information in the BMC dashboard. Information is available on the Maintenance->Firmware Information page.
 - Fixed missing DIMM information in the BMC dashboard.
 - Fixed blinking amber-colored power LED.
 - Fixed BMC update freeze while updating using Yafuflash.

- ► Fixed issues responding to 3.3V/5V/12V sensors.
- Fixed incorrect responses to GPU temperature assertion Fan Zone 1 goes to 80% and DIMM temperature reports 'device disabled'.
- The BMC now saves CPU MCA registers when it detects a fatal MCA error.
- Changes in 01.00.01
 - Fixed BMC update via dashboard erroneously preserving the configuration.
 - Fixed Network Link Configuration and Network IP Settings pages on the BMC dashboard to reflect changes only when saved.
 - Added dual FPGA image container update support.
 - Added PSU firmware container update support.
 - Enhanced SMBPBI support for GPU sensors, thermal polling and FAN control to avoid anomalous sensor reading for GPU sensors and corresponding thermal actions.
 - Added support for FPGA update of Image #1 to the BMC dashboard.
 - Added VLAN support to the BMC dashboard.

15.11. DGX A100 Delta PSU Release Notes

Changes in 1.6/1.6/1.7

Fixed OW reporting issue.

Appendix A. DGX A100 Firmware Update Process

This chapter provides an overview of the firmware update process when issuing ${\tt update_fw}$ all.

The following table shows the order in which the updates are performed, and whether a reboot or power cycle is required to complete the update. The table assumes that all firmware needs to be updated, and corresponds to the following sequence:

- 1. Issue update_fw all.
- 2. Power cycle the system.
- 3. Issue update_fw all.
- 4. Power cycle the system.
- 5. Issue update_fw all.

Table 1.Firmware Updated Upon Initial update_fw all

Update Order	Component	Reboot or Power Cycle Required	
1	BMC-CEC	None	
2	ВМС	None	
3	SBIOS	Reboot	
4	Switch PEX88080/PEX88064	Reboot	
5	Switch PEX88096 (U1~U3)	Reboot	
6	NVMe	DC Power Cycle	
7	GPU VBIOS and FUB	Reboot	
8	CEC1712 SPI	DC Power Cycle	

Table 2.Firmware Updated Upon Second update fw all

Update Order	Component	Reboot or Power Cycle Required		
1	Switch PEX88096 (U4)	Reboot		
2	FPGA	DC Power Cycle		

Table 3.Firmware Updated Upon Third update_fw all

Update Order	Component	Reboot or Power Cycle Required		
1	NVSwitch	Reboot		

Notice

This document is provided for information purposes only and shall not be regarded as a warranty of a certain functionality, condition, or quality of a product. NVIDIA Corporation ("NVIDIA") makes no representations or warranties, expressed or implied, as to the accuracy or completeness of the information contained in this document and assumes no responsibility for any errors contained herein. NVIDIA shall have no liability for the consequences or use of such information or for any infringement of patents or other rights of third parties that may result from its use. This document is not a commitment to develop, release, or deliver any Material (defined below), code, or functionality.

NVIDIA reserves the right to make corrections, modifications, enhancements, improvements, and any other changes to this document, at any time without notice.

Customer should obtain the latest relevant information before placing orders and should verify that such information is current and complete.

NVIDIA products are sold subject to the NVIDIA standard terms and conditions of sale supplied at the time of order acknowledgement, unless otherwise agreed in an individual sales agreement signed by authorized representatives of NVIDIA and customer ("Terms of Sale"). NVIDIA hereby expressly objects to applying any customer general terms and conditions with regards to the purchase of the NVIDIA product referenced in this document. No contractual obligations are formed either directly or indirectly by this document.

NVIDIA products are not designed, authorized, or warranted to be suitable for use in medical, military, aircraft, space, or life support equipment, nor in applications where failure or malfunction of the NVIDIA product can reasonably be expected to result in personal injury, death, or property or environmental damage. NVIDIA accepts no liability for inclusion and/or use of NVIDIA products in such equipment or applications and therefore such inclusion and/or use is at customer's own risk.

NVIDIA makes no representation or warranty that products based on this document will be suitable for any specified use. Testing of all parameters of each product is not necessarily performed by NVIDIA. It is customer's sole responsibility to evaluate and determine the applicability of any information contained in this document, ensure the product is suitable and fit for the application planned by customer, and perform the necessary testing for the application in order to avoid a default of the application or the product. Weaknesses in customer's product designs may affect the quality and reliability of the NVIDIA product and may result in additional or different conditions and/or requirements beyond those contained in this document. NVIDIA accepts no liability related to any default, damage, costs, or problem which may be based on or attributable to: (i) the use of the NVIDIA product in any manner that is contrary to this document or (ii) customer product designs.

No license, either expressed or implied, is granted under any NVIDIA patent right, copyright, or other NVIDIA intellectual property right under this document. Information published by NVIDIA regarding third-party products or services does not constitute a license from NVIDIA to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property rights of the third party, or a license from NVIDIA under the patents or other intellectual property rights of NVIDIA.

Reproduction of information in this document is permissible only if approved in advance by NVIDIA in writing, reproduced without alteration and in full compliance with all applicable export laws and regulations, and accompanied by all associated conditions, limitations, and notices.

THIS DOCUMENT AND ALL NVIDIA DESIGN SPECIFICATIONS, REFERENCE BOARDS, FILES, DRAWINGS, DIAGNOSTICS, LISTS, AND OTHER DOCUMENTS (TOGETHER AND SEPARATELY, "MATERIALS") ARE BEING PROVIDED "AS IS." NVIDIA MAKES NO WARRANTIES, EXPRESSED, IMPLIED, STATUTORY, OR OTHERWISE WITH RESPECT TO THE MATERIALS, AND EXPRESSLY DISCLAIMS ALL IMPLIED WARRANTIES OF NONINFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE. TO THE EXTENT NOT PROHIBITED BY LAW, IN NO EVENT WILL NVIDIA BE LIABLE FOR ANY DAMAGES, INCLUDING WITHOUT LIMITATION ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, PUNITIVE, OR CONSEQUENTIAL DAMAGES, HOWEVER CAUSED AND REGARDLESS OF THE THEORY OF LIABILITY, ARISING OUT OF ANY USE OF THIS DOCUMENT, EVEN IF NVIDIA HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. Notwithstanding any damages that customer might incur for any reason whatsoever, NVIDIA's aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms of Sale for the product.

Trademarks

NVIDIA, the NVIDIA logo, DGX, DGX-1, DGX-2, DGX A100, DGX Station, and DGX Station A100 are trademarks and/or registered trademarks of NVIDIA Corporation in the Unites States and other countries. Other company and product names may be trademarks of the respective companies with which they are associated.

Copyright

© 2023 NVIDIA Corporation & Affiliates. All rights reserved.

