



NVIDIA DOCA

Release Notes

Table of Contents

| | |
|---|---|
| Chapter 1. Introduction..... | 1 |
| Chapter 2. New Features, Updates, and Enhancements..... | 2 |
| Chapter 3. Installation Notes..... | 3 |
| 3.1. Embedded Software Components..... | 3 |
| 3.2. DOCA Packages..... | 4 |
| 3.3. Supported Operating System Distributions..... | 4 |
| Chapter 4. Technical Support..... | 6 |
| Chapter 5. Known Issues..... | 7 |

Chapter 1. Introduction

DOCA 2.0.2 is the first DOCA version to support NVIDIA® BlueField®-3 DPU. It also natively supports BlueField-2 DPUs.

With the addition of a data-path acceleration (DPA) engine to BlueField-3, DOCA 2.0.2 supports FlexIO SDK and DPA SDK.

Chapter 2. New Features, Updates, and Enhancements

General

- ▶ Added DOCA support for BlueField-3 DPUs



DOCA version 2.0.2 supports both BlueField-3 and BlueField-2 DPUs.

- ▶ Added beta-level support for Data Path Accelerator (DPA) SDK
- ▶ Added support for IPsec library in the DOCA for ConnectX package
- ▶ Added new GPUNetIO DOCA library
- ▶ Added support for VirtIO full emulation with Live Migration on BlueField-3
- ▶ Added DOCA support for openEuler OS on the DPU Arm
- ▶ BlueField official OS is Ubuntu 22.04
- ▶ May 18, 2023 – BlueField-3 tuning update for power and performance
- ▶ June 20, 2023 – BlueField-3 tuning update for power and performance



Important: Make sure to deploy the latest installation files in your environment. Notice the updates to the packages listed under the "Installation Files" section in the [NVIDIA DOCA Installation Guide for Linux](#). Please see the versions of the updated DOCA software components under section [Embedded Software Components](#).

Services

- ▶ New DOCA UCC Service (NGC collection): DPU offload of collective communication to the DPU Arm cores



Contact your NVIDIA representative for details and access.

Enhancements

- ▶ Incorporated DOCA Samples into their respective programming guides

Chapter 3. Installation Notes

Refer to the [NVIDIA DOCA Installation Guide for Linux](#) for information on:

- ▶ Setting up NVIDIA DOCA SDK on your BlueField DPU
- ▶ Supported BlueField platforms

3.1. Embedded Software Components

| Component | Version |
|-----------------------|--------------------------------|
| BlueField-3 firmware | 32.37.1300 |
| BlueField-2 firmware | 24.37.1300 |
| ATF | v2.2(release):4.0.3-3-g886241c |
| UEFI | 4.0.3-1-g2162ecf |
| doca_apps | 2.0.2027-1 |
| doca_grpc | 2.0.2027-1 |
| doca_libs | 2.0.2027-1 |
| doca-base | 23.04-0.5.3.0 |
| MFT | 4.24.0-72 |
| MLNX_DPDK | 22.11.1.4.2 |
| SPDK | 23.01-6 |
| mlx-regex | 1.2-ubuntu1 |
| virtio-net-controller | 1.5.18-1 |
| collectx-clxapi | 1.13.2 |
| libvma | 9.8.20-1 |
| SNAP | 4.1.0 |
| mlnx-libsnap | 1.5.2-5 |
| flexio | 23.4.1494-0 |
| dpacc | 1.4.0 |
| ucx | 1.15.0-1.2304052 |
| GPUNetIO | 2.0.2027-1 |
| rxp-compiler | 23.04.1 |
| rxpbench | 23.04.0 |

| Component | Version |
|-----------|---------|
| Rivermax | 1.30.16 |

3.2. DOCA Packages

| Device | Component | Version | Description |
|------------------------------|---|---------|--|
| Host | DOCA SDK | 2.0.2 | Software development kit package for developing host software |
| | DOCA Runtime | 2.0.2 | Runtime libraries required to run DOCA-based software applications on host |
| | DOCA Tools | 2.0.2 | Tools for developers and administrators on host |
| | Arm emulated (QEMU) development container | 4.0.3 | Linux-based BlueField Arm emulated container for developers |
| Target BlueField-2 DPU (Arm) | BlueField BSP | 4.0.3 | BlueField image and firmware |
| | DOCA SDK | 2.0.2 | Software development kit packages for developing Arm software |
| | DOCA Runtime | 2.0.2 | Runtime libraries required to run DOCA-based software applications on Arm |
| | DOCA Tools | 2.0.2 | Tools for developers and administrators for Arm target |

3.3. Supported Operating System Distributions

The default operating system of the BlueField DPU (Arm) is Ubuntu 22.04.

The supported operating systems on the host machine are the following:



Note: Only the following generic kernel versions are supported for DOCA local repo package for host installation (whether by SDKM or manually).

| Host Operation System | Kernel Support | Arch Support |
|-----------------------|--|--------------|
| CentOS 7.6 | 4.14.0-115.el7a.aarch64 | aarch64 |
| | 3.10.0-957.el7.x86_64 | x86 |
| CentOS 8.0 | 4.18.0-80.el8.x86_64 | |
| CentOS 8.2 | 4.18.0-193.el8.x86_64 | |
| RHEL 7.6 | 3.10.0-957.el7.x86_64 | |
| RHEL 8.0 | 4.18.0-80.el8.x86_64 | |
| RHEL 8.2 | 4.18.0-193.el8.x86_64 | |
| Rocky 8.6 | 4.18.0-372.41.1.el8.x86_64 | |
| Ubuntu 18.04 | 4.15.0-20-generic | |
| Ubuntu 20.04 | 5.4.0-26-generic | |
| Ubuntu 22.04 | 5.15.0-52-generic | |
| Debian 10.8 | 4.19.0-14-amd64 | |
| Windows | DOCA support for Windows is on DOCA's future roadmap. For Windows driver support, refer to WinOF-2 Release Notes . | |

Chapter 4. Technical Support

Customers who purchased NVIDIA products directly from NVIDIA are invited to contact us through the following methods:

- ▶ E-mail: enterprisesupport@nvidia.com
- ▶ Enterprise Support page: <https://www.nvidia.com/en-us/support/enterprise>

Customers who purchased NVIDIA M-1 Global Support Services, please see your contract for details regarding Technical Support.

Customers who purchased NVIDIA products through an NVIDIA-approved reseller should first seek assistance through their reseller.

Chapter 5. Known Issues

The following table lists the known issues and limitations for this release of DOCA SDK.

| Reference | Description |
|-----------|---|
| 3444073 | Description: <code>mlxfwreset</code> is not supported in this release. |
| | Workaround: Power cycle the host. |
| | Keyword: <code>mlxfwreset</code> ; support |
| | Reported in version: 2.0.2 |
| 3448841 | Description: While running CentOS 8.2, <code>switchdev</code> Ethernet DPU runs in "shared" RDMA net namespace mode instead of "exclusive". |
| | Workaround: Use <code>ib_core</code> module parameter <code>netns_mode=0</code> . For example: <pre>echo "options ib_core netns_mode=0" >> /etc/modprobe.d/mlnx-bf.conf</pre> |
| | Keyword: RDMA; isolation; Net NS |
| | Reported in version: 2.0.2 |
| 3365363 | Description: On BlueField-3, when booting <code>virtio-net</code> emulation device using a GRUB2 bootloader, the bootloader may attempt to close and re-open the <code>virtio-net</code> device. This can result in unexpected behavior and possible system failure to boot. |
| | Workaround: N/A |
| | Keyword: BlueField-3; <code>virtio-net</code> ; UEFI |
| | Reported in version: 2.0.2 |
| 3232444 | Description: After live migration of <code>virtio-net</code> devices using the VFE driver, the <code>max_queues_size</code> output from the <code>virtnet list</code> may be wrong. This does not affect the actual value. |
| | Workaround: N/A |
| | Keyword: <code>Virtio-net</code> ; live migration |
| | Reported in version: 2.0.2 |
| 3454119 | Description: When retrieving <code>rdma_read</code> result, the <code>data_len</code> field of the destination buffers may be updated to an incorrect length. |
| | Workaround: To avoid the bug, when constructing the destination buffers, make sure the data segment end is aligned with the end of the buffer. To fix the issue after it has occurred, after the job is complete, reset the <code>data_len</code> of each of the destination buffers to its value before the job was submitted. |
| | Keyword: RDMA |
| | Reported in version: 2.0.2 |

| Reference | Description |
|-----------|---|
| 3259805 | Description: Following many power cycles on the BlueField DPU, the virtio-net controller may fail to start with the error <code>failed to register epoll</code> in the log. |
| | Workaround: Restart the controller service. |
| | Keyword: Virtio-net; power cycle; epoll |
| | Reported in version: 2.0.2 |
| 3448228 | Description: On virtio-net devices with LSO enabled, bogus packets may be captured on the SF representor when running heavy <code>iperf</code> traffic. |
| | Workaround: Disable TSO. |
| | Keyword: Virtio-net; iperf |
| | Reported in version: 2.0.2 |
| 3373849 | Description: Different OVS-based packages can include their own <code>systemd</code> services which prevents <code>/sbin/mlnx_bf_configure</code> from identifying the right one. |
| | Workaround: Use a specific service name in <code>/sbin/mlnx_bf_configure</code> . |
| | Keyword: OVS; systemd |
| | Reported in version: 2.0.2 |
| 2706803 | Description: When an NVMe controller, SoC management controller, and DMA controller are configured, the maximum number of VFs is limited to 124. |
| | Workaround: N/A |
| | Keyword: VF; limitation |
| | Reported in version: 2.0.2 |
| 3380260 | Description: Double encryption (running the script twice to encrypt without destroying in between) causes revert failures. |
| | Workaround: N/A |
| | Keyword: IPsec; east-west-overlay-encryption |
| | Reported in version: 2.0.2 |
| 3380586 | Description: Public key acceleration is not enabled on OpenEuler BFB due to missing configurations in the <code>openssl.cnf</code> file. |
| | Workaround: N/A |
| | Keyword: PKA; OpenSSL |
| | Reported in version: 2.0.2 |
| 3273435 | Description: Changing the mode of operation between NIC and DPU modes results in different capabilities for the host driver which might cause unexpected behavior. |
| | Workaround: Reload the host driver or reboot the host. |
| | Keyword: Modes of operation; driver |
| | Reported in version: 2.0.2 |
| 3440413 | Description: DOCA Graph does not work if the first (root) node is of user-data type. |
| | Workaround: N/A |
| | Keyword: Graph; core; failure |
| | Reported in version: 2.0.2 |

| Reference | Description |
|-----------|--|
| 3438222 | Description: On BlueField DPU running Rocky, openEuler or Centos8.2 with default huge page size not equal to 2M, rxbench fails to initialize as no mounted hugetlbfs is found for the 2M size. |
| | Workaround: N/A |
| | Keyword: rxbench |
| | Reported in version: 2.0.2 |
| 3438248 | Description: dev_rep API running on the host side sometimes returns DOCA_ERROR_INVALID_INPUT instead of DOCA_ERROR_NOT_SUPPORTED. |
| | Workaround: N/A |
| | Keyword: dev_rep; API; error |
| | Reported in version: 2.0.2 |
| 3377199 | Description: After installing OpenEuler 20.03sp1 BFB, the 2nd port may raise configured with legacy mode. |
| | Workaround: Reboot the DPU. |
| | Keyword: OpenEuler; legacy |
| | Reported in version: 2.0.2 |
| 3362822 | Description: Running the gRPC firewall application in interactive mode and trying to add and remove the same entry leads to a failure on the server side which severs the connection to the server. |
| | Workaround: N/A |
| | Keyword: gRPC; firewall; interactive; connection |
| | Reported in version: 2.0.2 |
| 3275690 | Description: To install DOCA on an Ubuntu 22.04 host, use the following command: <code>apt-get install doca-runtime doca-sdk doca-tools openvswitch-switch -y</code> |
| | Workaround: N/A |
| | Keyword: Installation; Ubuntu 22.04; OVS; openvswitch-switch |
| | Reported in version: 1.5.1 |
| 3274589 | Description: Comm channel fails to initiated in Rocky Linux. |
| | Workaround: N/A |
| | Keyword: Comm channel; Rocky |
| | Reported in version: 1.5.1 |
| 3264749 | Description: In Rocky and CentOS 8.2 inbox-kernel BFBs, RegEx requires the following extra huge page configuration for it to function properly: <code>sudo hugeadm --pool-pages-min DEFAULT:2048M</code> <code>sudo systemctl start mlx-regex.service</code> <code>systemctl status mlx-regex.service</code> If these commands have executed successfully you should see <code>active (running)</code> in the last line of the output. |
| | Workaround: N/A |
| | Keyword: RegEx; hugepages |
| | Reported in version: 1.5.1 |
| | |

| Reference | Description |
|-----------|--|
| 3240153 | Description: DOCA kernel support only works on a non-default kernel. |
| | Workaround: N/A |
| | Keyword: Kernel |
| | Reported in version: 1.5.0 |
| 3217627 | Description: The <code>doca_devinfo_rep_list_create</code> API returns success on the host instead of <code>Operation not supported</code> . |
| | Workaround: N/A |
| | Keyword: DOCA core; InfiniBand |
| | Reported in version: 1.5.0 |

Notice

This document is provided for information purposes only and shall not be regarded as a warranty of a certain functionality, condition, or quality of a product. NVIDIA Corporation nor any of its direct or indirect subsidiaries and affiliates (collectively: "NVIDIA") make no representations or warranties, expressed or implied, as to the accuracy or completeness of the information contained in this document and assume no responsibility for any errors contained herein. NVIDIA shall have no liability for the consequences or use of such information or for any infringement of patents or other rights of third parties that may result from its use. This document is not a commitment to develop, release, or deliver any Material (defined below), code, or functionality.

NVIDIA reserves the right to make corrections, modifications, enhancements, improvements, and any other changes to this document, at any time without notice.

Customer should obtain the latest relevant information before placing orders and should verify that such information is current and complete.

NVIDIA products are sold subject to the NVIDIA standard terms and conditions of sale supplied at the time of order acknowledgement, unless otherwise agreed in an individual sales agreement signed by authorized representatives of NVIDIA and customer ("Terms of Sale"). NVIDIA hereby expressly objects to applying any customer general terms and conditions with regards to the purchase of the NVIDIA product referenced in this document. No contractual obligations are formed either directly or indirectly by this document.

NVIDIA products are not designed, authorized, or warranted to be suitable for use in medical, military, aircraft, space, or life support equipment, nor in applications where failure or malfunction of the NVIDIA product can reasonably be expected to result in personal injury, death, or property or environmental damage. NVIDIA accepts no liability for inclusion and/or use of NVIDIA products in such equipment or applications and therefore such inclusion and/or use is at customer's own risk.

NVIDIA makes no representation or warranty that products based on this document will be suitable for any specified use. Testing of all parameters of each product is not necessarily performed by NVIDIA. It is customer's sole responsibility to evaluate and determine the applicability of any information contained in this document, ensure the product is suitable and fit for the application planned by customer, and perform the necessary testing for the application in order to avoid a default of the application or the product. Weaknesses in customer's product designs may affect the quality and reliability of the NVIDIA product and may result in additional or different conditions and/or requirements beyond those contained in this document. NVIDIA accepts no liability related to any default, damage, costs, or problem which may be based on or attributable to: (i) the use of the NVIDIA product in any manner that is contrary to this document or (ii) customer product designs.

No license, either expressed or implied, is granted under any NVIDIA patent right, copyright, or other NVIDIA intellectual property right under this document. Information published by NVIDIA regarding third-party products or services does not constitute a license from NVIDIA to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property rights of the third party, or a license from NVIDIA under the patents or other intellectual property rights of NVIDIA.

Reproduction of information in this document is permissible only if approved in advance by NVIDIA in writing, reproduced without alteration and in full compliance with all applicable export laws and regulations, and accompanied by all associated conditions, limitations, and notices.

THIS DOCUMENT AND ALL NVIDIA DESIGN SPECIFICATIONS, REFERENCE BOARDS, FILES, DRAWINGS, DIAGNOSTICS, LISTS, AND OTHER DOCUMENTS (TOGETHER AND SEPARATELY, "MATERIALS") ARE BEING PROVIDED "AS IS." NVIDIA MAKES NO WARRANTIES, EXPRESSED, IMPLIED, STATUTORY, OR OTHERWISE WITH RESPECT TO THE MATERIALS, AND EXPRESSLY DISCLAIMS ALL IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE. TO THE EXTENT NOT PROHIBITED BY LAW, IN NO EVENT WILL NVIDIA BE LIABLE FOR ANY DAMAGES, INCLUDING WITHOUT LIMITATION ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, PUNITIVE, OR CONSEQUENTIAL DAMAGES, HOWEVER CAUSED AND REGARDLESS OF THE THEORY OF LIABILITY, ARISING OUT OF ANY USE OF THIS DOCUMENT, EVEN IF NVIDIA HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. Notwithstanding any damages that customer might incur for any reason whatsoever, NVIDIA's aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms of Sale for the product.

Trademarks

NVIDIA, the NVIDIA logo, and Mellanox are trademarks and/or registered trademarks of Mellanox Technologies Ltd. and/or NVIDIA Corporation in the U.S. and in other countries. The registered trademark Linux® is used pursuant to a sublicense from the Linux Foundation, the exclusive licensee of Linus Torvalds, owner of the mark on a world-wide basis. Other company and product names may be trademarks of the respective companies with which they are associated.

Copyright

© 2023 NVIDIA Corporation & affiliates. All rights reserved.