



## **Bug Fixes in This Version**

Below are the bugs fixed in this version. For a list of fixes previous version, see [Bug Fixes History](#).

Internal Reference Number	Description
3729466	<b>Description:</b> Resolved a discalculation issue where more Q-counters were freed than allocated when moving to switchdev mode.
	<b>Keywords:</b> Q-counters, switchdev
	<b>Discovered in Release:</b> 23.10-1.1.9.0
	<b>Fixed in Release:</b> 23.10-2.1.3.1
3727822	<b>Description:</b> Fixed an issue that allowed concurrent creation of encap entries, and could potentially cause double free vulnerabilities.
	<b>Keywords:</b> encap entries, double free
	<b>Discovered in Release:</b> 23.10-1.1.9.0
	<b>Fixed in Release:</b> 23.10-2.1.3.1
3728381	<b>Description:</b> Fixed an issue that exposed debugfs entries for non supported RoCE general parameters, such as rtt_resp_dscp.
	<b>Keywords:</b> debugfs, RoCE
	<b>Discovered in Release:</b> 23.10-1.1.9.0
	<b>Fixed in Release:</b> 23.10-2.1.3.1
3710957	<b>Description:</b> Fixed an issue that triggered an error message by updating the rule actions STE apply flow. Following the update, the flow checks if the rule domain is different from the ASO CT action domain when applying the ASO CT action.
	<b>Keywords:</b> Software Steering
	<b>Discovered in Release:</b> 23.10-1.1.9.0
	<b>Fixed in Release:</b> 23.10-2.1.3.1