



Bug Fixes History

Ref #	Issue Description
38 36	Description: BIOS attribute in Redfish schema "SPCR UART" does not comply with expected format.
59	Keyword: Redfish; BIOS
8	Fixed in version: 4.9.0
40 35	Description: When eMMC is stuck, Linux tries to recover it including resetting the eMMC itself and re-initializing it.
18	Keyword: eMMC stuck
7	Fixed in version: 4.9.0
38 94 90	Description: eMMC clock toggling loop is observed after boot is completed.
7	Keyword: eMMC; GPIO; toggling
7	Fixed in version: 4.8.0
38 63	Description: Restarting openibd results in kernel panic after modifying kernel IPsec configurations.
01	Keyword: IPsec
1	Fixed in version: 4.8.0
38 78 45 8	Description: <code>/usr/lib/udev/rules.d/80-ifupdown.rules</code> runs <code>/lib/udev/ifupdown-hotplug</code> which uses ifquery for all newly created interfaces. This dramatically slows down SF interfaces creation.
8	Keyword: Subfunction
	Fixed in version: 4.8.0
39 01 51	Description: Failure to verify measurements when UEFI secure boot is enabled.
1	Keyword: UEFI Secure Boot
1	Fixed in version: 4.8.0
38 75 39 4	Description: After the BFB installation, the root partition UUID in <code>/etc/fstab</code> does not match current partition UUID. As a result root partition is mounted as read-only:
	<code>/dev/nvme0n1p2 on / type xfs (ro,relatime,attr2,inode64,logbufs=8,logbsize=32k,noquota)</code>

Ref #	Issue Description
	Keyword: Read-only; OL; UUID
	Fixed in version: 4.8.0
38 81 94 1	Description: When working with RShim 2.0.28, PCIe host crash may rarely occur at the beginning of BFB push after the Arm reset.
	Keyword: RShim; driver
	Fixed in version: 4.8.0
38 86 31 5	Description: To reset or shut down the BlueField Arm, it is mandatory to specify the <code>--sync 0</code> argument. For example:
	<pre>mlxfwreset -d <device> -l 1 -t 4 --sync 0 r</pre>
	Keyword: Arm; shutdown
	Fixed in version: 4.8.0
39 56 21 0	Description: BMC version change using BFB installation can fail if the previous BMC version change process did not finish.
	Keyword: BMC
	Fixed in version: 4.8.0
39 50 11 4	Description: QP number can go beyond 0xFFFF. Change datatype to uint32_t to hold entire value.
	Keyword: Virtnet
	Fixed in version: 4.8.0
39 80 84 2	Description: Openibd queries deprecated parameter <code>ECPF_ESWITCH_MANAGER</code> until the query times out.
	Keyword: Service; openibd
	Fixed in version: 4.8.0
39 48 00 9	Description: The command <code>bfcfg -d</code> may show an incorrect OOB MAC address.
	Keywords: OOB; MAC
	Fixed in version: 4.8.0

Ref #	Issue Description
38 14	Description: Kubernetes official repository changed location and it causes apt/yum failures on BlueField OSes older than BSP 4.7.0 (DOCA 2.7.0).
52 6	Keywords: Kubernetes; OS
	Fixed in version: 4.7.0
38 14	Description: The location of the official Kubernetes repository changed, causing apt/yum failures.
52 6	Keywords: Kubernetes
	Fixed in version: 4.7.0
38 20 66	Description: Virtio-net may see TX timeout on specific queues.
1	Keywords: Emulated devices
	Fixed in version: 4.7.0
38 50 45	Description: BMC components update fails while using default BMC root password.
9	Keywords: BMC; update
	Fixed in version: 4.7.0
37 74	Description: When enrolling a certificate to the UEFI DB, the failure message " <code>ERROR: Unsupported file type!</code> " is displayed when the DB was full.
08 8	Keywords: SNAP; UEFI; error
	Fixed in version: 4.7.0
37 87	Description: Host PCIe driver hangs when hot plugging a device due to SF creation and error flow handling failure.
00 3	Keywords: Subfunction; hot-plug
	Fixed in version: 4.7.0
36 63 39	Description: On rare occasions, OP-TEE may panic upon boot.
8	Keywords: fTPM over OP-TEE
	Fixed in version: 4.7.0
36 77 36 6	Description: On rare occasions, the devices <code>/dev/tpm0</code> and <code>/dev/tpmrm0</code> are not created triggering an fTPM panic during boot. This message indicates that the fTPM over OP-TEE feature is not functional.
	Keywords: fTPM over OP-TEE

Ref #	Issue Description
	Fixed in version: 4.7.0
37 12 91 6	<p>Description: The following fTPM over OP-TEE error appears when booting BlueField:</p> <pre>ftpm-tee PRP0001:01: ftpm_tee_probe: tee_client_open_session failed, err=ffff3024</pre>
	Keywords: fTPM over OP-TEE
	Fixed in version: 4.7.0
38 30 03 4	<p>Description: The following bfscripts have been deprecated and may no longer work as expected: bfinst, bfdracut, bfacpievt. These scripts are no longer supported and will eventually be removed. Warning logs have been added to notify users.</p>
	Keywords: Deprecated bfscripts
	Fixed in version: 4.7.0
36 18 93 6	<p>Description: When moving to DPU mode from NIC mode, it is necessary to reinstall the BFB and perform a graceful reboot to the DPU by shutting down the Arm cores before rebooting the host system.</p>
	Keywords: NIC mode
	Fixed in version: 4.7.0
36 03 14 6	<p>Description: Running <code>mlxfwreset</code> on BlueField-3 may cause the external host to crash when the RShim driver is running on that host.</p>
	Keywords: RShim; mlxfwreset
	Fixed in version: 4.7.0
34 44 07 3	<p>Description: <code>mlxfwreset</code> is not supported in this release.</p>
	Keywords: mlxfwreset; support
	Fixed in version: 4.7.0
36 60 46 0	<p>Description: Ubuntu kernel 5.15.0-88-generic backports a bug from the upstream kernel which results in virtio-net full emulation not functioning.</p>
	Keywords: Kernel
	Fixed in version: 4.6.0

Ref #	Issue Description
36 95 36 7	<p>Description: For BlueField-2, although an option to configure "large ICM size" appears in the UEFI menu it is not functional as large ICM size is not supported on it.</p> <p>Keywords: UEFI</p> <p>Fixed in version: 4.6.0</p>
35 71 28 5	<p>Description: Intermittent UEFI/grub exception after many power-cycles:</p> <pre> Call Stack: Synchronous Exception at 0xF4B72E0C ERR[UEFI]: PC=0xF4B72E0C ERR[UEFI]: PC=0xF4B72E70 ERR[UEFI]: PC=0xF4B73570 ERR[UEFI]: PC=0xF4B74904 ERR[UEFI]: PC=0xF4F04444 ERR[UEFI]: PC=0xF4F044F8 ERR[UEFI]: PC=0xF4F05160 ERR[UEFI]: PC=0xF4F02030 ERR[UEFI]: PC=0xFDFC3A38 (0xFDFB0000+0x13A38) [1] DxeCore.dll ERR[UEFI]: PC=0xF56E3594 (0xF56D4000+0xF594) [2] BdsDxe.dll ERR[UEFI]: PC=0xF56F1FFC (0xF56D4000+0x1DFFC) [2] BdsDxe.dll ERR[UEFI]: PC=0xF56F40D4 (0xF56D4000+0x200D4) [2] BdsDxe.dll ERR[UEFI]: PC=0xFDFC6E50 (0xFDFB0000+0x16E50) [3] DxeCore.dll ERR[UEFI]: PC=0x880092E0 ERR[UEFI]: PC=0x8800947C ERR[UEFI]: X0=0x0 X1=0xF4B78FC3 X2=0xE X3=0x0 ERR[UEFI]: X4=0x0 X5=0xFFFFFFFFFFFFFFFF8 X6=0x0 X7=0xFFFFFFFFF5 ERR[UEFI]: X8=0xF4B79480 X9=0x2 X10=0xFFFFFFFFFFFFFFFF X11=0xFFFFDC00 </pre>

Ref #	Issue Description
	Keyword: Security
	Fixed in version: 4.5.0
35 99 83 9	Description: On a reboot following BFB install, the error message "Boot Image update completed, Status: Volume Corrupt" is observed. The error is non-functional and may be safely ignored.
	Keyword: Software provisioning; EFI capsule update; eMMC boot partitions
	Fixed in version: 4.5.0
35 56 79 5	Description: The first uplink representor interface may not be renamed to <code>p0</code> from <code>ethX</code> .
	Keyword: Representors
	Fixed in version: 4.5.0
36 29 87 5	Description: Fixed base address of static ICM.
	Keyword: ICM
	Fixed in version: 4.5.0
33 65 36 3	Description: On BlueField-3, when booting virtio-net emulation device using a GRUB2 bootloader, the bootloader may attempt to close and re-open the virtio-net device. This can result in unexpected behavior and possible system failure to boot.
	Keywords: BlueField-3; virtio-net; UEFI
	Fixed in version: 4.5.0
33 73 84 9	Description: Different OVS-based packages can include their own systemd services which prevents <code>/sbin/mlnx_bf_configure</code> from identifying the right one.
	Keywords: OVS; systemd
	Fixed in version: 4.5.0
36 05 33 2	Description: A dmseg is printed due to the OVS bridge interface being configured DOWN by default.
	Keyword: OVS
	Fixed in version: 4.2.1
34 79	Description: For non-LSO data, a max chain of 4 descriptors is posted onto the send queue resulting in a partial packet going out on the wire.

Ref #	Issue Description
040	<p>Keyword: Send; LSO</p> <p>Fixed in version: 4.2.1</p>
3549785	<p>Description: NVMe and mlx5_core drivers fail during BFB installation. As a result, Anolis OS cannot be installed on the SSD and the <code>mlxfwreset</code> command does not work during Anolis BFB installation.</p> <p>Keyword: Linux; NVMe; BFB installation</p> <p>Fixed in version: 4.2.1</p>
3393316	<p>Description: When LSO is enabled, if the header and data appear in the same fragment, the following warning is given from tcpdump:</p> <pre>truncated-ip - 9 bytes missing</pre> <p>Keyword: Virtio-net; large send offload</p> <p>Fixed in version: 4.2.1</p>
3554128	<p>Description: "<code>dmidecode</code>" output does not match "<code>ipmitool fru print</code>" output.</p> <p>Keywords: IPMI; print</p> <p>Fixed in version: 4.2.1</p>
3508018	<p>Description: Failure to ssh to Arm via 1GbE OOB interface is experienced after performing warm reboot on the DPU.</p> <p>Keywords: SSH; reboot</p> <p>Fixed in version: 4.2.0</p>
3451539	<p>Description: BSP build number (fourth digit in version number) does not appear in UEFI menu.</p> <p>Keywords: UEFI; software</p> <p>Fixed in version: 4.2.0</p>
3259805	<p>Description: Following many power cycles on the BlueField DPU, the virtio-net controller may fail to start with the error <code>failed to register epoll</code> in the log.</p> <p>Keywords: Virtio-net; power cycle; epoll</p>

Ref #	Issue Description
	Fixed in version: 4.2.0
32	Description: Enabled reset on MMC to enhance recovery on error.
66	Keywords: MMC; reset
18	
0	Fixed in version: 4.2.0
34	Description: The PKA engine is not working on CentOS 7.6 due to multiple OpenSSL versions (1.0.2k 1.1.1k) being installed and the library loader not selecting the correct version of the openssl library.
48	
21	Keywords: PKA; OpenSSL
7	Fixed in version: 4.2.0
34	Description: On virtio-net devices with LSO (large send offload) enabled, bogus packets may be captured on the SF representor when running heavy <code>iperf</code> traffic.
48	
22	Keywords: Virtio-net; iperf
8	Fixed in version: 4.2.0
34	Description: OpenSSL is not working with PKA engine on CentOS 7.6 with 4.23 5.4 5.10 kernels due to multiple versions of OpenSSL(1.0.2k and 1.1.1k) are installed.
52	
58	Keywords: OpenSSL; PKA
3	Fixed in version: 4.2.0
34	Description: 699140280000 OPN is not supported.
55	
87	Keywords: SKU; support
3	Fixed in version: 4.2.0
35	Description: Populate the vGIC maintenance interrupt number in MADT to avoid harmless.
19	
34	Keywords: Error
1	Fixed in version: 4.2.0
35	Description: The timer frequency is measured using the c0 fmon feature causing new kernels to complain if CNTFRQ_ELO has a different value on different cores.
22	
65	Keywords: Timer frequency
2	Fixed in version: 4.2.0

Ref #	Issue Description
35 31 96 5	Description: Memory info displayed via <code>dmidecode</code> is not correct for memory sizes 32G and above. Keywords: Memory; dmidecode Fixed in version: 4.2.0
33 62 18 1	Description: A customized BFB with an older kernel does not support bond speed above 200Gb/s. Keywords: Bond; LAG; speed Fixed in version: 4.2.0
31 77 56 9	Description: DCBX configuration may not take effect. Keywords: DCBX; QoS; Ildpad Fixed in version: 4.2.0
28 24 85 9	Description: Hotplug/unplug of virtio-net devices during host shutdown/bootup may result in failure to do plug/unplug. Keywords: Virtio-net, hotplug Fixed in version: 4.2.0
32 52 08 3	Description: Assert errors may be observed in the RShim log after reset/reboot. These errors are harmless and may be ignored. Keywords: RShim; log; error Fixed in version: 4.0.3
32 40 06 0	Description: Hotplug of a modern virtio-net device is not supported when <code>VIRTIO_EMULATION_HOTPLUG_TRANS</code> is <code>TRUE</code> from mlxconfig. Keywords: Virtio-net; hotplug; legacy Fixed in version: 4.0.3
32 40 18 2	Description: Virtio-net full emulation is not supported in CentOS 8.2 with inbox-kernel 4.18.0-193.el8.aarch64. Keywords: Virtio-net; CentOS Fixed in version: 4.0.3
31 51	Description: If secure boot is enabled, the following error message is observed while installing Ubuntu on the DPU:

Ref #	Issue Description
884	<p><code>ERROR: need to use capsule in secure boot mode</code>. This message is harmless and may be safely ignored.</p> <p>Keywords: Error message; installation</p> <p>Fixed in version: 3.9.3</p>
2793005	<p>Description: When Arm reboots or crashes after sending a virtio-net unplug request, the hotplugged devices may still be present after Arm recovers. The host, however, will not see those devices.</p> <p>Keywords: Virtio-net; hotplug</p> <p>Fixed in version: 3.9.3</p>
3107227	<p>Description: BlueField with secured BFB fails to boot up if the <code>PART_SCHEME</code> field is set in <code>bf.cfg</code> during installation.</p> <p>Keywords: Installation; bf.cfg</p> <p>Fixed in version: 3.9.2</p>
3109270	<p>Description: If the RShim service is running on an external host over the PCIe interface then, in very rare cases, a soft reset of the BlueField can cause a poisoned completion to be returned to the host. The host may treat this as a fatal error and crash.</p> <p>Keywords: RShim; ATF</p> <p>Fixed in version: 3.9.2</p>
2790928	<p>Description: Virtio-net-controller recovery may not work for a hot-plugged device because the system assigns a BDF (string identifier) of 0 for the hot-plugged device, which is an invalid value.</p> <p>Keywords: Virtio-net; hotplug; recovery</p> <p>Fixed in version: 3.9.0</p>
2780819	<p>Description: Eye-opening is not supported on 25GbE integrated-BMC BlueField-2 DPU.</p> <p>Keywords: Firmware, eye-opening</p> <p>Fixed in version: 3.9.0</p>

Ref #	Issue Description
2876447	<p>Description: Virtio full emulation is not supported by NVIDIA® BlueField®-2 multi-host cards.</p> <p>Keywords: Virtio full emulation; multi-host</p> <p>Fixed in version: 3.9.0</p>
2855485	<p>Description: After BFB installation, Linux crash may occur with <code>efi_call_rts</code> messages in the call trace which can be seen from the UART console.</p> <p>Keywords: Linux crash; <code>efi_call_rts</code></p> <p>Fixed in version: 3.9.0</p>
2901514	<p>Description: Relaxed ordering is not working properly on virtual functions.</p> <p>Keywords: MLNX_OFED; relaxed ordering; VF</p> <p>Fixed in version: 3.9.0</p>
2852086	<p>Description: On rare occasions, the UEFI variables in UVPS EEPROM are wiped out which hangs the boot process at the UEFI menu.</p> <p>Keywords: UEFI; hang</p> <p>Fixed in version: 3.9.0</p>
2934828	<p>Description: PCIe device address to RDMA device name mapping on x86 host may change after the driver restarts in Arm.</p> <p>Keywords: RDMA; Arm; driver</p> <p>Fixed in version: 3.9.0</p>
-	<p>Description: RShim driver does not work when the host is in secure boot mode.</p> <p>Keywords: RShim; Secure Boot</p> <p>Fixed in version: 3.9.0</p>
2787308	<p>Description: At rare occasions during Arm reset on BMC-integrated DPUs, the DPU will send "PCIe Completion" marked as poisoned. Some servers treat that as fatal and may hang.</p> <p>Keywords: Arm reset; BMC integrated</p> <p>Fixed in version: 3.9.0</p>
2585	<p>Description: Pushing the BFB image fails occasionally with a "bad magic number" error message showing up in the console.</p>

Ref #	Issue Description
607	Keywords: BFB push; installation Fixed in version: 3.9.0
2802943	Description: SLD detection may not function properly. Keywords: Firmware Fixed in version: 3.9.0
2580945	Description: External host reboot may also reboot the Arm cores if the DPU was configured using mlxconfig. Keywords: Non-volatile configuration; Arm; reboot Fixed in version: 3.9.0
2899740	Description: BlueField-2 may sometimes go to PXE boot instead of Linux after installation. Keywords: Installation; PXE Fixed in version: 3.8.5
2870143	Description: Some DPUs may get stuck at GRUB menu when booting due to the GRUB configuration getting corrupted when board is powered down before the configuration is synced to memory. Keywords: GRUB; memory Fixed in version: 3.8.5
2873700	Description: The available RShim logging buffer may not have enough space to hold the whole register dump which may cause buffer wraparound. Keywords: RShim; logging Fixed in version: 3.8.5
2801891	Description: IPMI EMU service reports cable link as down when it is actually up. Keywords: IPMI EMU Fixed in version: 3.8.0
2779861	Description: Virtio-net controller does not work with devices other than <code>mlx5_0/1</code> . Keywords: Virtio-net controller Fixed in version: 3.8.0

Ref #	Issue Description
2801378	Description: No parameter validation is done for feature bits when performing hotplug. Keywords: Virtio-net; hotplug Fixed in version: 3.8.0
2802917	Description: When secure boot is enabled, PXE boot may not work. Keywords: Secure boot; PXE Fixed in version: 3.8.0
2827413	Description: Updating a BFB could fail due to congestion. Keywords: Installation; congestion Fixed in version: 3.8.0
2829876	Description: For virtio-net device, modifying the number of queues does not update the number of MSIX. Keywords: Virtio-net; queues Fixed in version: 3.8.0
2597790	Description: A "double free" error is seen when using the "curl" utility. This happens only when OpenSSL is configured to use a dynamic engine (e.g. Bluefield PKA engine). Keywords: OpenSSL; curl Fixed in version: 3.8.0
2853295	Description: UEFI secure boot enables the kernel lockdown feature which blocks access by mstmcr. Keywords: Secure boot Fixed in version: 3.8.0
2854472	Description: Virtio-net controller may fail to start after power cycle. Keywords: Virtio-net controller Fixed in version: 3.8.0
2854995	Description: Memory consumed for a representor exceeds what is necessary making scaling to 504 SF's not possible. Keywords: Memory

Ref #	Issue Description
	Fixed in version: 3.8.0
28	Description: Modifying VF bits yields an error.
56	Keywords: Virtio-net controller
65	
2	Fixed in version: 3.8.0
28	Description: Arm hangs when user is thrown to livefish by FW (e.g. secure boot).
59	Keywords: Arm; livefish
06	
6	Fixed in version: 3.8.0
28	Description: The current installation flow requires multiple resets after booting the self-install BFB due to the watchdog being armed after capsule update.
66	
08	Keywords: Reset; installation
2	Fixed in version: 3.8.0
28	Description: Power-off of BlueField shows up as a panic which is then stored in the RShim log and carried into the BERT table in the next boot which is misleading to the user.
66	
53	Keywords: RShim; log; panic
7	Fixed in version: 3.8.0
28	Description: Various errors related to the UPVS store running out of space are observed.
68	
94	Keywords: UPVS; errors
4	Fixed in version: 3.8.0
27	Description: <code>oob_net0</code> cannot receive traffic after a network restart.
54	
79	Keywords: <code>oob_net0</code>
8	Fixed in version: 3.8.0
26	Description: Up to 31 hot-plugged virtio-net devices are supported even if <code>PCI_SWITCH_EMULATION_NUM_PORT=32</code> . Host may hang if it hot plugs 32 devices.
91	
17	Keywords: Virtio-net; hotplug
5	Fixed in version: 3.8.0

Ref #	Issue Description
25 97 97 3	<p>Description: Working with CentOS 7.6, if SF network interfaces are statically configured, the following parameters should be set.</p> <pre>NM_CONTROLLED="no" DEVTIMEOUT=30</pre> <p>For example:</p> <pre># cat /etc/sysconfig/network-scripts/ifcfg-p0m0 NAME=p0m0 DEVICE=p0m0 NM_CONTROLLED="no" PEERDNS="yes" ONBOOT="yes" BOOTPROTO="static" IPADDR=12.212.10.29 BROADCAST=12.212.255.255 NETMASK=255.255.0.0 NETWORK=12.212.0.0 TYPE=Ethernet DEVTIMEOUT=30</pre> <p>Keywords: CentOS; subfunctions; static configuration</p> <p>Fixed in version: 3.7.0</p>
25 81 53 4	<p>Description: When shared RQ mode is enabled and offloads are disabled, running multiple UDP connections from multiple interfaces can lead to packet drops.</p> <p>Keywords: Offload; shared RQ</p> <p>Fixed in version: 3.7.0</p>
25 81 62 1	<p>Description: When OVS-DPDK and LAG are configured, the kernel driver drops the LACP packet when working in shared RQ mode.</p> <p>Keywords: OVS-DPDK; LAG; LACP; shared RQ</p> <p>Fixed in version: 3.7.0</p>
26 01	<p>Description: The gpio-mlxbf2 and mlxbf-gige drivers are not supported on 4.14 kernel.</p>

Ref #	Issue Description
094	Keywords: Drivers; kernel
	Fixed in version: 3.7.0
2584	Description: Virtio-net-controller does not function properly after changing uplink representor MTU.
427	Keywords: Virtio-net controller; MTU
	Fixed in version: 3.7.0
243839	Description: VXLAN with IPsec crypto offload does not work.
2	Keywords: VXLAN; IPsec crypto
	Fixed in version: 3.7.0
2406	Description: Address Translation Services is not supported in BlueField-2 step A1 devices. Enabling ATS can cause server hang.
401	Keywords: ATS
	Fixed in version: 3.7.0
2402	Description: PHYless reset on BlueField-2 devices may cause the device to disappear.
531	Keywords: PHY; firmware reset
	Fixed in version: 3.7.0
240038	Description: When working with strongSwan 5.9.0bf, running <code>ip xfrm state show</code> returns partial information as to the offload parameters, not showing " <code>mode full</code> ".
1	Keywords: strongSwan; ip xfrm; IPsec
	Fixed in version: 3.7.0
2392604	Description: Server crashes after configuring PCI_SWITCH_EMULATION_NUM_PORT to a value higher than the number of PCIe lanes the server supports.
	Keywords: Server; hang
	Fixed in version: 3.7.0

Ref #	Issue Description
22 93	Description: Loading/reloading NVMe after enabling VirtIO fails with a PCI bar memory mapping error.
79	Keywords: VirtIO; NVMe
1	Fixed in version: 3.7.0
22 45	Description: When working with OVS in the kernel and using Connection Tracking, up to 500,000 flows may be offloaded.
98	Keywords: DPU; Connection Tracking
3	Fixed in version: 3.7.0
19 45	Description: If the Linux OS running on the host connected to the BlueField DPU has a kernel version lower than 4.14, MLNX_OFED package should be installed on the host.
51	Keywords: Host OS
3	Fixed in version: 3.7.0
19	Description: During heavy traffic, ARP reply from the other tunnel endpoint may be dropped. If no ARP entry exists when flows are offloaded, they remain stuck on the slow path.
00	Workaround: Set a static ARP entry at the BlueField Arm to VXLAN tunnel endpoints.
20	Keywords: ARP; Static; VXLAN; Tunnel; Endpoint
3	Fixed in version: 3.7.0
20 82	Description: During boot, the system enters systemctl emergency mode due a corrupt root file system.
98	Keywords: Boot
5	Fixed in version: 3.6.0.11699
22 78	Description: Creating a bond via NetworkManager and restarting the driver (openibd restart) results in no pf0hpf and bond creation failure.
83	Keywords: Bond; LAG; network manager; driver reload
3	Fixed in version: 3.6.0.11699

Ref #	Issue Description
22	Description: Only up to 62 host virtual functions are currently supported.
86	Keywords: DPU; SR-IOV
59	
6	Fixed in version: 3.6.0.11699
23	Description: Before changing SR-IOV mode or reloading the mlx5 drivers on IPsec-enabled systems, make sure all IPsec configurations are cleared by issuing the command <code>ip x s f && ip x p f</code> .
97	
93	Keywords: IPsec; SR-IOV; driver
2	Fixed in version: 3.6.0.11699
24	Description: In Ubuntu, during or after a reboot of the Arm, manually, or as part of a firmware reset, the network devices may not transition to switchdev mode. No device representors would be created (pf0hpf, pf1hpf, etc). Driver loading on the host will timeout after 120 seconds.
05	
03	Keywords: Ubuntu; reboot; representors; switchdev
9	Fixed in version: 3.6.0.11699
24	Description: EEPROM storage for UEFI variables may run out of space and cause various issues such as an inability to push new BFB (due to timeout) or exception when trying to enter UEFI boot menu.
03	
01	Keywords: BFB install; timeout; EEPROM UEFI Variable; UVPS
9	Fixed in version: 3.6.0.11699
24	Description: When using OpenSSL on BlueField platforms where Crypto support is disabled, the following errors may be encountered:
58	<code>PKA_ENGINE: PKA instance is invalid</code>
04	<code>PKA_ENGINE: failed to retrieve valid instance</code> This happens due to
0	OpenSSL configuration being linked to use PKA hardware, but that hardware is not available since crypto support is disabled on these platforms.
	Keywords: PKA; Crypto
	Fixed in version: 3.6.0.11699
24	Description: All NVMe emulation counters (Ctrl, SQ, Namespace) return "0" when queried.
56	
94	Keywords: Emulated devices; NVMe
7	Fixed in version: 3.6.0.11699

Ref #	Issue Description
2411542	<p>Description: Multi-APP QoS is not supported when LAG is configured.</p> <p>Keywords: Multi-APP QoS; LAG</p> <p>Fixed in version: 3.6.0.11699</p>
2394130	<p>Description: When creating a large number of VirtIO VFs, hung task call traces may be seen in the dmesg.</p> <p>Keywords: VirtIO; call traces; hang</p> <p>Fixed in version: 3.5.1.11601</p>
2398050	<p>Description: Only up to 60 virtio-net emulated virtual functions are supported if LAG is enabled.</p> <p>Keywords: Virtio-net; LAG</p> <p>Fixed in version: 3.5.1.11601</p>
2256134	<p>Description: On rare occasions, rebooting the BlueField DPU may result in traffic failure from the x86 host.</p> <p>Keywords: Host; Arm</p> <p>Fixed in version: 3.5.1.11601</p>
2400121	<p>Description: When emulated PCIe switch is enabled, and more than 8 PFs are enabled, the BIOS boot process might halt.</p> <p>Keywords: Emulated PCIe switch</p> <p>Fixed in version: 3.5.0.11563</p>
2082985	<p>Description: During boot, the system enters systemctl emergency mode due a corrupt root file system.</p> <p>Keywords: Boot</p> <p>Fixed in version: 3.5.0.11563</p>
2249187	<p>Description: With the OCP card connecting to multiple hosts, one of the hosts could have the RShim PF exposed and probed by the RShim driver.</p> <p>Keywords: RShim; multi-host</p> <p>Fixed in version: 3.5.0.11563</p>
2363	<p>Description: When moving to separate mode on the DPU, the OVS bridge remains and no ping is transmitted between the Arm cores and the remote server.</p> <p>Keywords: SmartNIC; operation modes</p>

Ref #	Issue Description
650	Fixed in version: 3.5.0.11563
2394	Description: Pushing the BFB image v3.5 with a WinOF-2 version older than 2.60 can cause a crash on the host side.
226	Keywords: Windows; RShim
6	Fixed in version: 3.5.0.11563

Notice
This document is provided for information purposes only and shall not be regarded as a warranty of a certain functionality, condition, or quality of a product. NVIDIA Corporation (“NVIDIA”) makes no representations or warranties, expressed or implied, as to the accuracy or completeness of the information contained in this document and assumes no responsibility for any errors contained herein. NVIDIA shall have no liability for the consequences or use of such information or for any infringement of patents or other rights of third parties that may result from its use. This document is not a commitment to develop, release, or deliver any Material (defined below), code, or functionality.
NVIDIA reserves the right to make corrections, modifications, enhancements, improvements, and any other changes to this document, at any time without notice.
Customer should obtain the latest relevant information before placing orders and should verify that such information is current and complete.
NVIDIA products are sold subject to the NVIDIA standard terms and conditions of sale supplied at the time of order acknowledgement, unless otherwise agreed in an individual sales agreement signed by authorized representatives of NVIDIA and customer (“Terms of Sale”). NVIDIA hereby expressly objects to applying any customer general terms and conditions with regards to the purchase of the NVIDIA product referenced in this document. No contractual obligations are formed either directly or indirectly by this document.
NVIDIA products are not designed, authorized, or warranted to be suitable for use in medical, military, aircraft, space, or life support equipment, nor in applications where failure or malfunction of the NVIDIA product can reasonably be expected to result in personal injury, death, or property or environmental damage. NVIDIA accepts no liability for inclusion and/or use of NVIDIA products in such equipment or applications and therefore such inclusion and/or use is at customer’s own risk.
NVIDIA makes no representation or warranty that products based on this document will be suitable for any specified use. Testing of all parameters of each product is not necessarily performed by NVIDIA. It is customer’s sole responsibility to evaluate and determine the applicability of any information contained in this document, ensure the product is suitable and fit for the application planned by customer, and perform the necessary testing for the application in order to avoid a default of the application or the product. Weaknesses in customer’s product designs may affect the quality and reliability of the NVIDIA product and may result in additional or different conditions and/or requirements beyond those contained in this document. NVIDIA accepts no liability related to any default, damage, costs, or problem which may be based on or attributable to: (i) the use of the NVIDIA product in any manner that is contrary to this document or (ii) customer product designs.
No license, either expressed or implied, is granted under any NVIDIA patent right, copyright, or other NVIDIA intellectual property right under this document. Information published by NVIDIA regarding third-party products or services does not constitute a license from NVIDIA to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property rights of the third party, or a license from NVIDIA under the patents or other intellectual property rights of NVIDIA.
Reproduction of information in this document is permissible only if approved in advance by NVIDIA in writing, reproduced without alteration and in full compliance with all applicable export laws and regulations, and accompanied by all associated conditions, limitations, and notices.
THIS DOCUMENT AND ALL NVIDIA DESIGN SPECIFICATIONS, REFERENCE BOARDS, FILES, DRAWINGS, DIAGNOSTICS, LISTS, AND OTHER DOCUMENTS (TOGETHER AND SEPARATELY, “MATERIALS”) ARE BEING PROVIDED “AS IS.” NVIDIA MAKES NO WARRANTIES, EXPRESSED, IMPLIED, STATUTORY, OR OTHERWISE WITH RESPECT TO THE MATERIALS, AND EXPRESSLY DISCLAIMS ALL IMPLIED WARRANTIES OF NONINFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE. TO THE EXTENT NOT PROHIBITED BY LAW, IN NO EVENT WILL NVIDIA BE LIABLE FOR ANY DAMAGES, INCLUDING WITHOUT LIMITATION ANY DIRECT, INDIRECT, SPECIAL, INCIDENTAL, PUNITIVE, OR CONSEQUENTIAL DAMAGES, HOWEVER CAUSED AND REGARDLESS OF THE THEORY OF LIABILITY, ARISING OUT OF ANY USE OF THIS DOCUMENT, EVEN IF NVIDIA HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES. Notwithstanding any damages that customer might incur for any reason whatsoever, NVIDIA’s aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms of Sale for the product.
Trademarks
NVIDIA and the NVIDIA logo are

trademarks and/or registered trademarks of NVIDIA Corporation in the U.S. and other countries. Other company and product names may be trademarks of the respective companies with which they are associated.

Copyright 2025. PDF Generated on 03/09/2025