Bug Fixes In This Version

Ref #	Issue Description
3894907	Description: eMMC clock toggling loop is observed after boot is completed.
	Keyword: eMMC; GPIO; toggling
	Reported in version: 4.7.0
3863011	Description: Restarting openibd results in kernel panic after modifying kernel IPsec configurations.
	Keyword: IPsec
	Reported in version: 4.7.0
3878458	Description: /usr/lib/udev/rules.d/80-ifupdown.rules runs /lib/udev/ifupdown-hotplug which uses ifquery for all newly created interfaces. This dramatically slows down SF interfaces creation.
	Keyword: Subfunction
	Reported in version: 4.7.0
3901511	Description: Failure to verify measurements when UEFI secure boot is enabled.
	Keyword: UEFI Secure Boot
	Reported in version: 4.7.0
3875394	Description: After the BFB installation, the root partition UUID in /etc/fstab does not match current partition UUID. As a result root partition is mounted as read-only: /dev/nvme0n1p2 on / type xfs (ro,relatime,attr2,inode64,logbufs=8,logbsize=32k,noquota)
	Keyword: Read-only; OL; UUID
	Reported in version: 4.7.0

Ref #	Issue Description
388 194 1	Description: When working with RShim 2.0.28, PCIe host crash may rarely occur at the beginning of BFB push after the Arm reset.
	Keyword: RShim; driver
	Reported in version: 4.7.0
388 631 5	Description: To reset or shut down the BlueField Arm, it is mandatory to specify the `--sync 0` argument. For example: ``` mlxfwreset -d <device> -l 1 -t 4 --sync 0 r ```
	Keyword: Arm; shutdown
	Reported in version: 4.7.0
395 621 0	Description: BMC version change using BFB installation can fail if the previous BMC version change process did not finish.
	Keyword: BMC
	Reported in version: 4.7.0
395 011 4	Description: QP number can go beyond 0xFFFF. Change datatype to uint32_t to hold entire value.
	Keyword: Virtnet
	Reported in version: 4.7.0
398 084 2	Description: Openibd queries deprecated parameter `ECPF_ESWITCH_MANAGER` until the query times out.
	Keyword: Service; openibd
	Reported in version: 4.6.0
394 800 9	Description: The command `bfcfg -d` may show an incorrect OOB MAC address.
	Keywords: OOB; MAC
	Reported in version: 3.9.7