



Known Issues in This Release

Ref #	Issue
38593 62	Description: UFM TFS endpoint dashboard report Switch port TX/RX rate reach Tbps
	Keywords: TFS, Switch Port, TX/RX
	Workaround: N/A
	Discovered in Release: v6.15.1
38813 65	Description: Malfunctioning of the rest API when deleting port associated to a pkey
	Keywords: CloudX, API, Bare-Metal
	Workaround: N/A
	Discovered in Release: v6.15.2
38628 47	Description: UFM reports wrong cable length for NDR optical cables connected to Quantum-2 NDR switch
	Keywords: NDR, Optical Cables, Quantum-2, Switch
	Workaround: N/A
	Discovered in Release: v6.17.0

cond

Info

For a list of known issues from previous releases, please refer to [Known Issues History](#).

Copyright 2024. PDF Generated on 06/06/2024